



International
Edition

Machine Tool Practices

Ninth Edition

Richard R. Kibbe
Roland O. Meyer
John E. Neely
Warren T. White



PEARSON

Machine Tool Practices

NINTH EDITION

RICHARD R. KIBBE

ROLAND O. MEYER

JOHN E. NEELY

WARREN T. WHITE

PEARSON

Boston Columbus Indianapolis New York San Francisco Upper Saddle River
Amsterdam Cape Town Dubai London Madrid Milan Munich Paris Montreal Toronto
Delhi Mexico City Sao Paulo Sydney Hong Kong Seoul Singapore Taipei Tokyo

Contents

- Preface, vi
- Guided Tour, viii
- Acknowledgments, xi
- About the Authors, xiii

SECTION A

Introduction, 1

- Unit 1** Shop Safety, 6
- Unit 2** Mechanical Hardware, 14
- Unit 3** Reading Drawings, 26

SECTION B

Hand Tools, 35

- Unit 1** Arbor and Shop Presses, 37
- Unit 2** Work-Holding and Hand Tools, 45
- Unit 3** Hacksaws, 54
- Unit 4** Files, 57
- Unit 5** Hand Reamers, 63
- Unit 6** Identification and Uses of Taps, 67
- Unit 7** Tapping Procedures, 72
- Unit 8** Thread-Cutting Dies and Their Uses, 77
- Unit 9** Off-Hand Grinding, 81

SECTION C

Dimensional Measurement, 87

- Unit 1** Systems of Measurement, 103
- Unit 2** Using Steel Rules, 107
- Unit 3** Using Vernier, Dial, and Digital Instruments for Direct Measurements, 116
- Unit 4** Using Micrometer Instruments, 125

- Unit 5** Using Comparison Measuring Instruments, 146
- Unit 6** Using Gage Blocks, 166
- Unit 7** Using Angular Measuring Instruments, 174
- Unit 8** Tolerances, Fits, Geometric Dimensions, and Statistical Process Control (SPC), 183

SECTION D

Materials, 193

- Unit 1** Selection and Identification of Steels, 197
- Unit 2** Selection and Identification of Nonferrous Metals, 203
- Unit 3** Hardening, Case Hardening, and Tempering, 209
- Unit 4** Annealing, Normalizing, and Stress Relieving, 221
- Unit 5** Rockwell and Brinell Hardness Testers, 225

SECTION E

Layout, 235

- Unit 1** Basic Semiprecision Layout Practice, 244
- Unit 2** Basic Precision Layout Practice, 250

SECTION F

Preparation for Machining Operations, 263

- Unit 1** Machinability and Chip Formation, 266
- Unit 2** Speeds and Feeds for Machine Tools, 275

- Unit 3** Cutting Fluids, 279
- Unit 4** Using Carbides and Other Tool Materials, 284

SECTION G

Sawing Machines, 301

- Unit 1** Using Reciprocating and Horizontal Band Cutoff Machines, 313
- Unit 2** Abrasive and Cold Saws, 323
- Unit 3** Preparing to Use the Vertical Band Machine, 326
- Unit 4** Using the Vertical Band Machine, 335

SECTION H

Drilling Machines, 341

- Unit 1** The Drill Press, 346
- Unit 2** Drilling Tools, 349
- Unit 3** Hand Grinding of Drills on the Pedestal Grinder, 358
- Unit 4** Operating Drilling Machines, 362
- Unit 5** Countersinking and Counterboring, 374
- Unit 6** Reaming in the Drill Press, 377

SECTION I

Turning Machines, 383

- Unit 1** The Engine Lathe, 391
- Unit 2** Toolholders and Toolholding for the Lathe, 399
- Unit 3** Cutting Tools for the Lathe, 405
- Unit 4** Lathe Spindle Tooling, 413
- Unit 5** Operating the Machine Controls, 420
- Unit 6** Facing and Center Drilling, 425
- Unit 7** Turning between Centers, 435
- Unit 8** Alignment of the Lathe Centers, 448
- Unit 9** Other Lathe Operations, 451
- Unit 10** Sixty-Degree Thread Information and Calculations, 465
- Unit 11** Cutting Unified External Threads, 470
- Unit 12** Cutting Unified Internal Threads, 481
- Unit 13** Cutting Tapers, 485
- Unit 14** Using Steady and Follower Rests, 496

- Unit 15** Additional Thread Forms, 502
- Unit 16** Cutting Acme Threads on the Lathe, 507

SECTION J

Vertical Milling Machines, 511

- Unit 1** Vertical Spindle Milling Machines, 514
- Unit 2** Cutting Tools and Cutter Holders for the Vertical Milling Machine, 517
- Unit 3** Setups on the Vertical Milling Machine, 523
- Unit 4** Vertical Milling Machine Operations, 530
- Unit 5** Using the Offset Boring Head, 540

SECTION K

Horizontal Spindle Milling Machines, 545

- Unit 1** Horizontal Spindle Milling Machines, 549
- Unit 2** Types of Spindles, Arbors, and Adapters, 553
- Unit 3** Arbor-Driven Milling Cutters, 556
- Unit 4** Work-Holding Methods and Standard Setups, 562
- Unit 5** Machine Setup and Plain Milling, 567
- Unit 6** Using Side Milling Cutters, 577
- Unit 7** Using Face Milling Cutters on the Horizontal Milling Machine, 581

SECTION L

Grinding and Abrasive Machining Processes, 585

- Unit 1** Selection and Identification of Grinding Wheels, 598
- Unit 2** Truing, Dressing, and Balancing of Grinding Wheels, 606
- Unit 3** Grinding Fluids, 612
- Unit 4** Horizontal Spindle Reciprocating Table Surface Grinders, 617
- Unit 5** Work Holding on the Surface Grinder, 621

- Unit 6** Using the Surface Grinder, 625
Unit 7 Problems and Solutions in Surface Grinding, 632
Unit 8 Center-Type Cylindrical Grinders, 635
Unit 9 Using the Cylindrical Grinder, 641
Unit 10 Universal Tool and Cutter Grinder, 645

SECTION M

Computer Numerical Control and Other Advanced Machining Processes, 659

- Unit 1** CNC Machine Tool Programmable Axes and Position Dimensioning Systems, 668
Unit 2 CNC Programming, 673
Unit 3 CNC Tooling, 705
Unit 4 Other Advanced Machining Processes, 718

APPENDIX 1

Answers to Self-Tests, 726

APPENDIX 2

General Tables, 751

- Table 1** Decimal Equivalents of Fractional Inches, 752
Table 2 Inch/Metric Conversion Table, 753

- Table 3** Tap Drill Sizes, 755
Table 4 Metric Tap Drill Sizes, 756
Table 5A Tapers, 757
Table 5B Tapers and Angles, 758
Table 6 General Measurements, 759
Table 7A Density or Specific Gravity of Metals and Alloys, 761
Table 7B Approximate Melting Points of Metals and Various Substances, 762
Table 8 Right-Triangle Solution Formulas, 763
Table 9 Wire Gages and Metric Equivalents, 764
Table 10 Cutting Speeds for Commonly Used Materials, 765
Table 10A Feeds for High-Speed Steel End Mills, 765
Table 10B Coolants and Cutting Oils Used for General Machining, 765

APPENDIX 3

Precision Vise Project Drawings, 766

- Glossary, 771
 Index, 781

Index

Note: Page numbers in *italics* refer to figures and illustrations.

Abbreviations

for machining operations, 29–30

Abrasive sawing machines, 323, 323

abrasives for wheels, 324

cutoff saws, 303, 304

operation, 324, 324, 325

safety, 305, 306, 324

selecting, 324

wheel bonds, 324

wheel speeds, 324

Absolute dimensioning, CNC, 671, 672

Accuracy

in measurement, defined, 89

with micrometers, 131

when using steel rules, 107

with vernier calipers, 117–119

user accuracy, 89

Acme cutters, 507–510

cutting on lathe, 507–510

Acme forms, 502–503, 503

Acme taps, 70, 70

Acme thread gages, 507, 507

Acme threads, 507–510

Acme tool gages, 507, 507

Acute angles

defined, 174, 174

measurement, 176

in right triangles, 178, 178

trigonometric functions, 257–258, 258

Adjustable face spanner wrenches, 50, 51

Adjustable hook spanner wrenches, 50, 51

Adjustable parallels, 148–149, 149, 150

use with sine bar, 180–181, 181

Adjustable reamers, 64, 64

Adjustable wrenches, 49, 50

Air gages, 92–93, 93, 94, 95

Alignment

of lathe centers, 415–450

measurement, defined, 88

Alignment telescope, 101, 102

Allen wrenches *See* Socket head wrenches

Alloy steels, 17, 18

Alloys

approximate melting points listed, 762

density and specific gravity, 761

Aluminum, 203, 204

American National form, 466, 466

American National standard taper pipe thread, 468, 469

Angle milling machine, 535–537

Angle vise, 368, 368

Angles

acute, 174, 174

arithmetic, reviewed, 175, 759

clearances, on milling cutters, 557, 645, 646

face milling cutters, 582–583

on lathe tools, 405–406, 405

terms and definitions, 406

layout calculations, 260

nose radius, 406, 406

obtuse, 174, 174

right, 174, 174

right-hand and left-hand, 406–407, 406

in right triangle, 257–258, 258

tapers and (chart), 758

Angular measurement units, 174–175

Angular measuring instruments

bevel protractors, 175, 176

plate protractors, 175, 176

sine bars, 178, 180–181

sinometer angle gages, 175, 176

universal bevel vernier protractors, 176–177, 176

Angularity, defined, 89, 89

Annealing

of band saw welds, 328–329, 329

normalizing and stress relieving, 221–223

Apprentice machinists, 4

Aprons, on engine lathes, 392–393, 394

Arbor driven cutters

plain types, 556, 556, 557

side milling types, 557–560

Arbor presses, 37, 38

uses of, 37–38, 38

Arbors

horizontal mill, 553–555

setup, 571–572, 572

spacing and bearing collars, 553, 554

for lathe, 444, 444

support bearings, 554–555, 554

Arc versus chord length errors, 158, 159

Area measurement rules, 759

Arithmetic average, 190

Assembly drawings, 28

Autocollimators, 101, 101

Automotive machinists, 4

Auxiliary views, on drawings, 27–28, 28

Babbitt metals, 206, 206

Back spotfacing, 375, 376

Balancing, of grinding wheels, 609–610, 610

Ball and roller bearings, 39

Ball-bearing lathe centers, 435–436, 437, 437

Ball peen hammers

for layout, 238, 239

machinist's, 48–49, 49

- Band blade welders, 326, 326
- Band machines
 - advantages, 306–307
 - high-tool velocity types, 309, 309, 310
 - horizontal, 302, 302
 - large-capacity type, 309, 310
 - types of, 308–309
 - vertical, 306, 308, 308
- Band machining, 306–307
- Band saw welding, 326
 - annealing welds, 328–329, 329
 - grinding welds, 329, 329, 330
 - horizontal, safety, 304
 - preparation of blade, 326–327, 328
 - problems, 329, 330
 - safety, 328, 328
 - vertical, safety, 311, 311–312, 312
- Bar chucker, CNC, 661, 662, 662
- Base, vertical mill, 514
- Bastard cut files, 59, 60
 - coarseness, 57, 57
- Bearing pullers, 39, 39
- Bearings, four types of, 716
- Bed, engine lathe, 392, 394
- Bed-type horizontal mill, 546
- Beryllium copper, 205
- Bevel protractors, 175, 176
- Bilateral tolerances, 28
- Bills of materials, on drawings, 31
- Blocks, CNC programs, 676–681
- Blueprinting, of drawings, 30
- Bolster plates, on shop presses, 39
- Bolt circles, geometric construction layout, 248–249
- Bolts
 - abbreviations on drawings, 30
 - carriage, 17, 17
 - defined, 16
 - diameter of bolt circle (D.B.C. or B.C.), 30
 - grade marking for, 19
 - head markings, 19
 - machine, 17, 17
 - stud, 17, 17
 - types, 17
- Bore gage expansion plug, 94, 96
- Bores and shafts, 39–40
- Boring
 - blind hole, 455, 455
 - CNC cutting tools, 709, 710, 710
 - in lathe, 453–456
 - thread relief, 455–456, 456
 - through boring, 454–455, 455
- Boring bars
 - engine lathe, 403–404, 404
 - for lathe
 - setup positions, 454, 454, 455
 - types, 453, 453
 - toolholder, 400, 400
- Bottoming taps, 67–68, 68
- Box end wrenches, 49–50, 50
- Brass, 205
- Bridge reamers, 378–379, 378
- Brinell Hardness tester, use of, 231–233
- Broach
 - keyway broaching, 40–42, 41
 - guide for, 41, 41
 - production broaching, 42, 43
 - push broaching recommendations, 42
- Bronze, 205
- Bushings
 - guide, for pressing, 39, 39
 - installing, 38–39, 39, 40
 - special tooling, 39, 39
- C-clamp, 367, 368
- C-clamp body
 - drilling procedure, 370–372
- C-clamp tools, 47, 47, 48
- CAD/CAM (Computer Aided Design and Manufacturing), 2
 - part programming with, 698–699
- Cadmium, 204–205
- Calibration
 - defined, 131
 - in measurement, 91
 - micrometers, 131
 - use of gage blocks, 139, 140, 161, 162
- Calipers
 - dial, 123, 123
 - electronic (digital), 123–124, 124
 - hermaphrodite applications of, 238, 238
 - inside micrometers, 127, 127
 - outside micrometers, 130, 130
 - slide, 108, 109
 - spring, 146, 147
 - vernier, 117–119
- CAM (Computer Aided Manufacturing), 2
 - part programming with, 698–699
 - post-processor, 699, 700
- Camlock spindle nose, for lathe, 414, 414
- Capscrews, 17, 19
- Carbide face mills, 584, 584
- Carbide inserts, identification, 292, 296
- Carbide toolholders
 - identification systems, 292, 295, 296
- Carbide tools, 284–294
 - new technology, 294
 - selection of, 285–292
- Carbide-tipped chucking reamers, 379, 379
- Carbide-tipped helical flute chucking reamers, 379, 379
- Carbide-tipped straight flute chucking reamers, 379, 379
- Carriage bolts, 17, 17
- Carriages, engine lathe, 392–393, 394
- Carrying objects, safety aspects, 11–12
- Case hardening and tempering, 209–220
 - of steels, 215, 215–217
- Cast iron surface plates, 236, 236
- Cat heads, 498, 499, 500
- Cemented carbide cutting tools, 284–285
- Center drilling, lathe, 432, 432–433, 433
- Center drills, 350, 351, 366, 370, 373
 - countersinks, 374, 374
- Center punches
 - automatic center, 239, 240
 - center, 239, 239

- hollow grinding, 83, 84
- optical, 239–240, 240
- Centers
 - dead, for lathe, 435, 437, 437
 - lathe, 428, 429, 432–433
 - lathe tailstock, 435–436, 436, 437
 - live, for lathe, 435–436, 436, 437
- Centerhead
 - machinist's combination square set, 152–154, 152
 - round stock center layout, 240, 241, 497
- Centerless grinders, 589–591
- Center-type cylindrical grinders. *See* Cylindrical grinders
- Ceramic tools, 288, 294, 297
- Cermets, 297
- Chamfer bushing bores, 39–40, 40
- Chamfer tap, 67, 67
- Chamfers
 - reading drawings, 29
 - symbols, 31
- Chatter, in boring operations, 453–454, 453, 454
- Chemical safety, 6–7
- Chip breakers
 - cemented carbide inserts, 292, 292, 293
 - CNC, 706, 706
 - Kenloc Chip-Control insert application, 294
 - for lathe tools, 409–410, 409
 - types of, 273, 274
- Chip control
 - lathe, 409–410, 409
 - milling machine, 574
- Chip formation, 266, 269, 270–271
 - safety when turning, 442, 442
- Chip removal, CNC, 667
- Chip structure analysis, 271–273
- Chisels
 - hollow grinding, 83, 84
 - types, 52, 53
- Chromium, 205
- Chucks
 - drill press, 350, 350
 - independent four-jaw, for lathe, 414, 415
 - installing camlock type, on lathe, 425, 426–427
 - magnetic
 - lathe, 416, 417
 - surface grinder, 621–622, 621, 622
 - vertical spindle milling machine, 525–526, 526
 - six-jaw, for lathe, 414, 415
 - tailstock, for lathe, 432, 432
 - three-jaw universal, for lathe, 414–416, 415, 415
 - two-jaw universal, for lathe, 414, 415
 - vacuum, for surface grinders, 622, 622
- CIM (Computer Integrated Manufacturing), 2
- Circular interpolation
 - CNC, 686–688, 688
- Circularity, defined, 88
- Circumference, general measurement techniques, 759
- Clamps
 - C types, 47, 47, 48
 - parallel, 47, 47
 - strap, 366, 367
- Clearance angles, on milling cutters, measurement, 645, 647
- Climb milling
 - angles, 583, 583
 - horizontal mill, 571, 572
 - vertical mill, 530
- CNC (Computer Numerical Control)
 - absolute dimensioning systems, 671, 672
 - adaptive control (AC), 717–718
 - advantages and capabilities, 660
 - angular interpolation, 683, 683
 - automatic tool changer (ATC), 663, 663, 676, 677, 714–715
 - CAD and CAM, 660
 - chip removal, 667
 - circular interpolation, 686–688, 688
 - color graphics, 667
 - contour machining, 663, 665, 666
 - coordinate tables, for drilling, 680
 - cutter compensation, 685–686, 686
 - developing programs, 676–681
 - electrodischarge machining (EDM), 661
 - flexible manufacturing systems, 664, 667
 - fundamental programmable axes, on machine tools, 670–671
 - G code table, 675
 - helical milling, 663, 667
 - history, 660
 - horizontal spindle machining center, 663, 664, 667, 670, 670, 671
 - human and robot-operated, 2
 - incremental positioning systems, 671, 672
 - laser, 661, 661, 722
 - linear interpolation, 681–682, 681
 - miscellaneous function commands (M codes), 674
 - modal commands, 674, 675
 - operating the machine tool, 702–703
 - parabolic and cubic interpolation, 688
 - polar coordinates, 668, 669, 670
 - position dimensioning systems, 668–672
 - preparatory function commands (G codes), 674, 675, 676
 - program blocks, 676–681
 - programmable axes, 668–672
 - programmable rotary table, 663, 666
 - programmable rotational axes, 671
 - quadrants, 668, 669
 - safety, 665, 666
 - single-point threading, 663, 666
 - standard programming code, 674
 - tapping, 688–689
 - tool and cutter grinding, 656, 658
 - tool coatings, 706
 - tool materials, 705
 - tooling, 705–717
 - turning centers, 661, 662
 - turn/mill centers, 661, 662
 - types and capabilities of machine tools, 661, 662, 663–667
 - vertical spindle machining centers, 663, 663, 664, 665
 - X-Y plane, 668–669, 669
 - X-Z plane, 669
 - Y-Z plane, 669
 - Z-axis offsets, 670–671

- CNC cutting tools
 - boring, 709, 710, 710
 - coatings, 706
 - end mill ball nose chip thinning, 712–713, 713
 - end mill chip thickness, 711–712, 712
 - end mill rigidity, 713–714, 714
 - high-speed machining, 706–707
 - hole making, 707–708, 707
 - indexable drills, 708, 708
 - reaming, 709, 709
 - roller burnishing, 711, 711
 - spade drills, 709
 - tapping, 689, 709–710
 - trepanning, 709
- CNC dimensioning systems
 - absolute positioning, 671, 672
 - Cartesian coordinates, 668
 - coordinate tables, 679–680, 680
 - incremental mode, 671, 672
 - rectangular coordinates, 668, 669
- CNC programming
 - code, 674
 - drilling, 673–703
 - general technique, 673
 - methods, 673
 - offset files, 677
 - part programming with CAD/CAM, 698–699
 - programming example, 690–693
 - prompted programming systems, 699–702
 - single-point threading, 689–690, 697–698
 - turning, 690
 - codes, 693–697
- CNC tooling
 - adaptive control (AC), 717–718
 - EPROM offset data, 714–715, 715
 - high speed spindles, 715, 716
 - touch sensor inspections systems, 715, 715, 716
- Coatings, CNC cutting tools, 706
- Coaxial dial indicators, vertical mills, 527, 527
- Code, CNC programming, 674
- Cold saws, 303, 304, 325, 325
- Collet chucks, 418, 418
- Collet sleeves, 418, 418
- Collets
 - R-8, for milling machine, 521
 - rubber flex type, for lathe, 417, 417
 - solid, for vertical mill, 521, 521
 - split, 521, 521
 - spring type, 418, 418
 - steel-spring, for lathe, 417, 417
- Column, vertical mill, 514
- Combination center drill and countersink, 374, 374
- Combination square set, 152–154, 152
- Combination wrenches, 50, 50
- Comparator
 - dial indicator, 161–162, 162
 - electromechanical, 163–164, 164
 - electronic, 100, 100, 161, 161
 - micrometer, for threads measurement, 478, 478
 - optical, 101, 101, 161, 161
 - for visual surface roughness, 98, 98
- Comparison measuring instruments
 - adjustable parallels, 148–149, 149, 150
 - dial test indicators, 159–161
 - diemaker's square, 154, 154
 - indicators, 155–161
 - machinist's combination square, 152, 152
 - planer gage, 151–152, 151–152
 - precision beveled edge squares, 152–153, 153
 - profile projector, 163, 163
 - shop tip, 164
 - small hole gage, 148, 149–150
 - spring calipers, 146, 147
 - squares, 152–154
 - telescoping gages, 146–148, 147–149
 - thickness gages, 149–151, 151
- Compressed air, safety with, 10
- Computer Aided Design (CAD), 2, 3
 - part programming with, 698–699
- Computer Aided Manufacturing (CAM), 2
- Computer Integrated Manufacturing (CIM), 2
- Computer Numerical Control. *See* CNC (Computer Numerical Control)
- Concentricity, defined, 88
- Contour sawing
 - vertical band saws, 339–340, 340
- Contouring, with band saw, 307, 307, 310, 310
- Controls
 - on lathe, 420–424
 - clutch rod, 423, 423
 - feed rates, 421–424
 - quick change gear selector, 421, 422
- Conventional milling
 - horizontal mill, 571, 572
 - vertical mill, 530
- Conversion charts (metric), 105, 753–754
- Conversion dials, 105, 105
- Conversion factors, metric system, 104–105
- Coolant separators, 283
- Coolants listed, 765
- Coordinate layouts
 - height gage, 256–257
- Coordinate layouts, for hole patterns, 249, 256–257, 258–259
- Coordinate measurement, calculations, 256–257, 258–259
- Coordinate measuring machines, 98, 99
- Copper and copper alloys, 205
- Cosine error, 158, 159
- Cosine ratio, of acute angles defined, 257
- Counterbores
 - interchangeable pilots, 375, 375
 - multiflute, 375, 375
 - two-flute, 375, 375
- Counterboring
 - defined, 29
 - symbols, 30
- Countersinking
 - defined, 29
 - symbols, 30
- Countersinks, 374, 374
- Crazing, prevention of, 293
- Crescent wrench, 49, 50
- Cross peen hammers, 49, 49

- Cubic boron nitride (CBN), 599, 599
 - truing, 607–608, 608
- Cubic boron nitride (CBN) cutting tools, 294, 297
- Curved tooth files, 59, 59
- Cutoff lathe tools, 407–409
- Cutoff machines
 - cold saws, 303, 304, 325, 325
 - safety, 306, 306
 - horizontal band saws, 302, 302, 303
 - reciprocating saws, 302
 - tilt frame band saws, 302–303, 303, 304
- Cutoff toolholders, engine lathe, 403, 403
- Cutter compensation, 685–686, 686
- Cutters
 - Acme threads, 507–510
 - arbor driven, for horizontal mills, 556, 556–561
 - carbide, for lathe, 285–297, 405, 405
 - face milling, horizontal mill, 581–584
 - hand grinding, 410–412
 - high speed, lathe, 405–407
 - involute gear cutters, 560–561, 560
 - lead angle, 582, 582
 - re-sharpening milling types, 650–656
 - turning unified threads, 470–471
 - types, 407–409, 410
 - vertical milling machine, 517–521, 521
 - Woodruff key, 519, 519
- Cutting fluids, 765
 - application methods, 281–283
 - cutting oils, 280–281, 765
 - drilling machines, 364
 - effects, 279–280
 - emulsions, 280
 - gaseous fluids, 281
 - for grinding, 604, 605, 612–616
 - grinding machines, 364
 - metal cutting, 264–265, 266, 270
 - sawing with, 315
 - semisynthetic fluids, 280
 - synthetic fluids, 280
 - types, 280–281
 - vertical band saws, 339, 340
- Cutting speeds (CS), 275–277
 - calculations
 - drill press, 362–363
 - for commonly used materials, 531, 531, 765
 - defined, 530–531
 - drilling, 362–363
 - horizontal milling machine, 567
 - lathe, 439–441
 - sawing, 313
 - vertical milling machines, 530–531
- Cutting tools
 - cemented carbides, 284–285
 - ceramics, 288, 294, 297
 - clearance, 294, 297
 - cubic boron nitride, 294, 297
 - diamond, 298
 - drill press, 349–357
 - engine lathe, 405
 - form cutters, 407, 407
 - high speed steels, 405–407
 - high-carbon steels, 284
 - horizontal mill, 556–561
 - materials, 284–298
 - vertical mill, 517–520, 521
- CVSG grinding abrasive, 600
- Cyanogen compounds
 - precautions, 6
- Cylindrical grinders
 - accessories, 640
 - capabilities, 637–639, 640
 - major parts, 635–637, 635
 - mandrel grinding, procedure for, 643–644
 - setup, 641–642, 643–644, 643
 - types, 588–592
 - workholding on, 637, 637
- Cylindrical ring gage, 91, 93
- Cylindrical squares, 153–154, 153, 154
- Dead lathe centers, 437, 437
- Decibels (dB), safety aspects, 8
 - level of various sounds, 9
- Decimal angles, 175
- Decimal equivalents. *See also* Metric
 - for drill sizes, 354–355
 - of fractional inches (table), 753
 - inch/metric conversion tables, 753–754
- Decimal notation, 112
- Decimal rules, 112–113, 113
- Deep hole drilling machines, 344, 344
- Depth gage
 - dial indicator type, 123–124, 123
 - vernier type, 121
- Depth micrometer
 - reading, 138–139, 139
- Depth micrometers, 138, 138
- Depth of threads, 466, 467
- Desmond dresser, 82
- Detail drawings, 28, 31
- Diagonal cutters, 48, 48
- Dial bore gages, 94, 96
- Dial calipers, 123, 123
- Dial depth gages, 123, 123
- Dial indicating expansion plug bore gages, 94, 96
- Dial indicating inprocess grinding gages, 95, 97
- Dial indicating screw thread snap gage, 94
- Dial indicating screw thread snap gages, 94, 97
- Dial indicating snap gages, 94, 95
- Dial indicating thread plug gages, 94, 97
- Dial indicators
 - care and use of, 156–157, 157
 - depth gages, 123–124, 123
 - potential for error, 157–158, 159
 - types, 155, 155–161, 156
- Dial instruments, shop tip, 123
- Dial test indicators, 157, 157
 - use of, 159–161
- Dial thickness gages, 93, 95
- Diamond, as superabrasive, 599–600, 599, 604
- Diamond cutting tools, 298
- Die sinker's riffler files, 59, 59
- Die threading
 - by hand, 79–80

- Die threading (*Continued*)
 - on lathe, 79, 79, 459, 459
- Die-cast metals, 205–206, 205
- Diemaker's squares, 154, 154
- Dies
 - blanks, 77, 78
 - button, 77
 - markings, 77, 77
 - rethreading type, 78, 78
 - solid square, 78, 79
 - thread cutting, 77–80
 - two-piece, 77, 78
- Diestock, 77, 78
- Digital readout (DRO)
 - horizontal mill, 547, 547
 - vertical mill, 106, 106, 529, 529
- Dimensional metrology, 88
- Dimensioning systems, in drawings, 28, 28
 - coordinate or absolute, 29, 29
 - decimal inch notations, 29, 29
 - dual system, 29, 30
 - standard tolerances, 28
 - tolerances, 28
- Direct-reading micrometers, 127, 127
- Discrimination
 - 10:1 rule, 90
 - in measurement, 90
 - micrometers, 131
 - steel rules, 107
- Disk micrometers, 125, 126
- Dividers, for layouts, 237–238, 238
- Dividing heads, 564, 564
- Dovetails
 - machining, 535–537
- Draw filing, 61, 61
- Drawings
 - assembly, 28, 31, 32
 - auxiliary views, 27–28, 28
 - bill of material, 31
 - blueprinting, 30–31
 - change blocks, 31, 31
 - detail, 28, 31
 - dimensioning systems, 28
 - exploded, 26, 27
 - finish, marks on, 29, 30
 - formats, 30–31, 32
 - hidden lines, 26–27, 27
 - isometric, 26, 27
 - oblique, 26, 27
 - orthographic format, 26–28, 27
 - pictorial formats, 26
 - precision vise project drawings, 766–769
 - reading and interpreting, 28–31
 - sectioned views, 27, 28
 - title blocks, 30, 31, 31
- Dress safety, 8
- Dressing
 - grinding wheels on pedestal grinders, 82, 83
 - surface grinder wheels, 606
- Drift punch, for drill sleeve, 353, 356, 356
- Drill and hole gage layout, 244–247, 248
- Drill chucks, for lathe tailstock, 401, 402
- Drill grinding procedure, 359–361
- Drill presses
 - chucks, 350, 350
 - cutting tools, 349–357
 - deep hole, 344, 344
 - heavy duty, 342
 - micro, 342, 343
 - procedures, 364–366, 365, 366
 - radial arm, 342, 342, 346, 347, 348, 348
 - reaming with, 65–66, 65
 - safety, 344–345
 - sensitive, 342, 342, 346, 346
 - table, 342
 - turret, 342, 343, 343
 - types, 342–344
 - upright, 342, 342, 345, 346–347, 348
 - vises, 367–368, 368
 - workholding, 366, 367, 368–371
- Drilling
 - angle plates, 367, 368
 - C-clamp body, procedure, 370–372
 - jigs and fixtures, 370, 371
 - lathe, procedures, 364–366, 365, 366, 451–452
 - pecking, 364
- Drilling machines, operation, 362–373
- Drill point gages, 358, 358, 361, 361
- Drill pointing machines, 356, 357
 - split-point design, 356, 357
- Drills
 - accuracy of drilled holes, 356
 - burnishing, 350
 - center, 350, 351
 - drill sizes, decimal equivalent tables, 354–355
 - gun, 352, 352
 - hand grinding, 359–361
 - hard steel, 352, 352
 - high-helix, 349, 350
 - high-speed, 349
 - jobber's, 350
 - left-hand, 349, 350
 - low-helix, 349, 350
 - major parts, 349
 - oil hole, 350
 - selection, 351–353
 - size series, 353
 - spotting, 349, 351, 351
 - standard helix jobbers, 349
 - step, 351, 351
 - tap, 72–73, 73
 - taper shank, 349
 - three-flute, 349
 - twist, 351, 352
 - twist, parts of, 349–350, 349, 350
 - types, 349–351
- Drive plates, 417, 417
- Drives
 - back gear systems, for lathe, 420–421
 - band saws, 336, 337
 - lathe headstock, 420, 421
 - variable-speed, 420, 420

- Ear protection, sound suppressors for, 8, 8
- EBM machining, 720
- ECM machining, 721, 721
- Edgefinder, use on vertical mill, 526, 526
- EDM machining, 74, 718–720
 - CNC, 660
 - as tap disintegrator, 74
- Electrical safety, 11
- Electrochemical machining (ECL, ECDB), 721, 721
- Electrodischarge machining. *See* EDM machining
- Electrolytic grinding (ELG), 720
- Electromechanical comparators, 163–164, 164
- Electron beam machining (EBM), 720
- Electronic calipers, 123–124, 124
- Electronic comparators, 100, 100, 161, 161
- Electronic digital comparators, 161, 161, 163–164, 163
- Electronic digital travel indicators, 99–100, 99, 100
- Electronic micrometers, 130–131, 131
- ELG grinding, 720–721
- ELG machining, 720–721
- End mill ball nose chip thinning tools, 712–713, 713
- End mill chip thickness tools, 711–712, 712
- End mill holders, 521, 521
- End mills
 - ball end, 519, 519
 - checking cutting edges, 533
 - corner rounding, 519, 519
 - dovetail, 519, 519
 - four-flute, 517–518
 - helical flute, 518, 518
 - high-speed steel feeds, 765
 - high-speed steel helical, 518, 518
 - indexable, 520, 520, 521
 - leaning slots, causes for, 532, 532
 - roughing, 518–519, 519
 - sharpening, 654–656, 657
 - shell, 535, 536
 - single-angle dovetail, 519, 519
 - size markings, 535
 - straight flute, 518, 518
 - tapered, 519, 519
 - three-flute, 517
 - t-slot, 519, 519
 - two-flute, 517, 518
 - Woodruff key, 519, 519
- Engine lathes, 391
 - aprons, 392–393, 394
 - beds, 392, 394
 - boring bars, 403–404, 404
 - carriage, 392–393, 394
 - parts, 392–394, 392
- Engineers, professional, 4
- English system of measurement, 103–104
- EPROM offset data, 714–715, 715
- Expansion fits, 185
- Expansion plug bore gage, 94, 96
- Expansion reamers, 64, 64
- External threaded fasteners, 16–21
- Eye protection, 6, 7, 8
- Face driver, for lathe, 417, 417
- Face milling, 538–539
- Face milling cutters
 - horizontal mill, 581–584
 - use of, 581–584
- Face plate for lathe, 417, 417
- Face shields, 7, 8, 8
- Facing
 - on lathe, 425–430, 431
 - offset boring head, 542, 543
 - setup, 425–427
- Feathered key, 25
- Feed rates calculations
 - horizontal milling machines, 567–569
 - vertical milling machines, 531–532
- Feeds
 - breakage and, 264
 - calculations, 277–278
 - drilling, 363, 363, 364
 - high-speed steel end mills, 765
 - in metal cutting, 266
 - milling, 567–568
 - reaming, 379–380
 - turning, 439–441
- Files
 - bastard cut, 57, 57, 59, 60
 - card for cleaning, 60, 60
 - care and use, 60–62
 - curved tooth type, 59, 59
 - die sinker's rifflers, 59, 59
 - flat, 58, 58
 - half-round, 59, 59
 - handles, 60–61, 61
 - knife, 58, 58
 - lathe, 58, 58
 - major parts, 57, 57
 - mill, 58, 58
 - pillar, 58, 58
 - pinning, 60
 - round, 59, 59
 - square, 58, 58
 - Swiss pattern, 59, 59
 - tang, 57
 - thread repair, 59, 60
 - three square, 59, 59
 - types, 57–60
 - warding, 58, 58
- Finish marks, on drawings, 29, 30
- Fire extinguishers, 10–11
- Fits, shrink and expansion, 183, 185
- Fixed face spanner wrenches, 50, 51
- Fixed gages, 91, 92
- Fixed thread gages, 91, 92
- Flash chrome plating, 71
- Flat files, 58, 58
- Flatness, defined, 88
- Flexible Manufacturing System (FMS), 3, 664, 667
- Flycutters, 520, 520
- Follower rests
 - for lathes, 500
 - use of, 500

- Foot protection, 7-8
- Footstock, horizontal milling machines, 564, 564
- Form cutters, for lathe, 407, 407
- Four-jaw chuck
 - centering workpiece, 426
 - for lathe, 414, 415
- fpm (feet per minute), 313
- Friction sawing, 310, 311
- Fumes, control of, 6
- Furnaces, for heat treating, 212-213

- G code table, 675
- Gage blocks
 - applications, 171-172, 172
 - calculating stack height, 170-171
 - checking surface, with optical flats, 169, 169, 170
 - preparation for use, 167-168
 - preparing for storage, 170
 - sets with accessories, 164, 164
 - tolerances, 167
 - types and grades, 166
 - use with sine bar, 180-181, 181
 - value of, 167
 - wear blocks, 171, 172
 - wringing, 167-168, 169
- Gages
 - adjustable limit snap gages, 91, 92
 - air, 92-93, 93, 94
 - air plug, 92, 94
 - bore, 94, 96
 - CNC tool length, 678, 678
 - column (flow-type), 92, 94, 95
 - cylindrical plug, 91, 93
 - cylindrical ring, 91, 93
 - fixed, 91, 92
 - fixed thread, 92
 - go and no go, 79, 91
 - height. *See also* Height gages
 - for layout, 242, 242-243, 243
 - planer, 151-152, 151-152
 - for layout, 151-152, 151-152, 242, 243
 - plug, 94, 97
 - precision height gages, 159-160, 160
 - pressure-type air snap gages, 92, 94
 - radius, 149, 151
 - rule depth, 109-110, 109, 110
 - saw blades, 314, 314
 - screw pitch, 466
 - small hole, 148, 149, 149-150
 - snap, 91, 92
 - standard hook, 108, 108, 109
 - surface, 240-241
 - for layout, 240-241
 - taper plug, 91, 92
 - taper ring, 91, 92, 492-493
 - telescoping, 146-148, 147-149
 - thickness, 149-151, 151
 - thread plug, 91, 92, 483, 483
 - thread ring, 91, 92, 477, 477
 - thread roll snap, 477, 478
 - wire gages and metric equivalents, 764
- Galling, prevention of, 364

- Gang drill presses, 342, 343
- Gantry vertical spindle machining center, CNC, 663, 664
- General machinists, 3-4
- Geometric construction layouts
 - for bolt circles, 248-249
- Geometric dimensions, 186-187
- Geometric tolerances
 - concentricity notations, 186
 - datum and basic dimensions, 186-187
 - drawing formats for, 187, 188-189
 - feature location notations, 186
 - least material condition (LMC), 187
 - maximum material condition (MMC), 187
 - orientation notations, 186
 - regardless of feature size (RFS), 187
 - symmetry notations, 186
 - true position, 186
- Gib adjustment screws, 516, 516
- Gib head keys, 25
- Grade markings, on bolt heads, 19
- Grades
 - gage blocks, 166, 167
 - surface plates, 236
- Granite surface plates, 236, 236
- Grinders. *See* Grinding machines
- Grinding, CBN-plated grinding process, 548
- Grinding dust
 - collectors, 6, 7
 - health hazard, 6
- Grinding fluids
 - application methods, 613-614
 - cleaning, 614-615
 - grinding waste disposal, 615
 - steps to follow, 616
 - types, 604, 612-613
 - straight oil, 613
 - water-soluble chemical types, 612
 - water-soluble oil types, 612-613
- Grinding machines
 - abrasive processes, 593-595
 - adaptive machine controls, 593
 - centerless, 588, 589-591
 - cost effectiveness, 593
 - cylindrical, 588-592, 591
 - electrolytic, 720-721
 - fluids for, 612-616
 - free abrasive, 594, 594
 - gear finishing, 592-593, 592, 593
 - lapping and honing, 594, 594
 - superfinishing, 594, 595
 - pedestal, 81-84
 - See also* Pedestal grinders
 - roll-type, 588-589, 590
 - safety, 595
 - selection and identification, 598-605
 - superabrasives, 593-594
 - surface, 586-587, 588
 - See also* Surface grinders
 - thread grinders, 592, 593
 - universal tool and cutter, 591-592, 592
 - vibratory deburring, 594, 595
- Grinding twist drills, 358-361

Grinding wheels

- balancing of, 609–610, 610
 - concentration, 600
 - FEPA and U.S. sizes compared, 602–603
 - radius and form dressing, 609, 609, 610
 - ring testing, 81–82, 82, 595–596, 596
 - size and shape, 600, 600, 601
 - standard wheel marking systems, 600–602
 - truing and dressing, 606–609
 - types of abrasives, 598–600
- Groove micrometers, 130, 130
- Grooving, on lathe, 459–461
- Guide for broaching, 41, 41
- Gun drills, 352, 352
- Gun taps, 68, 68

Hacksaws

- blade sets, 54, 55
- cuts on workpiece, 56, 56
- hand, parts, 54–55
- power, 302
- use of, 55–56

Half round files, 59, 59

Hammers

- ball peen, 48–49, 49
- cross peen, 49, 49
- for layout, 238–239, 239
- lead, 49, 49
- maul, 48, 48
- soft, 49, 49
- straight peen, 49, 49
- toolmaker's, 239, 239

Hand grinding, of drills, 358–361

Hand grinding cutters, 410–412

Hand protection, 9

Hand reamers, 63–66

- adjustable, 64, 64
- helical flute, 64, 64
- major parts, 63
- Morse taper socket, 64–65, 64, 65
- spiral flute taper pin, 64, 64
- straight flute, 64, 64
- use of, 65–66

Hand tap wrenches, 50, 52

Hand tappers, 72, 73

Hand tools

- hacksaws, 54–56
- safety, 36

Hardening of metals, 209–210, 210

Hardness, measurement of, 225, 226

Headstock spindle, engine lathe, 391–392, 392

Heat treating

- case hardening, 215–217
- furnaces for, 212–213
- problems during, 217–220
- quenching media, 213–214, 215
- safety, 196
- of steels, 210–212
- tempering, 215–217

Height gages

- checking zero reference, 252–253
- by coordinate measure, 256–257

- dial, 242, 242
- digital, 242, 242
- gage blocks, 242, 243
- mechanical dial, 251, 251
- scribers, 250, 251
- vernier, parts, 250

Helical flute hand reamers, 64, 64

Helical milling, CNC, 663, 667

Helix angle, of threads, 468, 468

Helpers, 4

Hermaphrodite calipers, 238, 238

Hidden lines, on drawings, 26–27, 27

High speed bearings

- types of bearings, 716

High speed lathe cutters, 405–407

High speed lathe tools

- angle degrees for, 409

High speed spindles, 715, 716

- types of bearings, 716

High-carbon steels, 284

High-velocity band machines, 309, 309, 310

Hole making cutting tools, 707–708, 707

Hook rule, 108, 108, 109

Hook spanner wrenches, 50, 51

Horizontal band machines, 302, 302, 303

- plate saws, 302, 303
- safety, 304–305, 304, 305

Horizontal band saws, 316

- installing blades, 315–316, 319, 320

operation, 316–317, 318

sawing problem, 320–321, 321

workholding, 318, 319

Horizontal milling machines

- arbor setups, 571–572, 572
- arbor support bearings for, 554–555, 554
- arbor types, 553–555
- attachment and accessories for, 547–548
- backlash eliminator, 546, 546
- bed type, 546
- controls, 550–551
- cutters, 556–561, 559–560
- cutting fluids, 569
- digital readout (DRO), 547, 547
- footstock for, 564, 564
- horsepower calculations, 568–569
- keyseat milling, 579–580
- knee and column, 546
- large CNC machining center, 547, 547
- locks, 551
- major parts, 549, 550
- milling cutters, 556–561
- plain milling, 567, 572–574, 574
- rotary tables, 564, 564
- routine maintenance, 551–552
- safety, 548
- setup, 567, 569–571
- side milling, 577–580, 580
- size, 549
- spacing and bearing collars, 553, 554
- spindle tapers, 553, 554
- squaring workpiece, procedure, 574–575, 575–576, 575, 576
- straddle milling, 580, 580

- Horizontal milling machines (*Continued*)
 table, 546, 549, 549, 562–563, 563
 types, 546
 wipers to protect accuracy, 551
 workholding, 562–566, 569, 570–571
- Horizontal spindle machining centers,
 CNC, 663, 664, 667, 670, 670, 671
- Horizontal spindle surface grinders. *See* Surface grinders
- Horseplay in the shop, 9–10
- Hot metal safety, 196
- Housekeeping, in machine shops, 10
- HSS cutting tools, 284
- Hub micrometers, 127, 127
- Hydraulic presses, 37, 37
- Hydrojet machining, 721, 721
- Hypotenuse, in right triangle, 178
- Inch/metric conversion tables, 753–754
- Indexable drills, 708, 708
- Indicating micrometers, 127, 127
- Indicating mill vise, procedure, 569–570
- Indicators
 dial and dial test, 155–161, 157
 electronic digital travel, 99–100, 99, 100
 surface finish, 98, 99, 99
- Infeed, 266
- Inserts, carbide, identification, 292, 296
- Inside micrometer calipers, 127, 127
- Inside micrometers, 136–138
- Inspectors, 4
- Interchangeable anvil micrometers, 127–128, 128
- Interference (press) fit, bushings, 39
- Interference fringes, 169, 170
- Interlocking joint pliers, 47, 47
- Internal infeed, calculation for threading, 482
- Internal micrometers, 127, 128
- Internal thread inserts, 21–22, 23
- Internal threads, cutting, 481–483
- Internally threaded fasteners, nuts, 20–22
- International System of Units (SI), 104
- Interrupted thread taps, 68, 68
- Jig boring, 512
- Job opportunities, 2–4
- Job selector
 horizontal band machines, 315, 315
 vertical band machines, 336, 337
- Just-in-time production, 516
- Kerf
 handsaws, 54, 55
 of saw blades, 313, 314
- Keys
 feathered, 25
 gib head, 25
 square, 25
 taper, 25
 Woodruff, 25
- Keyseats
 bores and shafts, 39–40
 defined, 37–38
- Keyways
 broaching, procedure for, 40–42
 milling
 horizontal mill, 579–580
 vertical mill, 535, 535
- Knee and column
 horizontal mill, 546
 vertical mill, 514
- Knife files, 58, 58
- Knurling, on lathe, 461–463
 toolholder types, 461, 461, 462
- Knurling tool, on lathe, 403, 403
- Large capacity band machines, 309, 310
- Laser interferometer, 101, 102
- Laser machining, 722, 722
- Lathe centers
 alignment, 415–450
 ball bearing, 435–436, 437
 dead, 435–436, 437
 half center, 430, 431
 pipe and tube, 437, 437
 types, 435–437
- Lathe cutters
 Acme threads, 507–510
 hand grinding procedure for, 410–412
- Lathe dogs, 435, 435, 437–438, 438
- Lathe files, 58, 58
- Lathe operations
 boring, 453–456
 center drilling, 432–433
 drilling, 400–401, 432–433, 451–453
 facing, 425–427
 grooving, 459–461
 knurling, 461–463
 parting, 459–461
 reaming, 456–457, 458
 recessing, 459–461
 tapping, 458–459
 threading, 470–480, 471–475
 toolposts, 399–400, 399, 400
 turning, 435–437
- Lathes
 apron, 392–393, 394
 automatic, with CNC, 384–385
 backlash compensating adjustments, 396, 396
 bed, 392, 394
 camlock spindle nose, 414, 414
 carriage, 392–393, 394, 491, 491
 chip control, 410
 cleaning the lead screw, 395, 395
 CNC chucks, 385, 386
 cutting fluid applications, 281–282
 cutting speed calculations, 439–441
 dead centers, 435–436, 437, 437
 files, 59, 59
 flturn, 385, 386
 follower rest, 500
 gib adjustment, 395–396, 396
 headstock, 391–392, 392
 headstock spindle, 391–392, 392

- independent four-jaw chucks, 414, 415
- internal threading, 481–483
- magnetic chucks, 416, 417
- maintenance and adjustments on, 395–397
- on-site machining, 387, 387
- saddle, 392
- safety, 387–390
- setup, for threading, 471–472
- six-jaw chucks, 414, 415
- spindle, 392, 413–416
- spindle tooling, 413–418
- steady rest, 496–499
- swing, measurement, 394
- tailstock, 393–394, 394, 396–397, 397
- tracer, 385, 386
- types, 384–386
- vertical boring mills, 384, 385
- ways, 392
- Layout
 - accessories for, 243, 243
 - basic precision practice, 255–259
 - clamp frame, 255, 255, 256
 - classifications, 236
 - dividers, 237–238, 238
 - drill and hole gage, 244–247, 248
 - dyes, 237, 237
 - geometric construction for bolt circles, 248–249
 - position-one, 255, 255–256
 - position-three, 255–256, 256, 257
 - position-two, 255, 256
 - precision practice, 250–260
 - preparation of workpiece, 244
 - round stock center, 497
 - scribers for, 237–238, 237
 - semiprecision, 244–249
 - tables, 236
 - tools for, 236–243
 - trammel points for, 238, 238
- Layout punches, 239–240, 240
- Layout tables, 236
- Layout tools
 - reshaping, 83
- Lead and lead alloys, 206, 206
- Least material condition (LMC), 187
- Length, 88–89, 88, 89
 - measurement rules, 759
- Lifting and hoisting, 195, 195
 - techniques for safe, 9, 10
- Light, measurements with, 100–102
- Lighting, importance of, 525
- Limit dimensioning, 184
- Limited machinists, 4
- Linear interpolation
 - CNC, 681–682, 681
 - linear, CNC, 683, 683
- Lock-out tag-out procedures, 11
- Long taper spindles, for lathe, 413, 414
- M codes, CNC programming, 674
- Machinability, 266, 273–274
- Machine bolts, 17, 17
- Machine hazards, 12
- Machine operators, 2–3
- Machine reamers, 377–379. *See also* Reamers; Reaming
 - arbor, 378, 378
 - chucking
 - carbide tip, 379, 379
 - helical flute carbide tipped, 379, 379
 - helical flute, 377, 378
 - helical taper pin, 378, 378
 - jobber's, 377, 378
 - Morse taper, 378, 378
 - rose, 377, 378
 - shell, 378, 378
 - taper bridge, 378–379, 378
 - taper shank helical flute, 377, 378
 - taper shank straight flute, 377, 378
 - types, 377–379
- Machine reaming
 - cutting fluids, 380
 - problems, 380–381
 - stock allowance, 380, 380
- Machine screws, 17, 17
- Machine screws, head styles, 18
- Machine tools
 - CNC, 660, 661, 662
 - speeds and feeds, 275–278
- Machines, for layout, 242–243, 243
- Machining centers
 - CNC, 663, 663–664
- Machining operations defined, 267–269
- Magnesium, 206
- Magnetic chuck lathes, 416, 417
- Magnetic chuck surface grinder, 621–622, 621, 622
- Magnetic chuck vertical mill, 525–526, 526
- Maintenance machinists, 4
- Mandrel grinding procedure, 643–644
- Mandrels
 - expanding type, 444, 445
 - gang, 444, 445
 - stub, 444, 445, 446
 - taper, for lathe work, 444
- Marine machinists, 4
- Material Safety Data Sheets (MSDS), 7
- Materials
 - for cutting tools, 284–298
 - hot metal safety, 196
 - lifting and hoisting, 195, 195
 - safety in carrying, 195
 - safety in handling, 196
 - selection and identification of steels, 197–202
- Maul hammers, 48, 48
- Maximum material condition (MMC), 187
- Measurement. *See also* Decimal equivalents; Metric system
 - area, 759
 - by comparison methods, 146
 - decimal equivalents of fractional inches, 752
 - electronic, 98–100, 98
 - inch/metric conversion tables, 753–754
 - length, 759
 - reference points, 107

- Measurement. *See also* Decimal equivalents; Metric system systems, 103–106
of tapers, 492–494
of threads, 477–480
volume and capacity, 760
weight, 760
- Mechanical dial measuring instruments, 93–97, 93, 94
- Mechanical dial travel indicators, 95–97, 98
- Mechanical hardware, 14–25
- Metal cutting, principles of, 266–271
- Metals. *See also individual metals*; Nonferrous metals alloys, 194
approximate melting points listed, 762
classifying, 195
density and specific gravity, 761
hardening of, 210–212, 210
machinability, 273–274
oxidation reduction process, 194
safety, 6
space-age, 194
- Meters, 104, 759
- Metric mechanical dial travel indicators, 106, 106
- Metric rules, 113–114, 114
- Metric system of measurement, 104–105
dual dimensioning of drawings, 29, 30
equivalent measurements of length, 759
inch/metric conversion table, 753–754
volume and capacity, 760
weight, 760
wire gages and metric equivalents, 764
- Metric threads
basic designations, 751
forms, 469, 469
- Metrology, 88
dimensional, 88
general principles, 89–91
- Micro drill presses, 342, 343
- Microinches, 29, 99
- Micrometer squares, 154, 155
- Micrometers
ball attachments, 130, 130
blade type, 125, 125, 126
caliper-type outside, 130, 130
carbide-tipped, 132
care of, 131–133
collars, on lathe, 422–423, 423
combination inch/metric, 125, 126
comparator type, 125, 126, 478, 478
depth type, 138–139, 138, 139
digital electronic, 130–131, 131
direct-reading, 127, 127
discrimination of, 131
disk type, 125, 126
groove type, 130, 130
hub, 127, 127
indicating bench, 98, 98
indicating type, 127, 127
inside, 127, 127, 136–138
interchangeable anvil, 127–128, 128
internal type, 127, 128
metric type, 139–142
outside, 130, 130, 191
point comparator, 125, 126
reading inch types, 133–134
reliability and accuracy, 131
screw pitch, 479
screw thread comparator, 125, 126
screw thread type, 128, 129
shop tip, 135
spline, 128, 128
square, 154, 155
taper, 130, 130
for taper measurement, 494, 495
thread comparator, 478, 478
tubing, 129–130, 129, 130, 139–130
turning to length, 444, 444
turning to size, 442, 442
types of, 125–131
using, 124–125
V-anvil, 129, 129
vernier, 143–144, 143
- Mill files, 58, 58
- Milling cutters
clearance angles, 645, 646, 647
horizontal milling machines, 556–561
safety, 557
sharpening, 647, 648
vertical milling machines, 517–521, 521
- Milling machine tapers, 485–494
- Miscellaneous function commands (M codes), 674
- Modal commands, CNC programming, 674, 675
- Modified square threads, form of, 500, 500
- Mold makers, 4
- Molybdenum, 206
- Morse taper drill sockets, 353, 356
- Morse taper reamers, 64–65, 64, 65
- Morse taper twist drills, 349–350, 350
- Morse tapers
dimensions for, 485, 486
drill chucks, 401, 402
drill sleeves, 353, 356
reamers, 378, 378
- MSDS (Material Safety Data Sheets), 7
- Multiple lead threads, cutting of, 503–506
- Multispindle drill presses, 343, 343
- Needlenose pliers, 48, 48
- Nickel, 206, 206
- Nickel-based alloys, 207
- Nonferrous metals
beryllium copper, 205
brass, 205
bronze, 205
cadmium, 204–205
chromium, 205
copper and copper alloys, 205
die-cast metals, 205
lead and lead alloys, 206, 206
magnesium, 206
molybdenum, 206
nickel, 206, 206
nickel-based alloys, 207
precious metals, 207
safety, 6

- selection and identification, 203–208
- tantalum, 207
- tin, 207, 207
- titanium, 207, 208
- tungsten, 208
- zinc, 208
- zirconium, 208
- Normalizing, 221–222, 221
- Nose
 - engine lathe spindles, 392, 393
 - lathe spindles, types, 413–416
- Nut taps, 70, 70
- Nuts, common types, 20–21, 21

- Oblique drawings, 26, 27
- Obtuse angles, defined, 174, 174
- Occupational Safety and Health Act (OSHA), 7, 12
- Offset boring heads
 - controlling bore diameters, 542
 - facing with, 542, 543
 - feeds and speeds, 542
 - parts of, 540, 541
 - setup, 541, 541
- Open ended wrenches, 49, 50
- Optical center punches, 239–240, 240
- Optical comparators, 101, 101, 161, 161
 - for thread measurement, 479, 480, 481
- Optical flats, 100–101, 101, 169
 - for checking gage blocks, 169, 169–170
- Orthographic drawings, 26–28, 27
- Orthographic projections, on drawings, 26, 27
- Outside micrometers, 130, 130, 191
 - care of, 131–133
 - major parts, 131

- Parabolic and cubic interpolation, 688
- Parallax errors, 110, 110
- Parallel clamps, 47, 47
- Parallels
 - adjustable, 148–149, 149, 150
 - drill press setup tools, 366–367, 367
 - in layouts, 254
- Parting, in lathe, 459–461
- Pedestal grinders
 - adjusting spark guard, 82, 82
 - adjusting tool rest, 82, 82
 - dressing wheel, 82, 83
 - for drill grinding, 358–361
 - replacing wheel, 81, 81
 - safety, 82, 84
 - setup, 81–82
 - using, 82–83, 82
- Percentage, of threads, 468
- Personal safety, 6–7
- Pillar files, 58, 58
- Pilots, for counterbore, 375, 375
- Pin punches, 52, 53
- Pins, types of, 24, 24
- Pipe and tube centers, 437, 437
- Pipe and tube lathe centers, 437, 437
- Pipe thread taps, 69, 69
- Pipe wrenches, 50, 51

- Pitch
 - bandsaw blades, 314, 314
 - diameter, of threads, 468, 468
 - hand hacksaw blades, 55, 55
 - screw threads, 466
- Plain milling, horizontal mill, 572–574, 574
- Planer gages, 151–152, 151–152
 - for layout, 242, 243
- Plasma beam machining, 721–722
- Plate protractors, 175, 176
- Plate saws, 302, 303
- Pliers
 - interlocking joint, 47, 47
 - needlenose, 48, 48
 - round nose, 47–48, 47
 - side cutting, 48, 48
 - slip joint, 47, 47
 - vis grip, 48, 48
- Plug gages
 - for taper measurement, 492–493
- Plug taps, 67, 68
- Plunge cutting, 533–534, 534
- Pneumatic comparators, 92–93
 - See also Air gages
- Point comparator micrometers, 125, 126
- Polar coordinates, CNC, 669, 670
- Position dimensioning systems, CNC machines, 668–672
- Position, of linear measurement instruments, 90, 90
- Power fed worktables, on band machines, 308–309, 309
- Power hacksaws. See Reciprocating cutoff machines
- Precious metals, 207
- Precision
 - layout, 244–260
 - in measurement, 89–90
- Precision beveled edge squares, 152–153, 153
- Precision height gages, 159–160, 160
 - with gage blocks, 171, 173
- Precision measurements, 90
- Precision vise project drawings, 766–769
- Press fits
 - dimensional allowance for, 185
 - surface finish for, 185
- Presses. See also Drill presses
 - arbor, 37–38, 38, 41, 42
 - hydraulic, 37
 - mechanical, 37, 38
- Pressing
 - bearings, 39, 39
 - bushings, 38–39, 40
- Pressure-type air gages, 92, 93
- Prick punch, for layouts, 239, 239
- Primary clearance angles, milling cutters, 645, 647
- Process annealing, 222–223
- Product technicians, 4
- Profile projectors, 163, 163, 164
- Programmable axes, CNC machine tools, 668–672
- Programmable rotary table, 663, 666
- Programming, defined, 673
- Programming methods
 - CNC, 673
 - prompted programming systems, 699–702
- Projections, on orthographic drawings, 26, 27

- Pulley taps, 69–70, 70
 Punch layout, 239–240, 240
 Punches
 drift, 353, 356, 356
 pin, 52, 53
 prick, for layout, 239, 239
 types, 52, 53
- Quadrants, CNC, 668, 669
 Quenching media
 heat treating, 213–215
 Quick change gear box, engine lathe, 394, 394, 422
 Quick change tool holders, engine lathe, 399–400, 399, 400
 Quick change tooling, drill press, 366, 366
 Quick change tooling system
 for vertical mill, 521, 522
- R-8 collets, for milling machine, 521
 Radial arm drill presses, 342, 342, 347, 348, 348
 major parts of, 347, 348, 348
 Radian measurement, 174–175, 174
 Radius gages, 149, 151
 Rake, on cutting tools, 266, 269
 Ram turret lathes, 384, 385, 386
 Ram vertical mills, 514, 515
 Ratios, trigonometric, 257
 Reading drawings, 26–32
 Reamers. *See also* Machine reamers
 adjustable, 64, 64
 carbide-tipped expansion, 379, 379
 carbide-tipped helical flute chucking, 379, 379
 chucking, 377, 378
 hand, 63–66
 machine, parts of, 377, 377
 shell, 378, 378
 taper pin, 378, 378
- Reaming
 CNC cutting tools, 709, 709
 in drill presses, 377–381
 by hand, 65–66
 on lathe, 456–457, 458
 Reaming cutting tools, 709, 709
 Reciprocating cutoff machines, 315
 blade selection, 314–315
 operation, 315–316
 Reciprocating saws, 302
 safety, 304
 Recovery, recrystallization and grain growth, 223, 223
 Rectangular coordinates, CNC, 668, 669
 Regardless of feature size (RFS), 187
 Reliability
 in measurement, 90
 using steel rules in measurement, 107–108
 Remote gaging, 98–99, 99
 Re-sharpening milling cutters, 650–656
 Retaining rings, 24, 24
 Re-threading dies, 78, 78
 Right angle, defined, 174, 174
 Right-angle trigonometry, 177–178, 177–182
 Right-triangle solution formulas, 763
 Ring and rocker tool posts, for engine lathe, 403
 Ring gages, for taper measurement, 492–493
 Ring test, grinding wheels, 81–82, 82, 595–596, 596
 Rockwell and Brinell Hardness testers, 225–233
 Rockwell hardness tester, use, 225–231, 228
 Roller burnishing tools, 711, 711
 Roll grinding machines, 588–589, 590
 Rose reamers, 377, 378
 Rotary tables, 537, 538
 horizontal milling machines, 564, 564
 Roughing, 277
 Roughness average (Ra), 99
 Roughness profiles, 99
 Round files, 59, 59
 Round nose pliers, 47–48, 47
 Round stock center layout, 240, 241, 497
 Roundness, defined, 88
 RPM, formula for calculation
 drill presses, 362
 lathes, 275, 431
 milling machines, 530–531, 567–568
 Rule depth gages, 109–110, 109, 110
 Rule measuring instruments, 107–115
 Rules
 applications of, in measurement, 110–111
 care of, 110
 decimal, 112–113, 113
 discrimination, 107
 flexible, 108, 108
 hook, 108, 108, 109
 metric, 113–114, 114
 narrow, 108, 108
 reading of, 111–114
 rigid steel, 108, 108
 short set, 108, 109
 slide caliper, 108, 109
 types, 108–110
- Saddles, on engine lathes, 392
 Safety
 abrasive sawing machines, 324
 checklist, for machines, 12
 chip formation when turning, 442, 442
 chip handling, 264, 387, 388, 389
 CNC machines, 665, 666
 cutoff machines, 304–306, 306
 drill presses, 344–345, 345
 federal laws, 12
 grinding machines, 596–597, 596, 597
 hand tools, 36
 hot metals, 196
 lathes, 387–390
 machine shop, 6–13
 milling machine, 512–513, 548
 pedestal grinders, 82, 84
 turning between chuck and center, 439
 Safety glasses, types of, 7, 7, 8
 Saw blades
 blade width, 314, 314
 gage of, 314, 314
 kerf, 313, 314
 materials, 313
 pitch, 314, 314
 saw tooth terminology, 314

- selection, 314–315
- set patterns, 314, 315
- tooth forms, 314, 314, 335, 335
- Saw teeth, set of, 54, 55, 322
- Saws
 - cold saws, 325, 325
 - safety, 306, 306
 - horizontal band saws, 302, 302, 303
 - reciprocating saws, 302
 - tilt frame band saws, 302–303, 303, 304
- Scale, defined, 107
- Scale drawings, 107
- Scale measuring instruments, 107
- Screw pitch gage, 466
- Screwdrivers
 - hollow grinding, 83, 83
 - offset, 50, 52
 - Phillips, 50, 52
 - standard blade, 50, 52
- Screws
 - cap, 17, 19
 - defined, 16
 - drive, 20, 22
 - head styles, 18
 - machine, 17, 17
 - self-tapping, 21
 - set, 18, 20
 - thread-cutting, 20, 21
 - thumbscrews, 20, 20
 - wing, 20, 20
- Screw thread micrometers, 128, 129, 479, 479
- Screw thread comparator micrometers, 125, 126
- Scribers
 - height gages, 250, 251
 - layout, 237–238, 237
- Secondary clearance angles, on milling cutters, 646, 647
- Sectioned views, on drawings, 27, 28
- Seizing, defined, 39, 40
- Selecting and identifying nonferrous metals, 203–208
- Selecting and identifying steels, 197–202
- Self tapping screws, 21
- Semiprecision layout, 244–249
- Sensitive drill presses, 342, 342, 346, 346
 - major parts of, 346, 347
- Serial taps, 68, 68
- Set screws, 18, 20
 - jackscrews, 18, 20
 - points, 18–19, 20
 - square head, 18, 20
- Setup persons, 3
- Shapes, steel bars, 201, 201
- Sharp vee thread forms, 465, 466
- Sharpening drills, on pedestal grinders, 358–361
- Sharpening milling cutters, 647, 648
- Shear flow, 279, 279
- Shell reamers, 378, 378
- Shim, for keyway broach, 41–42, 42
- Shop hazards, identification of, 10–12
 - See also Safety
- Shop presses
 - bending and straightening, 42–43
 - safety, 43
 - installing bushings, procedure for, 38–39, 39, 40
 - mandrels, 40, 40
 - types of, 37–38, 38
- Shop safety, 6–13. See also Safety
- Shrink fits, 185
- Side cutting pliers, 48, 48
- Side milling cutters, horizontal mill, 577–580, 580
- Silicon carbide, 598, 599
- Sine bar and gage blocks
 - for taper measurement, 493, 495
- Sine bars
 - angular measurements, 179–180, 181
 - constant tables, 181–182
- Sine ratio
 - acute angles, defined, 257
 - trigonometry, 177–182
- Single depth threads
 - external, 466, 467, 480, 481
 - internal, 483, 483
- Single-point threading, 663, 666, 689–690, 697–698
- Sinometer angle gages, 175, 176
- Sintering, 284
- Six-jaw universal chucks, for lathe, 414, 415
- Sixty-degree thread, calculations for, 465–469, 466
- Slide caliper rules, 108, 109
- Slip joint pliers, 47, 47
- Small hole gages, 148, 149, 150
- Snap gages, 91, 92
- Socket head wrenches, 50, 51
- Socket sets, 50, 50
- Socket wrenches, 50, 50
- Soft jaws, for lathe chuck, 416, 416
- Solid beam square, 152, 153
- Solid collets, for vertical mill, 521, 521
- Solid square dies, 78, 79
- Spade drills, 351, 351, 352, 709
- Spanner wrenches, types of, 50, 51
- Spark guards, pedestal grinder, 82, 82
- SPC. See Statistical process control
- Speeds
 - reaming, 379
 - tapping, 73–74
- Speeds and feeds
 - calculations for, 275–278
 - for machine tools, 275
- Sphericity, defined, 88
- Spheroidizing, 222, 222
- Spindle drill presses, 343, 343
- Spindle horizontal milling machines, 551
- Spindle lathe headstock, 391–392, 392
- Spindle lathes, tooling for, 413–416
- Spindle tapers
 - horizontal milling machines, 553, 554
- Spiral flute taper pin hand reamers, 64, 64
- Spiral fluted taps, 69, 69
- Spiral pointed taps, 68, 68
- Spline micrometers, 128, 128
- Spot drilling, 432–433, 433
- Spotfacing, 375–376, 376
 - defined, 29
 - symbols, 30
- Spotting drill, 351, 351

- Spring calipers, 146, 147
 - Spring cleaner, for lathe, 414, 414
 - Spring collets, 418, 418
 - Square files, 58, 58
 - Square keys, 25
 - Square micrometers, 154, 155
 - Squareness, defined, 89
 - Squares
 - cylindrical, 153–154, 153, 154
 - diemaker's, 154, 154
 - micrometer, 155
 - precision beveled edge, 152–153, 153
 - solid beam, 152, 153
 - Square threads, form of, 500, 500
 - Squaring workpiece, horizontal mill, 574–576, 575, 576
 - Stainless steels, 198
 - Standard tolerances, 184–185
 - Statistical process control (SPC), 183, 187, 189–191
 - tools for, 190–191
 - Statistics, in process control, 187
 - Steady rest
 - adjustment of, 496–497
 - use of, 498, 499
 - Steady rest lathes, 496–499
 - Steel bars, shapes, 201, 201
 - Steel rules, 107–115
 - Steels
 - alloy, 197
 - approximate melting points, 762
 - case hardening and tempering, 215–217
 - costs of, 202
 - heat treating, 210–213
 - identification systems, 197–198
 - pig iron, 195
 - selecting and identifying, 197–202
 - shafting, 202
 - shop tests for identifying, 199–201
 - stainless, 198
 - tool, 198–200
 - Steel-spring collets, for lathe, 417, 417
 - Step blocks, drill press workholding, 366, 367
 - Step drills, 351
 - Straddle milling, horizontal mill, 580, 580
 - Straight flute hand reamers, 64, 64
 - Straightness, defined, 88
 - Straight peen hammers, 49, 49
 - Straight pipe taps, 69, 70
 - Straight shank machine reamers, 378
 - Strap clamps, 366, 366, 367
 - drill press, 366, 366, 367
 - Strap wrenches, 50, 51
 - Stress relief anneal, 222, 222
 - Stub mandrels, 444, 445, 446
 - Stud bolts, 17, 17
 - Subland drill, 351
 - Superabrasives, 593–594
 - ratios contrasted, 625
 - Supermicrometers, 98, 98
 - Surface finish indicators, 99, 99
 - Surface gages, 240–241
 - Surface grinders, 586–588
 - accessories for, 618–619
 - chucks
 - care of, 622, 623
 - grinding-in, 626
 - setups, 623–624
 - types, 621–622, 621, 622
 - creep-feed grinding, 619
 - holding thin workpieces, 623–624
 - major parts, 617–618, 617, 618
 - nonmagnetic workpieces, 623, 624
 - odd-shaped workpieces, 623, 623
 - problems and solutions in grinding, 632–634
 - Type I surface grinder, 586–587, 587
 - Type II surface grinder, 586, 587, 587
 - Type III surface grinder, 586, 587, 587
 - use, 625–631
 - vee blocks grinding, 623, 626–631
 - workholding, 621–622, 621, 622
 - Surface plates
 - grades of, 236
 - types, 236
 - Surface roughness instruments, 99, 99
 - Swing of engine lathe, measurement, 394
 - Swiss pattern files, 59, 59
-
- T-bolts, 366, 367
 - T-slots, machining, 535–537
 - T-handle tap wrenches, 50, 52, 72, 72
 - Table horizontal mill, 546, 549, 562–563, 563
 - Table surface grinders, 586–587, 587
 - Table vertical mills, 514, 515
 - Tailstock centers, alignment, 415–450
 - Tailstock chucks, 432, 432
 - Tailstock engine lathes, 393–394, 394, 396–397, 397
 - Tailstock turrets, engine lathe, 400, 401, 401, 402
 - Tang files, 59, 61
 - Tangent ratio, of acute angle defined, 257
 - Tang twist drills, 350, 350
 - Tantalum, 207
 - Tap drills, 72–73, 73
 - size chart, 755
 - metric, 756
 - Tap wrenches, 50, 52, 72, 72
 - Taper bridge machine reamers, 378–379, 378
 - Taper micrometers, 130, 130
 - Taper milling machine arbors, 486
 - Taper per foot (tpf), 485–486
 - Taper pin reamers, 378, 378
 - Taper pipe thread
 - American National, 468, 469
 - Taper plug gages, 91, 92
 - Taper ring gages, 91, 92, 492–493
 - Taper shank drill sleeves, 394
 - Taper taps, 67, 68
 - Tapers, cutting of
 - compound slide method, 486–487
 - measurement of, 492–494
 - offset tailstock, 487–490
 - taper attachment, 490–492
 - plain taper, 490, 490, 491
 - telescoping taper, 490, 490, 491

- taper length taper portion (chart), 757
 - with angles, 758
 - uses of, 485–486
- Tapers, defined, 485
- Tapping
 - CNC cutting tools, 689, 709–710
 - with drill presses, 74–76
 - by hand, 74–76
 - lathe, 458–459
 - procedures, 72–76
 - safety, 74
 - speeds, 73–74
 - tap extractors, 74, 74
 - thread depth percentage, 73
- Taps
 - Acme threads, 70, 70, 509, 510
 - blind hole defined, 68
 - bottoming, 67–68, 68
 - chamfer, 67, 67
 - drill sizes, 73
 - gun type, 68, 68
 - identifying markings, 68, 68
 - interrupted thread, 68, 68
 - major parts, 67
 - nut, 70, 70
 - pitch diameter relief, 71, 71
 - plug, 67, 68
 - pulley, 69–70, 70
 - rake and hook angles, 70, 70
 - reducing friction when using, 70–71
 - serial, 68, 68
 - spiral fluted, 69, 69
 - spiral point, 68, 68
 - straight pipe, 69, 70
 - surface treatments, 71
 - taper pipe thread, 69, 69
 - taper type, 67, 68
 - thread forming type, 69, 69
- Telescoping gages, 146–148, 147–149
- Tempering, of steels, 215–217
- Test indicators, 157, 157
- Thickness gages, 149–151, 151
 - dial type, 93, 95
- Thread cutting
 - infeed calculations, 467, 468
- Thread cutting dies, 77–80
- Thread cutting screws, 20, 21
- Thread engagement defined, 16
- Thread files, 59, 60
- Thread fit classifications, 467
- Thread forming taps, 69, 69
- Thread forms
 - Acme, 502–503, 503
 - American National, 466
 - standard taper pipe, 468, 469
 - American Standard Stub Acme, 503, 503
 - buttress, 503, 504
 - general purpose Acme, 503, 503
 - lead, defined, 504
 - metric, 16, 469, 469
 - modified square, 500, 500
 - multiple lead, 503–506
 - sharp vee, 465, 466
 - square, 500, 500
 - thread-chasing dial, 505, 505
 - UNC, 15
 - UNF, 15
 - unified, 14, 466
 - UNS, 15
- Thread grinders, 592, 593
- Thread measurement, 477–480
 - external, 477–478
 - internal, 483, 483
 - methods, 91, 92, 477–480
 - new advanced methods, 478
 - optical comparator, 480, 481
 - plug gage, 91, 92, 483, 483
 - ring gage, 91, 92, 92, 474, 477, 477
 - sharp vee form, 465, 466
 - symbols for, 31
 - three-wire method, 478–480
- Threading, on lathe, 470–475
- Threading dies, 459, 459
 - by hand, 79–80, 80
 - lathe, 483
 - types, 77–79
- Threading tools, lathe, 408–409, 409
- Threaded fasteners
 - external, 16–21
 - identification, 15
 - internal thread inserts, 21–23
 - standard series, 15, 15–16
- Threaded spindle, for lathe, 413–414, 413
- Threads
 - classes of fits for, 15
 - cutting, on lathe, 471–475
 - designations, 467
 - drawings notations, 29–30
 - fit classifications, 467
 - forms of, 14–15
 - internal inserts, 21–22, 21, 23
 - metric, 16, 751
 - per inch, measurement, 466
 - symbols on drawings, 31
 - tolerance symbols, 751–752
- Three-jaw chucks, for lathe, 414, 415, 415
- Three-square files, 59, 59
- Three-view drawings. *See* Orthographic drawings
- Tilt frame band saws, 302–303, 303, 304
- Tin, 207, 207
- Titanium, 207, 208
- Tolerance limits, 183
- Tolerance symbols, 751
- Tolerances
 - bilateral, 28
 - decimal inch notations for, 184, 752
 - defined, 28
 - effect on mating parts, 184, 184
 - geometric, 186–187
 - limit notations for, 183, 183
 - metric notations for, 184

- Tolerances (*Continued*)
 plus-minus, 183–184
 standard, 184–185
 unilateral, 28
- Tool and cutter grinders
 additional capabilities of, 656, 657
 clearance angles, 650
 CNC advances, 656, 658
 cutter tooth rests for, 648, 649
 major parts of, 645, 646
 setup for cutter grinding, 650, 650
 sharpening
 cup wheel method, 651–652
 end mills, 654–656, 655, 657
 form-relieved cutter, 652–653, 654
 plain milling cutter, 647, 648
 safety, 655
 slitting saw on, 652, 652
 staggered-tooth cutter on, 652, 653, 654
 straight-wheel method, 652
 wheel abrasives for, 647–648
- Tool and die makers, 4
- Tool bit, lathe, grinding of, 410–412
- Tool breakdown, 264
- Tool length gages, CNC, 678, 678
- Toolhead vertical mill, 515, 515
 major parts of, 514–515, 514
- Toolholders
 carbide, identification systems for, 292, 295, 296
 CNC machining center, 663, 663
 engine lathe, 399–400, 399, 400
 engine lathe tailstock, 401–404
 milling machine, 521, 521
 offset, 403, 403
 straight shank, 402–403, 403
- Tooling, CNC, 705–717
- Tool rest, on pedestal grinders, 82, 82
- Toolmaker's hammers, 239, 239
- Toolmaker's microscopes, 100, 100
- Tool steels, 198–200
- Tools
 ceramic, 288, 294, 297
 dimensional measurement, 91–102
 drilling, 349–357
 hand, 45–53
 shapes most often used, 407, 407
- Tools, cutting
 drill press, 349–357, 350
 horizontal milling machine, 556–561
 lathe, 405–407
 materials for, 284–298
 metal-ion implantation, 520
 vertical milling machine, 517–520, 521
- Tooth forms, for saw blades, 314, 314
- Torque wrenches, 50, 51
- Touch sensor inspections systems, 715, 715, 716
- TPI (threads per inch), 466
- Trammel points, for layout, 238, 238
- Transfer measurement, 146
- Travel error, 158, 158
- Travel indicators, 99–100, 99, 100, 106, 106
- Trepanning cutting tools, 709
- Triangles, right, 257–260
 solution formulas, 763
- Trigonometry
 calculations for, in layouts, 258
 cosine ratio, 257
 definitions, 177–179, 257
 ratios for acute angles, 258
 sine ratio, 177–182, 257
 tangent ratio, 257
- Truing, of grinding wheels, 606, 607
- Tubing micrometers, 129–130, 129, 130, 138–139
- Tungsten, 208
- Turning
 center CNC, 661, 662, 663
 between centers, setup, 435
 chip safety, 442, 442
 drive (dog) plate, 435, 436
 finishing, 443, 443
 intermittent cuts, 441
 to length, procedure for, 443–444, 444
 safety, 439
 to size, procedure for, 442–443
 speeds and feeds, 439–441
 tapering wear, 443
 time for roughing and machining, 441
- Turning lathe operations, 435–437
- Turn/mill centers, 663
- Turret drill presses, 342, 343, 343
- Turret lathe tailstock, 400, 401
- Turret lathe toolpost, 401, 401, 402
- Turret lathes, 384, 385, 386
- Twist drills, 264, 264, 349–350, 349, 350, 351, 352
- Two-jaw universal chucks, for lathe, 414, 415
- Type I surface grinder, 586, 587
- Type II surface grinder, 586, 587
- Type III surface grinder, 586, 587
- Ultrasonic machining, 721, 721
- Unified external thread, cutting, 470–480
- Unified thread form, 466–467, 466
 major parts, 14
- Unilateral tolerances, 28
- Universal bevel vernier protractors, 176–177, 176
- Universal chucks, for lathe, 414–416, 415
- Universal tool and cutter grinders. *See* Tool and cutter grinders
- Universal vise, milling machine, 537, 537
- Upright drill presses, 346–347, 348
 heavy duty, 342, 342, 345
- User accuracy, 89
- V-anvil micrometers, 129, 129
- Vacuum chucks, for surface grinders, 622, 622
- Variables, in measurement, 91
- Vee blocks
 defined, 42
 drill press workholding, 369, 369
 grinding, 623, 626–631
 use in layouts, 243, 243, 253, 254
- Vernier
 coincident line, 116, 117
 principle of, 116, 117

- reliability and expectation of accuracy, 117
- shop tip, 119
- use of, 116
- Vernier bevel protractors, reading of, 177
- Vernier calipers
 - depth gage, reading of, 121
 - inch, 119, 119
 - metric, 119–121, 121
 - procedure for use, 119
 - reading of, 119–121
- Vernier height gages, 250–251
 - applications of, in layouts, 253, 253–254
 - checking zero reference, 252–253
 - discrimination and application, 116–117, 159
 - reading of, 251–252, 251–252
- Vernier micrometers, 143–144, 143
- Vertical band machines, 302, 306, 306
- Vertical band saws
 - adjusting coolant nozzle, 331–332, 332, 339, 340
 - applications of, 310, 310, 311
 - bands
 - adjusting tension, 333, 333
 - adjusting tracking, 333, 333
 - installing band guides, 330–331, 330, 331
 - selecting, 335–336, 336
 - setting velocity, 336–337, 337
 - welding, 326
 - contour sawing, 310, 310, 339–340, 340
 - friction sawing, 310, 311
 - operation, 335–340
 - other adjustments, 334, 334
 - safety, 311–312, 312
 - setting speed ranges, 337–338, 338
 - straight sawing, 338–339, 338, 339
- Vertical milling machines
 - backlash, 526
 - base and column, 514
 - climb milling, 530
 - CNC, 512, 512
 - coaxial dial indicators, 527, 527
 - conventional milling, 530
 - cutter holding on, 521, 522
 - cutting fluids for, 532–533
 - cutting speed calculations, 530–531
 - cutting tools, 517–520, 521
 - digital readout (DRO), 106, 106, 529, 529
 - face milling, 538–539
 - feed rate calculations for, 531–532
 - hole center locating, 526–527, 527
 - keyseat milling, 535, 535
 - locks, adjustment and maintenance of, 516
 - machining holes in vise body, 527–529
 - machining steps and squaring, 533
 - major parts, 514–515, 514
 - mill vise, 525–526
 - milling a cavity, 534–535
 - milling cutters, 517–520, 521
 - offset boring head, 540–543
 - operations, 530, 532, 533–539
 - plunge cutting, 533–534, 534
 - quill, 514, 515
 - ram, 514, 515
 - rotary tables, 537, 538
 - saddle, 514, 514
 - safety, 512–513
 - setups, 523–529
 - spindle on, 514, 515
 - squaring tool head, 523–524
 - standard, 512, 512
 - table, 514, 515
 - toolhead, 515, 515
 - touch-sensing probes, 527, 527
 - workholding on, 525–526
- Vertical spindle machining center
 - CNC, 663, 664, 665
- Vise body
 - machining holes in, 527–529
- Vise grip C-clamps, 48, 48
- Vise grip pliers, 48, 48
- Vises
 - care of bench, 46
 - cutaway view, 46
 - drill press work holding, 367–368, 368
 - mill, 569
 - milling machine, 563, 563
 - precision vise drawing project, 766–769
 - soft-jaw, 525, 526
 - types of, 45
 - uses of, 45–46
- Volume and capacity, measurements of, 760
- Warding files, 58, 58
- Washers
 - flat, 23, 23
 - lock, 23–24, 23
 - types, 23–24, 23
- Wear blocks, 171, 172
- Web, on twist drills, 358, 359
- Weight, measurements of, 760
- Welds, band saw blades, grinding, 329, 329, 330
- Wigglers, use in drill press, 369–370, 370
- Wire gages and metric equivalents, 764
- Wires, for thread measurement, 478–480
- Woodruff keys, 25
- Woodruff keyseat cutters, 519, 519
- Workholder turning lathe operations, 438, 438
- Workholding drill presses, 366, 367, 368–371
- Workholding grinding machines, 621–622, 621, 622
- Workholding hand tools, 45–48
- Workholding horizontal band saws, 318, 318
- Workholding horizontal mill, 562–566
- Workholding lathes, 413, 417
 - centering accuracy in inches, 418
- Workholding vertical milling machines, 525–528
- Wrenches
 - adjustable, 50, 51
 - box end, 49–50, 50
 - combination, 50, 50
 - crescent, 49, 50
 - hand tap, 50, 52
 - open-ended, 49, 50
 - pipe, 50, 51
 - safety, 53
 - socket, 50, 50

Wrenches (*Continued*)

spanner, types, 50, 51

strap, 50, 51

T-handle for taps, 50, 52, 72, 72

tap, 50, 52, 72, 72

torque, 50, 51

X-axis, CNC, 668, 669

X-Y plane, CNC, 668-669, 669

X-Z plane, CNC, 669

Y-axis, CNC, 668, 669

Y-Z plane, CNC, 669

Z-axis, CNC, 668-669, 669

Z-axis tool offsets

CNC, 677, 677

Zero reference, on height gages, 252-253

Zinc, 208

Zirconium, 208