


SECOND EDITION

WELDING



Don Geary
Rex Miller

CONTENTS

| | |
|---|-------------|
| Preface | xv |
| Acknowledgments | xvii |
| Introduction—Welding, Soldering, and Brazing workers | 1 |
| Nature of the Work | 1 |
| Working Conditions | 3 |
| Training, Other Qualifications, and Advancement | 4 |
| Employment | 5 |
| Job Outlook | 5 |
| Earnings | 6 |
| Related Occupations | 7 |
| Sources of Additional Information | 8 |
| Chapter 1 Oxyacetylene Welding Fuels | 9 |
| Performance Objectives | 9 |
| History of Gas Welding | 10 |
| Oxygen | 12 |
| <i>Liquid-Air Process</i> | 12 |
| <i>Cylinders</i> | 13 |
| <i>Safety Practices</i> | 14 |
| Acetylene | 16 |
| <i>Carbide-to-Water Generators</i> | 17 |
| <i>Containers</i> | 17 |
| <i>Precautions</i> | 19 |
| Review Questions | 20 |

| | | |
|------------------|--|-----------|
| Chapter 2 | Oxyacetylene Welding Equipment | 23 |
| | Performance Objectives | 23 |
| | Regulators | 24 |
| | <i>Single-Stage Regulators</i> | 24 |
| | <i>Two-Stage Regulators</i> | 24 |
| | <i>Differences</i> | 26 |
| | <i>Regulator Freezing</i> | 28 |
| | <i>Jump</i> | 29 |
| | <i>Creep</i> | 30 |
| | Hoses | 30 |
| | Torches | 33 |
| | <i>Injector Blowpipes</i> | 33 |
| | <i>Medium-Pressure Blowpipes</i> | 34 |
| | Tips | 37 |
| | <i>Cutting Attachments</i> | 38 |
| | <i>Slag and Flashback</i> | 39 |
| | Clothing and Gear | 40 |
| | Wrenches | 41 |
| | Flashback Arrestors and Check Valves | 41 |
| | Lighters | 42 |
| | Review Questions | 43 |
| Chapter 3 | Setting Up an Oxyacetylene Outfit | 45 |
| | Performance Objectives | 45 |
| | Attaching Regulators and Hoses | 46 |
| | Opening Valves | 47 |
| | Setting Working Pressures | 47 |
| | Lighting the Torch | 48 |
| | <i>Acetylene Flame</i> | 49 |
| | <i>Carburizing Flame</i> | 49 |
| | <i>Neutral Flame</i> | 49 |
| | <i>Oxidizing Flame</i> | 50 |
| | Concluding Tasks | 51 |
| | Review Questions | 53 |

| | | |
|------------------|--|-----------|
| Chapter 4 | Other Types of Welding and Equipment | 55 |
| | Performance Objectives | 55 |
| | Arc Welding | 56 |
| | <i>Electrodes</i> | 56 |
| | <i>Current-Supplying Machine</i> | 58 |
| | <i>Protection Gear</i> | 59 |
| | <i>Striking an Arc</i> | 60 |
| | <i>Cutting Metal</i> | 63 |
| | Tungsten Inert Gas Welding | 63 |
| | Gas Metal Arc Welding | 64 |
| | Additional Welding Processes | 66 |
| | Welding of Plastics | 76 |
| | Review Questions | 76 |
| Chapter 5 | Metals and Their Properties | 79 |
| | Performance Objectives | 79 |
| | History of Metals | 80 |
| | <i>Copper</i> | 80 |
| | <i>Iron</i> | 81 |
| | <i>Steel Making Processes</i> | 81 |
| | Physical Properties of Metals | 82 |
| | <i>Color</i> | 82 |
| | <i>Magnetism</i> | 83 |
| | <i>Melting Point</i> | 84 |
| | Chemical Properties of Metals | 84 |
| | Mechanical Properties of Metals | 86 |
| | <i>Tensile Strength, Ductility, and Hardness</i> | 86 |
| | <i>Compressive Strength, Toughness, and Malleability</i> | 87 |
| | <i>Impact Strength, Fatigue, and Brittleness</i> | 88 |
| | <i>Stress, Elasticity, and Creep</i> | 89 |
| | Metal Identification | 89 |
| | <i>Chip Test</i> | 90 |
| | <i>Spark Test</i> | 90 |
| | Iron | 94 |
| | Steel | 95 |
| | Copper | 96 |
| | Aluminum | 96 |

| | | |
|------------------|---|------------|
| | Magnesium | 98 |
| | Sources of Metals | 98 |
| | <i>Obtaining New Steel</i> | 98 |
| | <i>Obtaining Scrap Metal</i> | 99 |
| | Review Questions | 100 |
| Chapter 6 | Welding Supplies | 101 |
| | Performance Objectives | 101 |
| | Welding Rods | 102 |
| | Brazing Rods | 103 |
| | Surfacing Rods | 103 |
| | Fluxes | 104 |
| | Review Questions | 105 |
| Chapter 7 | Soldering | 107 |
| | Performance Objectives | 107 |
| | Tools | 109 |
| | <i>Soldering Irons</i> | 109 |
| | <i>Soldering Guns</i> | 110 |
| | <i>Torches</i> | 110 |
| | <i>Copper Tips</i> | 111 |
| | Choosing the Proper Solder | 114 |
| | Leadless Solder | 117 |
| | Fluxes | 118 |
| | <i>Noncorrosive Fluxes</i> | 118 |
| | <i>Corrosive Fluxes</i> | 118 |
| | <i>Flux and Solder Combinations</i> | 119 |
| | Surface Preparation | 120 |
| | Technique | 123 |
| | <i>Tinning the Tip</i> | 123 |
| | <i>Heating the Work Metal</i> | 124 |
| | <i>Tinning the Surface</i> | 125 |
| | <i>Chunky Solder</i> | 126 |
| | <i>Cooling and Cleaning the Soldered Area</i> | 127 |
| | <i>Soldering with a Flame</i> | 127 |
| | <i>Soldering Copper Plumbing Pipe</i> | 128 |

| | | |
|------------------|----------------------------------|------------|
| | Safety Considerations | 129 |
| | <i>Eye Protection</i> | 130 |
| | <i>Adequate Ventilation</i> | 130 |
| | Solders | 131 |
| | Solder Classifications | 131 |
| | Review Questions | 132 |
| Chapter 8 | Brazing and Braze Welding | 135 |
| | Performance Objectives | 135 |
| | Uses of Brazing | 136 |
| | Uses of Braze Welding | 137 |
| | Filler Material | 138 |
| | Flux | 138 |
| | Preparing Surfaces | 140 |
| | <i>Cleaning Metal</i> | 140 |
| | <i>Butt and Lap Joints</i> | 141 |
| | <i>Applying Flux</i> | 142 |
| | Brazing Technique | 143 |
| | <i>Heating the Base Metal</i> | 144 |
| | <i>Bonding</i> | 146 |
| | Brazing Versus Fusion Welding | 147 |
| | Silver and Bronze Brazing | 147 |
| | Brazing Aluminum | 148 |
| | Braze Welding Technique | 148 |
| | <i>Beveling Metal Edges</i> | 149 |
| | <i>Flame Cleaning</i> | 149 |
| | <i>Preheating and Heating</i> | 151 |
| | <i>Tinning</i> | 151 |
| | <i>Cooling</i> | 153 |
| | General Comments | 155 |
| | Cast Iron | 156 |
| | <i>Braze Welding</i> | 158 |
| | <i>Brazing</i> | 159 |
| | Review Questions | 159 |

| | | |
|-------------------|---------------------------------------|------------|
| Chapter 9 | Beginning Welding | 161 |
| | Performance Objectives | 161 |
| | Fusion Welding | 162 |
| | Torch Movement | 163 |
| | Puddling Metal | 165 |
| | <i>Heating Steel</i> | 165 |
| | <i>Puddle Characteristics</i> | 166 |
| | <i>Welding Beads</i> | 167 |
| | Working with Welding and Filler Rods | 170 |
| | <i>Coat Hangers</i> | 171 |
| | <i>Adding Filler Material</i> | 172 |
| | <i>Torch Control</i> | 173 |
| | <i>Filler Rod Size</i> | 173 |
| | Joining Two Pieces of Steel | 175 |
| | <i>Tack Welding</i> | 176 |
| | <i>Prefitting Pieces</i> | 177 |
| | <i>Welding Irregular Edge Pieces</i> | 177 |
| | <i>Heat Application</i> | 178 |
| | Welding Joints | 179 |
| | <i>Outside-Corner Weld</i> | 179 |
| | <i>Flange Joint Weld</i> | 181 |
| | <i>Butt Joint Weld</i> | 182 |
| | <i>T-Joint Weld</i> | 184 |
| | Review Questions | 185 |
| Chapter 10 | Welding Thicker Metals | 187 |
| | Performance Objectives | 187 |
| | Beveling Metal Edges | 189 |
| | <i>Grinding</i> | 189 |
| | <i>Cutting</i> | 189 |
| | Welding Steel Plate | 190 |
| | <i>Grinding Plate Edges</i> | 191 |
| | <i>Tack Welding Joint Edges</i> | 191 |
| | <i>Strength Test</i> | 193 |
| | <i>Characteristics of a Good Weld</i> | 193 |
| | Multilayer Welding | 193 |
| | Review Questions | 195 |

| | | |
|-------------------|--|------------|
| Chapter 11 | Protection and Problems | 197 |
| | Performance Objectives | 197 |
| | Paint Coatings | 198 |
| | Sandblasting | 198 |
| | Common Welding Difficulties | 199 |
| | <i>Torch Popping</i> | 199 |
| | <i>Weld Bead Holes</i> | 200 |
| | <i>Warping of Metal</i> | 201 |
| | Review Questions | 201 |
| Chapter 12 | The Weldability of Certain Metals | 203 |
| | Performance Objectives | 203 |
| | Iron | 204 |
| | Steel | 204 |
| | Copper | 205 |
| | Aluminum | 206 |
| | Review Questions | 207 |
| Chapter 13 | Cutting Metal | 209 |
| | Performance Objectives | 209 |
| | Equipment | 210 |
| | <i>Cutting Attachments</i> | 210 |
| | <i>Cutting Tip Holes</i> | 211 |
| | Chemical Reaction | 211 |
| | Success Factors | 213 |
| | Setup | 214 |
| | <i>Oxygen Flow</i> | 215 |
| | <i>Acetylene Flow</i> | 216 |
| | Precutting Procedures | 217 |
| | <i>Positioning of Hoses</i> | 218 |
| | <i>Access to Safety Equipment</i> | 219 |
| | Cutting a Hole in Steel Plate | 220 |
| | Cutting a Line across Steel Plate | 222 |
| | <i>Depressing the Oxygen Lever</i> | 223 |
| | <i>Factors Influencing Speed</i> | 223 |

| | |
|--|------------|
| <i>Perfect Cut</i> | 224 |
| <i>Too Fast Cut</i> | 224 |
| <i>Too Slow Cut</i> | 225 |
| <i>Too Much Preheat Cut</i> | 225 |
| Professional Cutting Tips | 226 |
| <i>Observe the Metal</i> | 226 |
| <i>Adding Oxygen</i> | 226 |
| <i>Proper Torch Movement</i> | 227 |
| <i>Preheat Flame Height</i> | 228 |
| <i>Setting up a Guide</i> | 228 |
| Cutting Thin Metal | 229 |
| Bevel Cutting | 230 |
| Cutting Thick Steel | 230 |
| Pipe Cutting | 234 |
| <i>Pipe Marking</i> | 234 |
| <i>Torch Angle</i> | 234 |
| <i>Two-Person Operation</i> | 235 |
| <i>Beveling Pipe Edges</i> | 235 |
| Piercing a Hole through Steel Plate | 236 |
| Other Cutting Methods | 237 |
| <i>Stack Cutting</i> | 237 |
| <i>Metal Powder Cutting</i> | 238 |
| <i>Chemical Flux Cutting</i> | 238 |
| <i>Underwater Torch Cutting</i> | 238 |
| <i>Arc Cutting</i> | 239 |
| <i>Air-Carbon Arc Cutting</i> | 239 |
| <i>Plasma Arc Cutting</i> | 240 |
| <i>Gas Tungsten Arc Cutting</i> | 241 |
| <i>Laser-Beam Cutting</i> | 241 |
| <i>Heat Effects from Flame and Arc Cutting</i> | 242 |
| Review Questions | 243 |
| Chapter 14 Safety | 245 |
| Performance Objectives | 245 |
| Clothing | 246 |
| <i>Cowhide Garments</i> | 247 |
| <i>Cotton and Wool Apparel</i> | 247 |
| <i>Flameproof Clothing</i> | 248 |
| <i>Head Covering</i> | 248 |
| <i>Boots and Shoes</i> | 249 |

| | |
|-------------------------------------|------------|
| Eye Protection | 250 |
| <i>Goggles</i> | 250 |
| <i>Face Shields</i> | 250 |
| <i>Filtering Lens</i> | 251 |
| <i>Clear Glass</i> | 251 |
| Respirators | 252 |
| Gloves | 253 |
| Aprons | 255 |
| Fires and Fire Equipment | 256 |
| <i>Fuel, Oxygen, and Heat</i> | 256 |
| <i>Fire Extinguishers</i> | 258 |
| <i>Sand and Water</i> | 259 |
| Burns | 259 |
| <i>First-Degree Burns</i> | 260 |
| <i>Second-Degree Burns</i> | 260 |
| <i>Third-Degree Burns</i> | 260 |
| Handling Welding Equipment | 261 |
| <i>Handling Oxygen</i> | 262 |
| <i>Handling Acetylene</i> | 264 |
| Review of Equipment Setup | 264 |
| <i>Oxygen Connections</i> | 265 |
| <i>Acetylene Connections</i> | 266 |
| Working with Oxyacetylene Equipment | 266 |
| Welding Hazards | 268 |
| In Summary | 269 |
| Review Questions | 270 |
| Chapter 15 The Home Workshop | 271 |
| Performance Objectives | 271 |
| Outdoor Workshop Advantages | 272 |
| <i>Ventilation</i> | 272 |
| <i>Equipment Setup</i> | 272 |
| <i>Minimal Cost</i> | 272 |
| Welding Table | 273 |
| <i>Assembly</i> | 273 |
| <i>Modifications</i> | 275 |
| <i>Outdoor Workshop Sites</i> | 276 |
| <i>Carport</i> | 276 |

| | | |
|-------------------|----------------------------------|------------|
| | <i>Cement or Stone Patio</i> | 277 |
| | <i>Outbuilding</i> | 277 |
| | Indoor Workshop Needs | 278 |
| | <i>Fire Station</i> | 278 |
| | <i>Accessibility</i> | 279 |
| | <i>Lighting</i> | 279 |
| | <i>Storage Space</i> | 280 |
| | Accessories | 281 |
| | <i>Mobile Cart</i> | 282 |
| | <i>Anvil</i> | 282 |
| | Local Codes | 283 |
| | Summary of Workshop Requirements | 283 |
| | Review Questions | 284 |
| Chapter 16 | Metal Projects | 285 |
| | Performance Objectives | 285 |
| | Metal Post Pounder | 286 |
| | Hay Manger | 287 |
| | Swing Target | 289 |
| | Garden Row Marker | 291 |
| | Metal Saw Horses | 292 |
| | Metal Gate | 293 |
| | Fireplace Grate | 295 |
| | Stationary Welding Tanks Stand | 296 |
| | Bench Grinder Stand | 297 |
| | Metal Workbench | 298 |
| | Review Questions | 300 |
| | Glossary | 301 |
| | Appendix | 317 |
| | Index | 323 |

INDEX

- Acetylene, 11, 16, 19
 - blowpipe, 164
 - brass fitting, 19
 - connections, 266
 - cutting tip, 214
 - cylinders, 17, 19
 - gas, 18
 - handling, 264
 - regulator, 20
- Additional information, 8
- Advancement, 4, 5
- Agitator lever, 18
- Air-carbon arc cutting, 239
- Alloying elements of steel, 97
- Alternating current, 58
- Aluminum, 96, 206
- American Welding Society, 8
- Anvil, 282
- Aprons, 255
- Arc
 - cutting, 239
 - striking an, 60, 62
 - welder, 57, 60
 - welding, 2, 3
 - shielded metal, 56
 - welding electrodes, 317
 - welding face mask, 61
 - welding machine, 58
- Arrestors, flashback, 41
- Assemblers, 7
- Attaching regulators and hoses, 46
- Attachments, cutting, 38, 210

- Bandana, 252, 253
- Base metal, 61, 144
- Beads, 167
- Bench grinder, 150, 189
 - stand project, 297
- Bessemer process, 82
- Beveling edges, 149, 189
 - pipe edges, 235
- Bleed the line, 51
- Blow-out, 20
- Blowpipe, 33, 164
 - balanced pressure, 34, 36
 - injector, 33
 - low-pressure, 33, 36
 - medium-pressure, 33, 34
 - welding, 35
- Boilermakers, 7
- Bonding, 75, 146
- Boots and shoes, 249
- Borax, 139
- Brass, 81
- Braze welding, 136, 158
 - uses of, 137
- Brazing, 2, 136, 159
 - aluminum, 148
 - rods, 102, 103
 - techniques, 143, 155
- Brinnell method, 87
- Brittle metal, 90
- Bronze coating, 154
- Bronze rod, 147
- Burns, 259, 260
 - 1st degree, 260
 - 2nd degree, 260
 - 3rd degree, 260
- Butt joint, 141
- Butt welds, 76

- Cable, working lead, 56
- Calcium carbide, 18
- Calcium chloride, 18
- Cap, tank protection, 268
- Capillary action, 137

- Carbide, 16
- Carbide-to-water generators, 17
- Carbon, 96
- Carbon monoxide, 80
- Carport, 276
- Cast iron, 92, 156
- Chart, pressure, 38
 - cutting tips, 39
- Chemical flux cutting, 238
- Chip test, 92
- Class A fires, 256
- Class B fires, 256
- Class C fires, 257
- Class D fires, 257
- Clean welding tips, 199
- Cleaning metal, 140
- Clothing, 246
 - fireproof, 248, 249
 - and gear, 40
- Coated electrodes, 319
- Coatings, 320
- Cold chisel, 231
- Collet, motor driven, 71
- Common joints, 194
 - design, 188
- Copper, 80, 96, 205
 - tips, 111
- Cowhide, 247
- Cracking, 27
- Crayon, temperature indicating, 85
- Creep, 30
- Cutting, 189
 - angle, 228
 - attachment tip, 39
 - bevel, 230
 - gas tungsten, 241
 - metal, 209
 - metals, 11
 - speed, 225
 - straight line, 222
 - tip, 215
 - tip holes, 211
 - tips, professional, 226
 - too fast, 224
 - too slow, 225
- Cylinders, 13
 - chained, 14
 - oxygen, 14
 - sizes, 14
 - storing, 15
- Deoxidizers, 57
- Ductility, 86
- Earnings, 5, 6
- EBW. *See* Electron beam welding
- Electron beam welding (EBW), 67
- EBW, 67
- Electroslag process, 69
- Electrode holder, 57
- Electrodes, 56
 - cutting, 63
 - flux-coated, 57
 - selection, 59
- Electron beam welding, 71
- Electroslag welding (ESW), 66, 67
- Employment, 5
- Equipment setup, 272
- ESW. *See* Electroslag welding
- European countries, 67
- Explosion welding, 75
- Explosions, 268
- Eye injury, 268
- Face shields, 250, 252
- FCAW. *See* Flux-cored-arc welding
- Filler material, 139, 172
- Fire, 268
 - extinguishers, 258
 - station, 278
- Fireplace grate project, 295
- Flame
 - acetylene, 49
 - carburizing, 49, 52
 - cleaning, 151
 - control, 207
 - cutting, procedures, 232
 - neutral, 49, 50, 52
 - oxidizing, 50, 52
 - pure acetylene, 51
 - straightening, 75
- Flange joint, 181
- Flash welding, 67, 68, 70, 162
 - inertia, 72, 73

- Flux, 56, 139
 - combinations, 120
 - coated wire, 65
- Flux-cored-arc welding, 158
- Fluxes, 104, 105, 118, 119
- Flywheel, 72
- Free carbon, 94
- Freezing, 60, 62
- Friction welding, FRW, 71
- Fusion, 10
- Fusion welding, 147
- FW. *See* Flash welding

- Garden row marker project, 291
- Gas-metal-arc welding (GMAW), 64,
65, 158
- Gas-tungsten-arc welding (GTAW), 158
- Gases, poisonous, 268
- Gauges, 25
- Gear, protection, 59
- Glossary, 301
- Gloves, 253, 254
- GMAW. *See* Gas-metal-arc welding
- Goggle parts, 251
- Goggles, 3
- Good weld, 193
- Graphite, 94
- Grinder stand project, 298
- Grinding, 189
- Grinding wheel, 95, 141
- GTAW. *See* Gas-tungsten-arc welding
- Gun, 240

- Hand cutting tools, 212
- Hand truck, 46
- Handle, blowpipe, 47
- Handling equipment, 261
- Hardness, 86, 87
- Hay manager project, 287
- Head coverings, 248
- Heat effects, 242
- Heat sources, 19
- Heating, 151
- Helmet, new, 59
- History of gas welding, 10
- Holds, weld bead, 200
- Home workshop, 271
 - cost, 272

- Hoods, 3
- Hoses, 30, 32
 - double, 32
 - older, 32
 - positioning, 218
 - Siamese, 32
 - storing, 33

- ICC regulation, 18
- Identification, metals, by chips, 93
- Impact strength, 88
- Iron, 81, 94, 204

- Job outlook, 5
- Joints comparison, 157
 - common brazing, 142
- Jump, 29

- Kinetic energy, 72
- Knobs, control, 34

- Lap joint, 141
- Laser-beam
 - cutting (LBC), 241
 - welding (LBW), 74, 75
- LBC. *See* Laser-beam cutting
- Leaks, 27
- Left-handed threads, 46
 - fittings, 20
- Lighter, new type, 42
 - standard striker, 42
 - torch, 40, 41
- Lighting, 279
 - grinding wheel, 280
- Liquid-air process, 12
- Local codes, 283

- Machining cuts, 243
- Magnesium, 83, 98
- Malleability, 87, 88
- Malleable cast iron, 94
- Melting point, 84, 85
- Metal
 - cutting, 13, 63, 209
 - edges, 149
 - gate, 293

- Metal (*Cont.*)
 - identification by appearance, 92
 - identification, 89
 - joining, 10
 - parent, 58
 - powder cutting, 238
 - saw horses project, 292
 - scrap, 99
 - sources, 98
 - warping, 201
 - workbench project, 299
- Metals
 - chemical properties, 84
 - ferromagnetic, 83
 - history of, 80
 - physical properties, 82
 - properties of, 86
- Metal insert gas (MIG), 2, 64, 158
 - welding equipment, 65
- Mild steel,
- Mobile cart, 282
- Multilayer, welding, 193, 194, 200

- Nature of the work, 1
- Neutral flame, 145, 218
 - adjusting, 219, 220

- Oil, avoid on regulators, 26
- Opening valves, 47
- Orifices, 39
- Other metals, 92
- Outbuilding, 277
- Outfit, welding, 66
- Oxidize, 11
- Oxyacetylene
 - cutting and welding, 65
 - welding, 9, 10, 11
- Oxy-gas cutters, 3
- Oxygen, 12, 13, 15
 - vs. air, 263
 - connections, 265
 - control knob, 216, 217
 - cutting lever, 38, 226
 - flow, 215
 - handling, 262
 - lever, 223
 - not flammable, 16
 - regulator, attaching, 28
 - valve, cracking, 47
- Paint coatings, 198
- Perfect cut, 224
- Pipe
 - cutting, 234
 - marking, 234
- Plasma, 3
- Plasma arc cutting, 240
- Plastics welding, 76
- Plate edges, 191
- Plow share, metal added, 104
- Poisonous fumes, 3
- Portable disc sander, 190
- Post pounder project, 286
- Preheat flame height, 225, 228
- Preheating, 151
- Pressure
 - setting, 47
 - working, 50
- Puddling, 170

- Qualifications, 4

- Regulator, acetylene, 24, 26, 163
 - diaphragm, 29
 - differences, 26
 - freezing, 28
 - oxygen, 25
 - snugged up, 48
- Regulators, 263
 - check list, 31
 - single stage, 24
 - two-stage, 24, 25
- Related occupations, 7
- Respirators, 252
- Rods, welding, 102, 171
 - sizes, 175

- Safety, 267
- Safety practices, 14
- Safety shoes, 3
- Safety plug, 20, 264, 265
 - acetylene cylinder, 21

- Sand and water, 259
- Sandblasting, 198
- Scared off, 75
- Scrap metal, 99
- Scratch method, 61
- Sears cutting tips, 214
- Setting pressure for oxygen, 217
- Setting up a guide, 228
- Sheet metal, cutting, torch, 229
- Shield-metal-arc welding (SMAW), 158
- Shielding, special, 58
- Skilled workers, 3
- Slag and flashback, 39
 - molten, 69
- SMAW. *See* Shielded-metal-arc welding
- Soap bubble test, 29
- Soapstone pencil, 222
- Solder
 - 20A, 115
 - 40- & 50 A, 115
 - 40A, 132
 - chunky, 125
 - fine, 117
 - general purpose, 116
 - leadless, 117
 - silver, 117
- Soldering, 2, 107, 108
 - copper plumbing pipe, 128
 - eye protection, 130
 - safety considerations, 129
 - technique, 123
 - ventilation, 130
- Soldering iron, 109-11
 - joints, 122
 - with flame, 127
- Soldering iron holder, 114
 - tip cleaning, 124
- Solders, classifications, 131
 - tin-lead, 115
 - types, 131
- Spark-lighter, 43
- Spark test, 90
- Sparks, 95
- Special wrench, 49
- Speed factors, 223
- Stack cutting, 237
- Steel, 95, 204
- Steel making process, 81
- Stone patio, 277
- Storage space, 280
- Storage stack, 281
- Strength test, 193
- Stress, elasticity, creep, 89
- Striker, 51
- Surface film, 75
 - tinning, 125
- Surfaces, preparing, 140
- Surfacing rods, 103
- Swing target project, 289
- T-joint weld, 184
- Tack welding, 153, 176
 - ends of a beveled edge joint, 192
 - steel scrap, 275
- Tank filler material, 19
 - before attaching, 48
 - valve, 27
- Tapping method, 62
- Tasks, concluding, 51
- Tensile strength, 86
- Tests, chip and spark, 90
- Thermit welding, 66, 67
 - cutting, 230
 - joining, 155
- Thicker metals, welding, 187
- Thin metal, cutting, 229
- TIG. *See* Tungsten inert gas
- Tinning, 123
- Tinted goggles, 250, 251
- Tip
 - cleaning, 40
 - clogged, 40
 - cutting, 37, 38
 - sizes, 37, 144
 - welding, 37
- Tools, common solder, 109, 121
- Torch
 - acetylene, 113
 - brazing, 112
 - hand cutting, 213
 - lighting, 48
 - propane, 112
 - Spitfire, 138



- Torch (*Cont.*)
 angle, 234
 lighter, 40
 movement, 163, 227
 popping, 199
 Toughness, 87
 Trade secret, 113
 Training, 4
 Truck, 20
 Tungsten inert gas (TIG),
 2, 63, 64
 Two-hands used for cutting, 222
- Ultrasonic welding (USW), 70, 72
 Underwater torch cutting, 238
 Unions, 7
 USW. *See* Ultrasonic welding
- V-grooved butt or fillet welds, 76
 Valve, acetylene flow, 216
 check, 41
 hose check, 42
 Ventilation, 272
 Vice grips, 152
- Water filler, 18
 Welders, 1
- Welding
 arc, 56
 gloves, 248
 hazards, 268-269
 irregular edges, 178
 processes, additional, 66
 rod as guide, 233
 rods, 103
 steel plate, 190
 table, 273
 dimensions, 274
 materials for, 273
 tanks stand project, 296
 tacking edges, 191
 tips, Sears, 192
 straightening, 41
 White-hot state, 221
 Wind chamber, 83
 Wiping threads, 263
 Wire brush, 148, 165
 Wire-feed welding, 65
 Work week, 4
 Working conditions, 3
 Workshop requirements, 283, 284
 Workshop, indoor, 278
 Wrought iron, 92
- Zinc, 81

