


We Support AWS



# WELDING

Skills, Processes and Practices  
for Entry-Level Welders



## BOOK 1

Occupational Orientation • Safety and Health of Welders  
• Drawing and Welding Symbol Interpretation  
Thermal Cutting • Weld Inspection Testing and Codes

LARRY JEFFUS • LAWRENCE BOWER

SC

671.52  
J45  
2010  
Bk. 1



# Contents

|  |           |
|--|-----------|
| Preface . . . . .  | xii       |
| AWS Acknowledgment . . . . .   | xv        |
| Acknowledgments . . . . .  | xvi       |
| About the Authors . . . . .  | xvii      |
| <b>Chapter 1 Introduction to Welding . . . . .</b>                                     | <b>1</b>  |
| <i>Introduction</i> . . . . .  | 2         |
| <i>Welding Defined</i> . . . . .   | 4         |
| <i>Uses of Welding</i> . . . . .   | 4         |
| <i>Welding Processes</i> . . . . .   | 7         |
| <i>Occupational Opportunities in Welding</i> . . . . .                                 | 11        |
| <i>Training for Welding Occupations</i> . . . . .                                      | 14        |
| <i>Qualified and Certified Welders</i> . . . . .                                       | 15        |
| <i>AWS Entry-Level Welder Qualification and Welder<br/>    Certification</i> . . . . . | 17        |
| <i>Experiments and Practices</i> . . . . .   | 18        |
| Layout . . . . .   | 19        |
| Written Procedures . . . . .   | 19        |
| Written Records . . . . .  | 19        |
| Verbal Instructions . . . . .  | 20        |
| <i>Welding Video Series</i> . . . . .  | 21        |
| <i>Metric Units</i> . . . . .  | 22        |
| <b>Chapter 2 Safety in Welding . . . . .</b>   | <b>27</b> |
| <i>Introduction</i> . . . . .  | 28        |
| <i>Burn Classification</i> . . . . .   | 29        |
| First-Degree Burns . . . . .   | 29        |
| Second-Degree Burns . . . . .  | 29        |
| Third-Degree Burns. . . . .  | 30        |
| Burns Caused by Light. . . . .   | 30        |
| <i>Face, Eye, and Ear Protection</i> . . . . .   | 32        |
| Face and Eye Protection. . . . .   | 32        |
| Ear Protection. . . . .  | 35        |
| <i>Respiratory Protection</i> . . . . .  | 35        |
| Training. . . . .  | 37        |
| Equipment . . . . .  | 37        |
| Fume Sources. . . . .  | 39        |
| Vapor Sources . . . . .  | 40        |

|   |    |
|---|----|
| <i>Ventilation</i> . . . . .                              | 40 |
| <i>Confined Spaces</i> . . . . .                          | 41 |
| <i>Material Safety Data Sheets (MSDSs)</i> . . . . .      | 42 |
| <i>Waste Material Disposal</i> . . . . .                  | 42 |
| <i>General Work Clothing</i> . . . . .                    | 42 |
| <i>Special Protective Clothing</i> . . . . .              | 43 |
| Hand Protection . . . . .                                 | 43 |
| Body Protection . . . . .                                 | 44 |
| Waist and Lap Protection . . . . .                        | 45 |
| Arm Protection . . . . .                                  | 45 |
| Leg and Foot Protection . . . . .                         | 45 |
| <i>Handling and Storing Cylinders</i> . . . . .           | 46 |
| Securing Gas Cylinders . . . . .                          | 46 |
| Storage Areas . . . . .                                   | 46 |
| Cylinders with Valve Protection Caps . . . . .            | 47 |
| General Precautions . . . . .                             | 47 |
| <i>Fire Protection</i> . . . . .                          | 48 |
| Fire Watch . . . . .                                      | 49 |
| Fire Extinguishers . . . . .                              | 49 |
| <i>Equipment Maintenance</i> . . . . .                    | 52 |
| Hoses . . . . .   | 52 |
| <i>Work Area</i> . . . . .                                | 52 |
| <i>Hand Tools</i> . . . . .                               | 53 |
| <i>Electrical Safety</i> . . . . .                        | 54 |
| <i>Electrical Safety Systems</i> . . . . .                | 56 |
| <i>Voltage Warnings</i> . . . . .                         | 56 |
| <i>Extension Cords</i> . . . . .                          | 56 |
| <i>Safety Rules for Portable Electric Tools</i> . . . . . | 59 |
| Grinders . . . . .  | 60 |
| Drills . . . . .  | 61 |
| <i>Metal-Cutting Machines</i> . . . . .                   | 61 |
| Shears and Punches . . . . .                              | 62 |
| Cut-off Machines . . . . .                                | 63 |
| Band Saws . . . . .                                       | 63 |
| <i>Material Handling</i> . . . . .                        | 63 |
| Lifting . . . . .   | 63 |
| Hoists or Cranes . . . . .                                | 63 |
| <i>Ladder Safety</i> . . . . .                            | 64 |
| Types of Ladders . . . . .                                | 64 |
| Ladder Inspection . . . . .                               | 65 |
| Rules for Ladder Use . . . . .                            | 65 |

### **Chapter 3 Drawing and Welding Symbol**

|                                    |           |
|------------------------------------|-----------|
| <b>Interpretation</b> . . . . .    | <b>69</b> |
| <i>Introduction</i> . . . . .      | 70        |
| <i>Weld Joint Design</i> . . . . . | 70        |



|  |           |
|--|-----------|
| Welding Process . . . . .                | 71        |
| Base Metal . . . . .                     | 72        |
| Plate Welding Positions . . . . .        | 72        |
| Pipe Welding Positions . . . . .         | 73        |
| Metal Thickness . . . . .                | 74        |
| Code or Standards Requirements . . . . . | 76        |
| Welder Skill . . . . .                   | 76        |
| Acceptable Cost . . . . .                | 76        |
| <i>Mechanical Drawings</i> . . . . .     | 77        |
| Lines . . . . .                          | 79        |
| Types of Drawings . . . . .              | 80        |
| Projection Drawings . . . . .            | 80        |
| Special Views . . . . .                  | 82        |
| Dimensioning . . . . .                   | 84        |
| <i>Welding Symbols</i> . . . . .         | 84        |
| Indicating Types of Welds . . . . .      | 85        |
| Weld Location . . . . .                  | 85        |
| Significance of Arrow Location . . . . . | 86        |
| <i>Fillet Welds</i> . . . . .            | 88        |
| Plug Welds . . . . .                     | 88        |
| Spot Welds . . . . .                     | 89        |
| Seam Welds . . . . .                     | 90        |
| Groove Welds . . . . .                   | 91        |
| Backing . . . . .                        | 94        |
| Flange Welds . . . . .                   | 95        |
| Nondestructive Testing Symbols . . . . . | 95        |
| <b>Chapter 4 Fabrication . . . . .</b>   | <b>99</b> |
| <i>Introduction</i> . . . . .            | 100       |
| <i>Fabrication</i> . . . . .             | 100       |
| Safety . . . . .                         | 102       |
| Shop Math . . . . .                      | 102       |
| <i>Layout</i> . . . . .                  | 108       |
| Nesting . . . . .                        | 113       |
| Kerf Space . . . . .                     | 116       |
| <i>Material Shapes</i> . . . . .         | 119       |
| <i>Assembly</i> . . . . .                | 120       |
| <i>Assembly Tools</i> . . . . .          | 122       |
| Clamps . . . . .                         | 122       |
| Fixtures . . . . .                       | 124       |
| <i>Fitting</i> . . . . .                 | 125       |
| <i>Tack Welding</i> . . . . .            | 126       |
| <i>Welding</i> . . . . .                 | 127       |
| <i>Finishing</i> . . . . .               | 128       |

|                  |  |            |
|------------------|--|------------|
| <b>Chapter 5</b> | <b>Welding Codes, Standards, and Cost . . .</b>                            | <b>131</b> |
|                  | <i>Introduction . . . . .</i>  | 132        |
|                  | <i>Codes, Standards, Procedures, and Specifications.</i>                   | 132        |
|                  | <i>Welding Procedure Qualification . . . . .</i>                           | 134        |
|                  | Welding Procedure Specification (WPS) . . . . .                            | 134        |
|                  | Qualifying the Welding Procedure<br>Specification . . . . .                | 135        |
|                  | Qualifying and Certifying . . . . .  | 135        |
|                  | <i>General Information . . . . .</i>                                       | 136        |
|                  | <i>Welding Costs . . . . .</i>   | 147        |
|                  | Cost Estimation. . . . .   | 148        |
|                  | Weld Metal Cost . . . . .  | 153        |
|                  | Factors for Cost Formulas . . . . .  | 165        |
|                  | Comparing Weld Metal Costs . . . . .                                       | 170        |
|                  | Other Useful Formulas. . . . .   | 174        |
| <br>             |  |            |
| <b>Chapter 6</b> | <b>Flame Cutting . . . . .</b>   | <b>177</b> |
|                  | <i>Introduction . . . . .</i>  | 178        |
|                  | <i>Metals Cut Using the Oxyfuel Process . . . . .</i>                      | 179        |
|                  | <i>Eye Protection for Flame Cutting . . . . .</i>                          | 180        |
|                  | <i>Cutting Torches . . . . .</i>   | 180        |
|                  | <i>Cutting Tips . . . . .</i>  | 182        |
|                  | <i>Oxyfuel Cutting, Setup, and Operation . . . . .</i>                     | 187        |
|                  | <i>Hand Cutting . . . . .</i>  | 192        |
|                  | <i>Layout . . . . .</i>  | 195        |
|                  | <i>Selecting the Correct Tip and Setting<br/>    the Pressure. . . . .</i> | 196        |
|                  | <i>The Chemistry of a Cut. . . . .</i>                                     | 197        |
|                  | <i>The Physics of a Cut. . . . .</i>                                       | 200        |
|                  | Preheat . . . . .  | 200        |
|                  | Speed . . . . .  | 200        |
|                  | Pressure. . . . .  | 200        |
|                  | Slag. . . . .  | 203        |
|                  | <i>Plate Cutting. . . . .</i>  | 203        |
|                  | <i>Cutting Table . . . . .</i>   | 204        |
|                  | <i>Torch Guides . . . . .</i>  | 204        |
|                  | <i>Distortion. . . . .</i>   | 207        |
|                  | <i>Cutting Applications. . . . .</i>                                       | 209        |
|                  | <i>Washing or Scarfing. . . . .</i>  | 212        |
|                  | <i>Pipe Cutting . . . . .</i>  | 213        |
| <br>             |  |            |
| <b>Chapter 7</b> | <b>Plasma Arc Cutting. . . . .</b>   | <b>217</b> |
|                  | <i>Introduction . . . . .</i>  | 218        |
|                  | <i>Plasma . . . . .</i>  | 218        |
|                  | <i>Arc Plasma. . . . .</i>   | 219        |



|                                       |     |
|---------------------------------------|-----|
| <i>Plasma Torch</i> . . . . .         | 219 |
| Torch Body . . . . .                  | 220 |
| Torch Head . . . . .                  | 220 |
| Power Switch . . . . .                | 221 |
| Common Torch Parts . . . . .          | 221 |
| Electrode Tip . . . . .               | 222 |
| Nozzle Insulator . . . . .            | 222 |
| Nozzle Tip . . . . .                  | 222 |
| Nozzle . . . . .                      | 223 |
| Water Shroud . . . . .                | 223 |
| <i>Power and Gas Cables</i> . . . . . | 223 |
| Power Cable . . . . .                 | 224 |
| Gas Hoses . . . . .                   | 224 |
| Control Wire . . . . .                | 225 |
| Water Tubing . . . . .                | 225 |
| <i>Power Requirements</i> . . . . .   | 225 |
| Voltage . . . . .                     | 225 |
| Amperage . . . . .                    | 226 |
| Wattage . . . . .                     | 226 |
| <i>Heat Input</i> . . . . .           | 227 |
| <i>Distortion</i> . . . . .           | 227 |
| <i>Applications</i> . . . . .         | 228 |
| Cutting Speed . . . . .               | 228 |
| Metals . . . . .                      | 229 |
| Standoff Distance . . . . .           | 229 |
| Starting Methods . . . . .            | 230 |
| Kerf . . . . .                        | 231 |
| <i>Gases</i> . . . . .                | 234 |
| Stack Cutting . . . . .               | 236 |
| Dross . . . . .                       | 236 |
| <i>Machine Cutting</i> . . . . .      | 236 |
| Water Tables . . . . .                | 237 |
| <i>Manual Cutting</i> . . . . .       | 238 |
| Setup . . . . .                       | 238 |
| <i>Plasma Arc Gouging</i> . . . . .   | 238 |
| <i>Safety</i> . . . . .               | 240 |

## **Chapter 8 Related Cutting Processes . . . . . 249**

|   |     |
|---|-----|
| <i>Introduction</i> . . . . .           | 250 |
| <i>Lasers</i> . . . . .                 | 250 |
| Laser Equipment . . . . .               | 252 |
| Applications . . . . .                  | 252 |
| Laser Types . . . . .                   | 253 |
| Laser Beam Cutting . . . . .            | 254 |
| Laser Beam Drilling . . . . .           | 256 |
| <i>Air Carbon Arc Cutting</i> . . . . . | 257 |
| Manual Torch Design . . . . .           | 258 |

|                                       |     |
|---------------------------------------|-----|
| Electrodes . . . . .                  | 259 |
| Power Sources . . . . .               | 260 |
| Air Supply . . . . .                  | 261 |
| Application. . . . .                  | 261 |
| Gouging. . . . .                      | 262 |
| Washing. . . . .                      | 262 |
| Safety . . . . .                      | 263 |
| <i>Oxygen Lance Cutting</i> . . . . . | 268 |
| Application. . . . .                  | 270 |
| Safety . . . . .                      | 270 |
| <i>Water Jet Cutting.</i> . . . .     | 270 |
| Applications . . . . .                | 271 |

## **Chapter 9 Testing and Inspection of Welds . . . . . 275**

|   |     |
|---|-----|
| <i>Introduction</i> . . . . .                 | 276 |
| <i>Quality Control (QC)</i> . . . . .         | 276 |
| <i>Discontinuities and Defects</i> . . . . .  | 276 |
| Porosity . . . . .                            | 277 |
| Inclusions . . . . .                          | 279 |
| Inadequate Joint Penetration . . . . .        | 281 |
| Incomplete Fusion . . . . .                   | 281 |
| Arc Strikes . . . . .                         | 283 |
| Overlap . . . . .                             | 283 |
| Undercut . . . . .                            | 283 |
| Crater Cracks . . . . .                       | 284 |
| Underfill . . . . .                           | 285 |
| Plate-Generated Problems . . . . .            | 286 |
| <i>Destructive Testing (DT)</i> . . . . .     | 287 |
| Tensile Testing . . . . .                     | 287 |
| Fatigue Testing . . . . .                     | 289 |
| Shearing Strength of Welds. . . . .           | 290 |
| Welded Butt Joints . . . . .                  | 292 |
| Fillet Weld Break Test . . . . .              | 296 |
| Testing by Etching. . . . .                   | 297 |
| Impact Testing . . . . .                      | 298 |
| <i>Nondestructive Testing (NDT)</i> . . . . . | 299 |
| Visual Inspection (VT) . . . . .              | 299 |
| Penetrant Inspection (PT). . . . .            | 299 |
| Magnetic Particle Inspection (MT). . . . .    | 300 |
| Radiographic Inspection (RT) . . . . .        | 301 |
| Ultrasonic Inspection (UT) . . . . .          | 302 |
| Leak Checking . . . . .                       | 308 |
| Eddy Current Inspection (ET) . . . . .        | 308 |
| Hardness Testing . . . . .                    | 309 |

**Chapter 10 Welder Certification . . . . . 313**

*Introduction . . . . . 314*

*Performance Tests . . . . . 314*

    Layout . . . . . 315

    Safety . . . . . 315

    Housekeeping . . . . . 315

    Cutting Out Parts . . . . . 316

    Fitup and Assembly of the Parts . . . . . 316

    Workmanship Standards for Welding . . . . . 319

    Weld Inspection . . . . . 320

*Welding Skill Development . . . . . 322*

**Appendix . . . . . 329**

**Glossary . . . . . 331**

**Index . . . . . 341**



# Index

*Italic* page references indicate material in figures or tables.

- AAR. *See* Association of American Railroads
- AASHTO. *See* American Association of State Highway and Transportation Officials
- abrasive cut-off wheels, 63
- abrasive grinding disk, 125
- acetone, 47-48
- acetylene
- flame temperature, 179
  - preheat holes, 186
  - welding processes employing, 8
- acetylene cylinders
- general precautions, 47-48, 48
  - storage, 47
- addition, 104
- adjustable wrenches, 53, 53
- Aerospace Industries Association of America (AIA), 133
- AIA. *See* Aerospace Industries Association of America
- air carbon arc cutting (CAC-A)
- air supply, 261
  - application, 261-262
  - back-gouging, 261, 266-267
  - edge cut, 265-266
  - electrodes, 259-260, 260
  - gouging, 259, 262, 262, 265, 266
  - origin of, 257
  - overview of, 257
  - power sources, 260
  - recommended procedures for various metals, 258
  - safety, 263-264
  - straight cut, 264
  - washing, 262, 263
  - weld removal, 267, 267-268
- air carbon arc torches
- gouging torch, 257
  - manual, 258-259
- airline respirators, 37
- air-purifying respirators, 37
- AISC. *See* American Institute of Steel Construction
- alphabet of lines, 79, 79, 80
- alternate bend test, 296
- American Association of State Highway and Transportation Officials (AASHTO), 133
- American Bureau of Ships, 76
- American Institute of Steel Construction (AISC), 133
- American National Standards Institute (ANSI), 133
- American Petroleum Institute (API), 133, 134
- American Railway Engineering and Maintenance of Way Association (AREMA), 134
- American Society of Mechanical Engineers (ASME), 76, 134
- American Water Works Association (AWWA), 134
- American Welding Society (AWS)
- codes and, 76
  - contact information, 134
  - welder certification, 314
  - welding defined by, 4
- ammonium persulfate, 297
- amortization, 174
- amps, 56
- angle iron, 120, 121
- angles, dimensioning, 120, 121
- ANSI. *See* American National Standards Institute
- A-number, 144, 145
- API. *See* American Petroleum Institute
- API Standard 1104, 133
- aprons, 44, 45
- arc cutting process, 219
- See also* plasma arc cutting
- arc plasma, 219
- arc strikes, 283, 283
- AREMA. *See* American Railway Engineering and Maintenance of Way Association
- argon
- as an assist gas, 255
  - plasma arc cutting, 235
  - plasma arc welding, 218
  - safety, 40, 41
- ASME. *See* American Society of Mechanical Engineers
- ASME Section IX, 76, 133
- asphyxiation, 41
- assembly, 120-122
- assembly drawings, 78
- assembly tools, 122-124
- assist gasses, 255, 255
- Association of American Railroads (AAR), 133
- atmosphere-supplying respirators, 37
- automated operation, 11
- automatic operation, 11
- automatic welding, operating factor, 164
- AWS. *See* American Welding Society
- AWS A3.0 Standard Welding Terms and Definitions, 8
- AWS D1.1, 76, 133, 136, 139
- AWS entry-level welder qualification and certification program, 17-18
- AWS Level I, 17
- AWS Level II, 17
- AWS Level III, 17
- AWS SENSE, 17, 319-320, 322
- AWWA. *See* American Water Works Association
- back-gouging
- air carbon arc, 261, 266-267
  - described, 75, 75-76
- backing, symbols for, 94, 94
- band saws, 63
- bar clamps, 122, 123
- bar codes, 252
- bar stock, shapes, 111
- base metal, P-numbers, 143, 325
- bending force, 70
- bevel cuts, 195
- beveling
- OFC process, 208-209
  - PAC process, 244-245, 245
- bib aprons, 44, 45
- bill of materials, 77, 79
- blowback, 211
- box end wrench, 53
- Brinell hardness tester, 309, 309



- burns
  - caused by light, 30-32
  - first-degree, 29, 29
  - second-degree, 29-30, 30
  - third-degree, 30, 31
- butt joints, 71
  - destructive testing, 292-296
  - weight per foot, 171-172
- cables, safety, 315
- CAC-A. *See* air carbon arc cutting
- cadmium, 39
- cam-lock clamps, 123, 123
- capacitors, 44
- carbon dioxide, 40, 41
- carbon dioxide extinguishers, 51
- carbon electrodes, 259-260, 260
- carburizing flame, 191
- casting, direct, 2
- castle nozzle tip, 230
- cavalier drawings, 80, 82
- C-clamps, 122, 122, 123, 318
- center punch, 108-109, 109
- certification, 15-18
- certified welders, 314
- chalk line, 108, 108, 109, 195
- chalk line reel, 109
- Charpy test, 298-299
- chipping goggles, 33
- chisels, 53, 54
- chlorinated hydrocarbons, 40
- Chrome 6, 39-40
- chromium hexavalent (CrVI) compounds, 39-40
- circle template, 113
- circumferential magnetization, 300, 301
- clamps, 122-123, 123
- cleats, 125, 125, 318
- clothing, protective, 42-45
- clustered porosity, 278, 279
- coalescence, 4
- coated electrodes
  - deposition efficiency, 156
  - operating factor, 164
- codes
  - agencies and organizations issuing, 133-134, 277
  - applications to specific needs, 133
  - defined, 132
  - differences among, 136, 139
  - most commonly used, 133
- cold lap, 282
- color-contrast penetrants, 299
- combination cutting torch, 180-181, 181
- combination square, 112
- combination symbols, 95, 97
- compass, 113
- compression force, 70
- concrete, cutting, 270
- confined spaces, 40, 41
- contour marker, 118, 119
- conversion charts, 106, 107, 108
- copper/tungsten tips, 222
- coupling distance, 193, 193
- cranes, 63, 64
- crater cracks, 284, 284-285, 285
- cups, for PAC torches, 222, 223
- cut-away view, 82
- cut-off machines, 63
- cutting flame, 191, 198
- cutting gas assist, 255, 255
- cutting head, 181
- cutting lever, 182, 183
- cutting profiles and standards, 317
- cutting tables, 204
- cutting tips
  - cleaning, 189, 190
  - freeing when stuck, 187
  - gaskets, 187
  - gas pressures, 184-185
  - high-speed, 183, 184
  - identification, 184
  - leaks, 187, 188
  - materials made from, 182
  - preheat holes, 185-187, 186
  - selection, 196
  - shapes, 185, 186
  - sizing, 183-184, 184
  - special types, 186
  - tip size and cutting pressure, 185, 197
  - See also* nozzle tips
- cutting torches
  - attachments, 181
  - combination type, 180-181, 181
  - equal-pressure torch, 181-182
  - flame adjustments, 191
  - guides, 204-205, 205
  - hand cutting, 192-195
  - injector torch, 182, 182
  - lighting, 190-191
  - machine cutting torch, 182, 183
  - mixing chamber, 181-182, 182
  - oxyacetylene hand torch, 180, 180
  - setup, 188-189
  - See also* air carbon arc torches; plasma arc torches
- cylinders
  - general precautions, 47-48
  - securing, 46
  - storage areas, 46, 46-47
  - with valve protection caps, 47
- cylindrical porosity, 278
- DCEP electrodes, 260
- decimals
  - converting fractions to, 105
  - converting to fractions, 105-106
- defects, 276-277
- delamination, 286, 286
- demand respirators, 37
- density, of metals, 153
- Department of Defense, 134
- deposited weld metal
  - cost per foot, 169-170, 171
  - cost per pound, 166-169, 174
  - estimating weight of, 167
- deposition efficiency
  - coated electrodes, 156
  - described, 154-155, 155
  - flux cored wires, 156, 160-163
  - solid wires, 161-162
  - of solid wires for GMAW, 162, 163, 163
  - of solid wires for SAW, 162, 162-164
  - stub loss and, 163
- deposition rates
  - calculating, 153
  - operating factor and, 164-165, 165
  - overview of, 155-156
  - tables, 157-159
- destructive testing (DT)
  - alternate bend test, 296
  - butt joints, 292-296
  - etching, 297-298
  - fatigue tests, 289-290, 290
  - fillet weld break test, 296-297, 297
  - free bend test, 295, 295-296, 296
  - guided bend test, 292-295, 293, 294, 295
  - impact test, 298, 298-299
  - nick-break test, 292, 292
  - shearing strength, 290, 291
  - tensile tests, 287-288, 288, 289
  - uses, 287
- detail view, 78, 82
- dimensions, 84, 84
- direct casting, 2
- discontinuities
  - arc strikes, 283, 283
  - crater cracks, 284, 284-285, 285
  - defined, 276
  - delamination, 286, 286
  - inadequate joint penetration, 281, 281
  - inclusions, 279-280, 280
  - incomplete fusion, 281-283, 282
  - kinds of, 277
  - lamellar tears, 286, 287
  - lamination, 286, 286



- overlap, 283, 283
- porosity, 277-278, 279
- tolerance and, 277
- undercut, 283-284, 284
- underfill, 285, 285
- distortion
  - controlling, 207, 208
  - defined, 207
  - in PAC, 227, 227-228, 228
- dogs, 125, 125, 318
- double-bevel edge, 71
- double bevel joint, 75
- double-insulated tools, 56
- double-J edge, 71
- double J-groove joint, 75
- double-U edge, 71
- double U-groove joint, 75
- double-V edge, 71
- double V-groove joint, 75
- drag, 195, 195
- drag lines, 200
- drills, 61
- dross, 236
- dry chemical extinguishers, 51
- E. O. Paton Electric Welding Institute, 7
- earmuffs, 35, 36
- earplugs, 35, 36
- earthquakes, 270
- eddy current inspection (ET), 308
- edge joint, 71
- edge preparation, 71, 71
- E7018 electrode, 278
- efficiency minus stub loss formula, 163
- Egyptians, 2
- electrical grounds, 54, 57
- electrical resistance, 54
- electrical safety
  - double-insulated tools, 56
  - electric shock, 54, 56
  - extension cords, 56-59
  - external grounding, 56, 57
  - voltage warnings, 56
- electric shock, 54, 56
- electrode caddy, 52
- electrodes
  - air carbon arc, 259-260, 260
  - coated, 156
  - deposition efficiency (*see* deposition efficiency)
  - deposition rates (*see* deposition rates)
  - filler metal specification numbers, 144, 326
  - F-number, 142, 144, 326
- electrode setback, 222, 230
- electrode tip, for PAC torches, 222
- electron beam welding, 91
- elongation, 288
- emphysema, 39
- entry-level welder, 314
- equal-pressure torch, 181-182
- equipment maintenance, 52
- etching, 297-298
- exhaust pickups, 41, 41
- exothermic gases, 255
- expanded metal, 230
- expanded sheet, 111
- exploded drawings, 78, 121
- extension cords, 56-59
- external grounding, 56, 57
- eye protection
  - for OFC, 180, 180
  - overview of, 32-34
  - plasma arc cutting, 241, 241
- eyes, damage from ultraviolet light, 34, 34
- fabrication
  - importance of, 100
  - safety, 102
  - shop math, 102-108
  - in space, 100, 101, 102
- face bend, 292, 293
- face protection, 32-34
- fatigue testing, 289-290, 290
- FCAW. *See* flux cored arc welding
- feet, 103
- ferrous metals, A-numbers, 145
- files, 54, 54
- filler materials
  - deposition efficiency, 154-155, 155
  - deposition rates, 157-159
  - function of, 4
  - types, 4
- filler metal
  - costs, 148
  - determination of weight, 153
  - specification numbers, 144, 326
- fillet welds
  - break test, 296-297, 297
  - cross-sectional area, 152
  - dimensioning, 88, 88
  - positions of test plates, 147
  - weight per foot, 169, 171-172
  - welding positions, 72, 73
  - weld volume, 152
- filter lenses, 241, 241
- finishing, 128-129
- finishing cost, 148
- fire extinguishers
  - locating, 50, 50, 51
  - types, 49-50
  - using, 51, 51
- fire protection
  - fire extinguishers, 49-51
  - fire watch, 49
  - hot work permits, 48, 49
- fire watch, 49
- first-degree burns, 29, 29
- fitting, 125
- fixed costs, 148
- fixtures, 124
- flange welds, 94, 94-95
- flare groove welds, 92, 93
- flashburns, 32
- flash glasses, 32
- flat plate weld, 72, 73
- flaws, 276
  - See also* discontinuities
- flow rates, of shielding gases, 153-154, 154
- flow welding, 3
- fluorescent penetrants, 299
- flux cored arc welding (FCAW)
  - operating factor, 164
  - overview of, 9-10
  - popularity of, 10
- flux cored wires, deposition efficiency, 156, 160-163
- flux-to-wire ratio, 154
- F-numbers, 142, 144, 326
- foam extinguishers, 51
- forced ventilation, 40-41, 41
- forge welding, 3
- fractions
  - adding and subtracting, 104
  - converting decimals to, 105-106
  - converting to decimals, 105
  - reducing, 104
- free bend test, 295, 295-296, 296
- full face shields, 32, 33
- full leather jackets, 44, 44
- full leather sleeves, 45, 45
- fume sources, 39-40
- fusion welding, 3
- gases
  - assist, 255, 255
  - plasma arc cutting, 234-235
  - See also individual gases*
- gas fittings, leak-checking, 189
- gas lasers, 254
- gas metal arc welding (GMAW)
  - deposition efficiency, 155, 162, 163, 163
  - equipment, 10
  - operating factor, 164
  - overview of, 8-9
  - popularity of, 10



- gas metal arc welding (GMAW)
  - (*continued*)
  - welding illustration, 22
  - weld metal costs, 170, 172
- gas-shielded flux cored wires, 161–162, 162
- gas tungsten arc welding (GTAW)
  - equipment, 9
  - with helium, 218
  - overview of, 8
- gas welding, 8
- gauntlet gloves, 43–44, 44
- gloves, 43–44, 44
- GMAW. *See* gas metal arc welding
- goggles, 32–34, 33
- gouge removal, 282
- gouging
  - air carbon arc, 259, 262, 262, 265, 266
  - See also* U-groove gouging
- gouging torches, 257
- graphite, 260
- grinders, 60, 125, 318
- grinding, 128–129
- grinding stones, 60, 61, 128
- groove welds
  - angle and cost, 76, 76–77
  - dimensioning, 91–92, 92, 93
  - positions of test pipe or tubing, 147
  - positions of test plates, 147
  - procedure qualification
    - requirements, 139
  - terms, 72
  - types, 91
  - using, 74–76
  - volume, 150–152
  - welding positions, 72, 73
- ground-fault circuit interrupter (GFCI), 58
- grounding plugs, 57
- GTAW. *See* gas tungsten arc welding
- guided bend test, 292–295, 293, 294, 295
- Guide for the Training and Qualification of Welding Personnel Entry Level Welder*, 322
- hand angle grinder, 128
- hand cutting
  - described, 192–195
  - effect of flame, speed, and pressure on, 203
- hand tools, 53–54
- hardness testing, 309, 309
- hard slag, 203
- hardsurfacing weld, 263
- hazardous waste material, 42
- heat-affected zone, 228
- heating tip, 181
- heliarc welding, 218
- helium, 218
- hexavalent chromium, 39–40
- Hex Chrome, 39–40
- high-speed cutting tips, 183, 184
- hoists, 63, 64
- hole cutting
  - OFC process, 206–207
  - PAC process, 243, 244
- horizontal fixed pipe weld, 74, 74
- horizontal plate weld, 72, 73
- horizontal rolled pipe weld, 73, 74
- hoses, 52
- hot work permits, 48, 49
- housekeeping, 315–316, 316
- hydrochloric acid, 297
- hydrogen
  - flame temperature, 179
  - plasma arc cutting, 235
- impact testing, 298, 298–299
- inches, 103
- inclined pipe weld, 74, 74
- inclusions, 279–280, 280
- incomplete fusion, 281–283, 282
- infrared light, 30, 32
- injector torches, 182, 182
- intermittent fillet welds, 88, 88
- International Space Station, 100, 102
- interpass cold lap, 281
- ionized gas, 218–219
- isometric drawings, 80, 82
- Izod test, 298, 298
- J-groove gouging, 266
- joint design
  - base metal, 72
  - code or standards requirements, 76
  - cost and, 76–77, 149–150, 150
  - metal thickness, 74–76
  - parts of, 71, 71
  - pipe welding positions, 73–74, 74
  - plate welding positions, 72, 73
  - significance of, 70–71
  - welder skill, 76
  - welding process, 71–72
- joints
  - dimensions, 71
  - prequalified, 140–141
  - purpose, 71
  - symbols for weld location, 85–86, 87
  - types, 71, 71, 75
  - See also* butt joints
- joules, 227
- kerf
  - layout, 116–118, 119
  - plasma arc cutting, 231–233, 233
- kindling point/temperature, 178, 198
- labor costs, 148, 150, 150, 165–166, 167
- ladders
  - inspection, 65
  - materials used in, 65
  - rules for use, 65, 66
  - safety, 64–65
  - types, 64–65
- lamellar tears, 286, 287
- lamination, 286, 286
- lap joint, 71
- laser beam cutting (LBC), 253, 254–256
- laser beam drilling (LBD), 253, 256
- laser beam welding (LBW), 253
- laser equipment, 252
- lasers
  - applications, 252–253
  - creating a beam, 251
  - physical properties, 250–251
  - priming, 251
  - types, 253, 253–254
- layout
  - circles, arc, and curves, 110, 112, 113
  - factors affecting, 110
  - kerf space, 116–118, 119
  - material shapes, 110, 111
  - nesting, 113–116
  - for OFC, 195–196
  - overview, 108–110
  - performance testing, 315
  - square, rectangular, and triangular
    - parts, 110, 112
  - as a vocation, 13
- leak checking, 308
- leather jackets, 44, 44
- leather pants, 45
- leggings, 45
- lens shade densities, 241, 241
- Leonardo da Vinci, 77
- lifting, 63, 63
- light, burns caused by, 30–32
- linear porosity, 278, 279
- linear slag inclusions, 279
- line burner, 182
- lines
  - laying out (*see* layout)
  - in mechanical drawings, 79, 79, 80
- locking pliers, 123, 123
- longitudinal magnetization, 300, 301
- longitudinal shearing strength, 290, 291
- lung cancer, 39
- machine cutting
  - effect of flame, speed, and pressure on, 200–203
  - PAC, 236–237, 237, 238
- machine cutting torches, 182, 183
- machine operation, 11



- magnetic particle inspection (MT), 300, 301
- maintenance, 52
- manual operation, 11
- MAPP
  - flame temperature, 179
  - preheat holes, 186
- material cost, 148
  - See also weld costs; weld metal costs
- material safety data sheets (MSDSs), 42
- material shapes
  - layout and, 110
  - types and dimensions, 111, 119–120
- math
  - adding and subtracting, 104
  - conversion charts, 106, 107, 108
  - converting decimals to fractions, 105–106
  - converting fractions to decimals, 105
  - measuring, 102, 103
  - reducing fractions, 104
  - rounding numbers, 105
  - tolerances, 103–104, 104
- measuring, 102, 103
- mechanical drawing
  - dimensioning, 84, 84
  - lines, 79, 79, 80
  - overview, 77
  - projection, 80
  - rotating views, 77
  - special views, 82–83
  - types, 80, 81, 82
- mechanical testing (DT), 276
  - See also destructive testing
- metal-cutting machines, 61–63
- metal fume fever, 39
- metal plate
  - beveling, 208–209
  - dimensioning, 119
  - OFC cutting, 192–195, 203–204, 205–206
  - welding positions, 72, 73
- metals, density, 153
- metal scribes, 108
- metric conversions, 22, 106, 107, 108
- metric units, 22–23
- Mexico City, 270
- MIL, 134
- mixing chamber, 181–182, 182
- monochromatic light, 250, 250–251
- MPS gases, preheat holes, 186, 186–187
- MSDSs. See material safety data sheets
- natural gas
  - flame temperature, 179
  - preheat holes, 186
- natural ventilation, 40
- Nd-YAG laser, 253, 253, 254
- neodymium-doped yttrium aluminum garnet laser, 253, 253, 254
- nesting
  - defined, 110
  - layout, 113–116
- neutral flame, 191
- nick-break test, 292, 292
- nitric acid, 298
- nitrogen
  - as an assist gas, 255
  - in PAC, 228
  - plasma arc cutting, 235
- nondestructive testing (NDT)
  - eddy current inspection, 308
  - hardness tests, 309, 309
  - leak checking, 308
  - magnetic particle inspection, 300, 301
  - penetrant inspection, 299, 300
  - radiographic inspection, 301–302, 302, 303–307
  - symbols for, 94, 94–95, 95, 96, 97
  - ultrasonic inspection, 302, 307, 308, 308
  - uses, 276
  - visual inspection, 299
- nonmetallic inclusions, 280, 280
- nozzle insulators, 222
- nozzles, 222, 223
- nozzle tips, 222–223, 223
- numerical-control oxygen cutting machine, 14
- OAW. See oxyacetylene welding
- OFC. See oxyfuel gas cutting
- OFW. See oxyfuel gas welding
- Ohm's law, 226
- operating factor, 164, 164–165
- orifice, 189
- orthographic drawing, 80, 121
- outside corner joint, 71
- overhead costs, 148, 165–166, 167
- overhead plate weld, 72, 73
- overhead straight cuts, 209
- overlap
  - described, 283, 283
  - performance testing, 320
- overwelding, 149
- oxidizing flame, 191
- oxyacetylene, 179
- oxyacetylene hand torch, 180, 180
- oxyacetylene welding (OAW), 8
- oxyfuel gas cutting (OFC)
  - acetylene in, 8
  - chemistry of cutting, 197–200
  - correct and poor cuts, 201
  - cutting applications, 209–211
  - cutting speed, 200
  - cutting tables, 204
  - cutting tips, 182–187
  - cutting tip selection, 196
  - cutting torches, 180–182
  - defined, 178
  - distortion, 207–209
  - eye protection, 180, 180
  - fuel gases, 178–179, 179
  - gas pressure, 196–197
  - hand cutting, 192–195
  - layout, 195–196
  - metals cut using, 179–180
  - physics of a cut, 200–203
  - pipe cutting, 213–215
  - plate cutting, 192–195, 203–204, 205–206
  - profile of cut plates, 202
  - torch guides, 204–205, 205
  - torch lighting, 190–191
  - torch setup, 188–189
  - uses of, 179
  - washing, 212, 212
- oxyfuel gas welding (OFW), 8
- oxyfuel (OF) gas processes, 8
- oxygen, as an assist gas, 255
- oxygen cutting machine, 14
- oxygen lance cutting
  - application, 270
  - equipment, 269
  - overview of, 268–269
  - safety, 270
- oxygen lance rods, 268
- ozone, 40
- PAC. See plasma arc cutting
- paints, 39
- part dimension, 116
- penetrant inspection, 299, 300
- performance tests
  - cutting out parts, 316, 317
  - fit and assembly of parts, 316–317, 318
  - housekeeping, 315–316, 316
  - introduction to, 314–315
  - layout, 315
  - safety, 315
  - weld inspection, 319–320
  - workmanship standards, 319, 320, 321, 322
- perspective drawing, 80
- phosgene, 40
- pictorial drawing, 78, 80, 82, 121
- pipe
  - dimensioning, 119–120
  - OFC cutting, 213, 213–215
  - shapes, 111
  - welding positions, 73–74, 74



- pipe clamps, 122, 124
- pipe gap adjustment tool, 124
- piping porosity, 278, 279
- plasma, 218–219
- plasma arc, 219
- plasma arc cutting (PAC)
- arc plasma, 219
  - beveling a plate, 244–245, 245
  - circuitry, 231
  - controlling pressure, 235
  - control wire, 225
  - cutting factors affected by gases, 234–235
  - cutting machine, 219
  - cutting speed, 228–229
  - distortion, 227–228
  - flat cutting holes, 243, 244
  - gases, 234–235
  - gas hoses, 224
  - gouging, 238–240, 240, 245, 245
  - heat input, 227
  - kerf, 231–233
  - machine cutting, 236–237, 237, 238
  - manual cutting, 238
  - metals cut using, 229
  - origin of, 218
  - plasma, 218–219
  - plasma gas swirling, 232, 232
  - plate cutting, 242–243
  - power cables, 224
  - power requirements, 225–227
  - safety, 240–241
  - stack cutting, 236
  - standoff distance, 229–230
  - starting methods, 230
  - terminology, 230
  - torches, 219–223
  - typical setup, 224
  - water injection, 232, 233
  - water tables, 221, 237, 239
  - water tubing, 225
- plasma arc torches
- body, 220
  - castle nozzle tip, 230
  - common parts, 221–223
  - cutting parameters, 227
  - hand-held, 221
  - head, 220
  - power switch, 221
  - replaceable parts, 222
  - replacement part kit, 223
- plate. *See* metal plate
- plenum chamber, 230
- pliers, locking jaw, 123, 123
- plug welds, 89, 98
- P-numbers, 143, 325
- porosity
- overview of, 277–278, 279
  - performance testing, 320
- portable electric tools, 59–61
- positive-pressure respirators, 38
- power costs, 166
- powered air-purifying respirators (PAPRs), 38
- power punches, 62
- power shears, 62
- power tools, 59–61
- PQR. *See* procedure qualification record
- preheat flame, 185, 200
- preheat holes, 185–187, 186
- preheating, 200
- procedure qualification record (PQR)
- contents of, 135
  - example form, 138
  - positions for groove welds, 139
  - practice exercise, 144–147
- process cost, 148
- projection drawings, 80
- propane
- flame temperature, 179
  - preheat holes, 186
  - safety and, 41
- propylene, 179
- pulsed lasers beams, 254
- pulse-echo system, 302, 308
- punches
- safety, 53, 54, 62
  - used in layout, 108–109, 109, 195–196, 196
- qualification, 15–18
- qualified welders, 314
- qualifying test plates, examining, 139
- quality control (QC), 276
- radiographic inspection (RT), 301–302, 302, 303–307
- reamers, 188
- refrigerants, 40
- regulators, working pressure, 196–197
- resistance welding, 3
- respirators, 37–38, 38
- respiratory safety
- fume sources, 39–40
  - need for, 36
  - objectives, 35–36
  - respirators, 37–38
  - training in, 37
  - vapor sources, 40
- robotic cutters, 237, 238
- Rockwell hardness tester, 309, 309
- rod welding, 8
- root bend, 292, 293
- rotated view, 83, 83
- SAE. *See* Society of Automotive Engineers
- safety
- air carbon arc cutting, 263–264
  - checklist, 55
  - confined spaces, 40, 41
  - cylinder handling and storage, 46–48
  - ear protection, 35, 36
  - electrical (*see* electrical safety)
  - equipment maintenance, 52
  - with fabrication, 102
  - face and eye protection, 32–34
  - fire protection, 48–51
  - hand tools, 53–54
  - ladders, 64–65
  - lifting, 63, 63
  - material safety data sheets, 42
  - metal-cutting machines, 61–63
  - performance testing, 315
  - plasma arc cutting, 240–241
  - portable electric tools, 59–61
  - respiratory protection, 35–40
  - ventilation, 40–41
  - waster material disposal, 42
  - work area, 52–53
  - work clothing, 42–45
- safety boots, 43, 43
- safety classes, 28
- safety glasses, 32–34, 33
- SAW. *See* submerged arc welding
- saws, 63
- scarfing, 212, 212
- scattered inclusions, 279–280
- scrap cost, 148
- scrap metal, 42
- scribes, 108, 195–196
- seam welds, 90, 91
- second-degree burns, 29–30, 30
- section lines, 82, 82
- section view, 82, 82
- self-contained breathing apparatus (SCBA), 37
- self-shielded flux cored wires, 161, 162–163
- semiautomatic operation, 11
- semiautomatic submerged arc welding, 164
- SENSE, 17, 319–320, 322
- set of drawings, 77, 78
- shade lens, 34, 35
- shear force, 70
- shearing strength, 290, 291
- shears, 62, 62



- sheet metal
  - cutting tip, 186
  - OFC cutting, 206
- Sheet Metal Welding Code*, 314
- sheets, dimensioning, 119
- shielded metal arc welding (SMAW)
  - deposition efficiency, 155
  - efficiency of coated electrodes, 156
  - equipment, 9
  - operating factor, 164
  - overview of, 8
- shielding gas, flow rate, 153-154, 154
- shop math. *See* math
- side bend, 293
- sidewall fusion, lack of, 281
- single-bevel edge, 71
- single bevel joint, 75
- single-J edge, 71
- single J-groove joint, 75
- single-U edge, 71
- single U-groove joint, 75
- single-V edge, 71
- single V-groove joint, 75
- SkillsUSA, 18
- slag
  - described, 203
  - inclusions and, 279, 280
- slitting adaptor, 207
- SMAW. *See* shielded metal arc welding
- soapstone, 108, 108, 118, 195, 196
- Society of Automotive Engineers (SAE), 134
- socket wrench, 53, 53
- soft slag, 203
- solid state lasers, 254
- solid wires
  - deposition efficiency, 161-162
  - efficiency for GMAW, 162, 163, 163
  - efficiency for SAW, 162, 162-164
  - operating factor, 164
- sparks, 197, 198, 210
- spats, 45
- specifications, 132
- spectacles, 33
- spot welds, 89, 90
- square cuts, 195
- square edge, 71
- squares, 112
- stack cutting, 236
- standards, 132
  - See also* codes
- Standard Symbols for Welding, Brazing and Nondestructive Examination*, 85
- standard-to-metric conversions, 106, 107, 108
- standard welding procedure specifications, 20
- standoff distance, 229-230, 230
- star cracks. *See* crater cracks
- steel, kindling temperature, 178
- steel rules, 102
- steel tape measures, 102, 103
- stick welding, 8
- straight edge, 118
- structural shapes, 111
- Structural Welding Code Steel*, 136, 139
- stub loss, 156, 163
- submerged arc welding (SAW)
  - efficiency of solid wires, 162, 162-164
  - flux-to-wire ratio, 154
- subtraction, 104
- supplied-air respirators (SARs), 37
- synchronized wave form, 251
- tack welders, 11
- tack welding
  - overview of, 126, 127
  - performance tests, 319, 321
- tape measures, 102, 103
- TB. *See* torch brazing
- tee joint, 71
- templates, 118
- tensile force, 70
- tensile strength, 288
- tensile testing, 287-288, 288, 289
- test plates, examining, 139
- third-degree burns, 30, 31
- Thomson, Elihu, 3
- Thoth, 2
- tip cleaners, 189, 190
- tips. *See* cutting tips; nozzle tips
- title box, 77, 78
- toggle clamps, 123, 123
- tolerance, 103-104, 104, 110, 277
- tool rests, 61, 61
- torch brazing (TB), 8
- torches. *See* air carbon arc torches; cutting torches; plasma arc torches
- torch welding, 8
- torsion force, 70
- track torches, 182
- transverse shearing strength, 290, 291
- tubing
  - dimensioning, 120
  - shapes, 111
- two-piece cutting tip, 186, 187
- Type A fire extinguishers, 50, 50
- Type B fire extinguishers, 50, 50
- Type C fire extinguishers, 50, 50
- Type D fire extinguishers, 50, 50
- U-groove gouging
  - air carbon arc, 265
  - PAC process, 244-245, 245
- ultrasonic inspection (UT), 302, 307, 308, 308
- ultraviolet light
  - burns and, 30, 31-32
  - eye damage from, 34, 34
- undercut, 283-284, 284
- underfill, 285, 285
- valve protection caps, 47
- vapor sources, 40
- variable costs, 148
- ventilation, 40-41, 41, 129
- venturi, 182
- vertical pipe weld, 74, 74
- vertical plate weld, 72, 73
- vertical straight cuts, 209
- visible light, 30, 32
- visual inspection (VT), 299
- voltage warnings, 56
- warning labels, 55
- washing
  - air carbon arc cutting, 262, 263
  - described, 212, 212
- waste material, disposal, 42
- water-cooled cutting tip, 186
- water injection plasma arc cutting, 232, 233
- water jet cutting, 270-272
- water shroud, 223
- water tables, 221, 237, 239
- wedges, 318
- weld, defined, 4
- weld costs
  - amortization of equipment costs, 174
  - approaches to, 147-148
  - comparing weld metal costs, 170, 172
  - cost per foot of weld metal, 169-170, 171
  - cost per pound of deposited weld metal, 166-169
  - estimation, 148-152
  - factors affecting, 132
  - factors for cost formulas, 165-170
  - fillet welds, 152
  - fixed and variable, 148
  - groove welds, 150-152
  - joint design and, 149-150, 150
  - metal costs, 153-165
  - operating factors, 154
  - worksheets, 168, 173



- weld curtains, 31, 31
- Welder and Welding Operator Performance Qualification Test Record (WPQR), 16, 322-327, 323
- Welder and Welding Operator Qualification Test Record (WQR), 323
- welder assemblers, 11-12
- welder certification, 15-18, 314
- welder fitters, 11-12
- Welder Performance Qualification Test Record*, 16, 322-327
- welder qualification, 15-18
- Welder Qualification Procedure*, 16
- welders' helpers, 11
- welders' shirts, 42-43, 43
- welder testing. *See* performance tests
- welding
  - defined, 4
  - forms for tracking weldments, 20, 21
  - history of, 2-4
  - key practices in, 127-128
  - selecting a joining process, 10-11
  - skills development, 322-327
  - standard procedure specifications, 20
  - symbols for, 84-87, 85
  - uses of, 4-7
  - weld positions (*see* welding positions)
  - weld removal, 267, 267-268
- welding engineers, 13
- welding goggles, 32-34, 33
- welding helmets, 33, 34, 35
- welding inspectors, 12
- welding nozzle, 181
- welding occupations
  - opportunities in, 11-13
  - training for, 14-15
- welding operators, 11
- welding positions, 147, 324
  - pipe, 73-74, 74
  - plate, 72, 73
- welding procedure qualification, 134-136
- welding procedure specification (WPS)
  - defined, 134
  - example forms, 137, 142
  - example of prequalified weld joints, 140-141
  - format, 136
  - information in, 135
  - procedure qualification record, 135
  - qualifying and certifying, 135-136
  - supplementary information, 136
  - weld beads and, 319
  - welder qualification and, 16
  - writing, 139, 141-144
- welding processes, 7-11
- welding safety. *See* safety
- welding salespeople, 12
- welding schedule, 134
- welding shop owners, 12-13
- welding shop supervisors, 12
- welding symbols
  - backing, 94, 94
  - fillet welds, 88, 88
  - flange welds, 94-95, 94
  - groove welds, 91-92, 92, 93
  - indicating weld types, 85, 85
  - information in, 84, 85
  - nondestructive testing, 94, 94-95, 95, 96, 97
  - plug welds, 89, 98
  - seam welds, 90, 91
  - significance of arrow location, 86-87
  - spot welds, 89, 90
  - standards, 85
  - weld location, 85-86
- welding tips, 181
- welding wires
  - deposition efficiency, 156, 160-163
  - deposition rates, 155-159
  - See also specific types*
- weld inspection, 319-320
- weld joint design. *See* joint design
- weld joints. *See* joints
- weld location, symbols for, 85-87, 86
- weld metal. *See* deposited weld-metal
- weld metal costs
  - coated electrodes, 156
  - comparing, 170, 172
  - cost of electrodes, wires, gases and flux, 153-154
  - deposition efficiency, 154-155, 155
  - deposition rates, 153, 155-159
  - determination of filler weight, 153
  - efficiency of flux cored wires, 156, 160-163
  - efficiency of solid wires for GMAW, 163
  - efficiency of solid wires for SAW, 163-164
  - operating factor, 164, 164-165
- weld volume
  - fillet welds, 152
  - groove welds, 150-152
- wet saws, 63
- wire brushes, 128
- work area safety, 52-53
- work clothing, 42-45
- workmanship standards, 319
- wormhole porosity, 278, 279
- WPS. *See* welding procedure specification
- X-ray systems, 301-302, 302, 303-307
- YAG laser, 253, 253, 254
- yards, 103
- zinc, 39