



Welding

 Larsen & Keller

Gersham Levitt

Table of Contents

Preface	VII
Chapter 1 Introduction to Welding	1
a. Welding	1
b. How to Weld	17
c. How to Learn Welding	26
d. Welder	36
e. How to Become a Welder	36
Chapter 2 Welding Methods	45
a. Electroslag Welding	45
b. Electric Resistance Welding	46
c. Hyperbaric Welding	49
d. How to Weld Underwater	51
e. How to Weld Galvanized Steel	55
f. How to Weld Aluminum	59
g. How to use a MIG Welder	65
h. How to TIG Weld	74
i. How to Weld Stainless Steel	82
j. How to Torch Weld	86
k. How to Weld Lead	89
l. How to Weld Cast Iron	92
m. How to Weld Copper	95
n. How to MIG Weld Aluminum	102
o. How to Weld Bronze	104
p. How to Weld Steel with a Flux Cored Welder	110
q. How to Weld with a "Buzz Box"	111
Chapter 3 Arc Welding	113
a. Arc Welding	113
b. How to Arc Weld	120
c. Shielded Metal Arc Welding	131
d. Gas Tungsten Arc Welding	138
e. Gas Metal Arc Welding	149
f. Flux-cored Arc Welding	157
g. Submerged Arc Welding	160
Chapter 4 Arc Welding Safety	165
a. Eye Protection	169
b. First Aid for Eyes	171
c. How to Choose Appropriate Eye Protection	172
Chapter 5 Plastic Welding	176
a. Plastic Welding	176
b. How to Weld Plastic	182

c. Friction Welding	185
d. Heat Fusion	187
e. Ultrasonic Welding	188
f. Spin Welding	193
g. How to Weld Thermoplastic	194

Chapter 6 Soldering	197
a. Soldering	197
b. How to Solder	213
c. How to Solder Electronics	223
d. How to Solder Pipe	231
e. How to Solder Silver	232
f. How to Solder Stained Glass	239

Index

Index

A

Alloy, 13, 56, 106, 108, 111, 130, 142, 144-145, 152-153, 156, 167, 170-171, 194, 206, 208-209, 213, 222, 225, 229, 232, 237-238, 241, 255

Aluminum, 5, 12, 15, 18, 22, 24, 28, 43-44, 47, 56, 67-71, 80, 82, 84, 86, 110-114, 116, 128-130, 146-149, 151-155, 159-163, 193-194, 197, 199-200, 207, 237, 255

Amperage, 27, 38-39, 42-43, 64-65, 72-73, 81, 85, 90, 119, 129-130, 134, 138, 255

Annealing, 23, 255

Arc Eye, 20, 44, 75, 126, 142, 148, 164, 255

Arc Flame, 39-40, 66, 129-130, 135, 255

B

Brazing, 7, 9, 56, 112-114, 116, 205, 207-210, 216, 242, 255

Butt Weld, 84, 90, 119, 255

Butt Welding, 14, 56, 195-196, 255

D

Dry Welding, 58-59, 255

Ductile, 18, 43, 130, 142, 163, 172, 255

E

Electric Arc, 10-11, 13, 20, 44, 53, 59, 103, 121, 125-129, 131, 135-136, 139-142, 146-149, 157, 159, 163-165, 169, 173, 255

Electric Resistance Welding, 5, 7, 10, 53-54, 57, 255

Electrode, 10-13, 25, 27-30, 36-41, 53-54, 56, 59-60, 66, 68, 72-73, 79, 82-84, 86, 90, 92, 108, 110-111, 113, 120-132, 134-137, 139-148, 157-167, 169-171, 176, 255

Electrode Holdgr, 10, 25, 38, 86, 134, 140-141, 143, 145, 159, 255

Electroslag Welding, 5, 7, 10, 13, 53-54, 124, 128, 255

Energy Beam, 14, 255

Explosion Welding, 15, 255

F

Foot Pedal, 72-73, 83, 85, 255

Forge Welding, 10, 14, 127, 193, 255

Friction Stir Welding, 10, 15

Friction Welding, 6-7, 9, 15, 19, 59, 184, 187, 193-195, 201, 255

G

Galvanized Steel, 5, 63-66

Gas Flame, 10, 255

Gas Metal Arc Welding, 5, 7, 9-12, 17, 53, 58, 74, 92, 122-123, 128, 130, 142, 146, 153-154, 157-160, 163

Gas Tungsten Arc Welding, 5, 10-11, 13, 17, 19, 58, 92, 122, 124, 128, 130, 146-151, 154, 158, 163, 255

Geometry, 15-16, 49, 161, 186, 188, 255

Glass Casting, 23, 255

Glass Welding, 23, 255

Glassblowing, 23, 255

Goggles, 20, 118, 126, 175, 178, 181-182, 209, 223, 243, 255

H

Hammer, 25, 30, 41, 94, 118-119, 162

Hyperbaric Welding, 5, 7, 53, 57-59, 255

L

Laser Cladding, 14, 255

Lead, 5, 13, 21-25, 29, 44, 68, 71, 88, 97-100, 127, 129, 142, 148, 161, 163, 174, 185, 198, 202, 205-206, 208-209, 211-215, 217-219, 222, 224-225, 232, 235, 239, 241-242, 255

Leather Gloves, 20, 44, 125, 131, 142, 148, 163, 255

M

Magnetic Pulse Welding, 10, 15, 255

Metallic Bonding, 18, 255

Metallurgy, 18, 49, 255

Metals, 7, 9, 18, 21, 44, 56, 59, 74, 77, 80-81, 84, 87, 89-91, 105, 121, 123-124, 126, 128-130, 139, 146, 148-149, 151-154, 156, 159-160, 165, 167-168, 174, 180, 187, 193-194, 197-200, 205, 217, 219, 222, 241-242, 255

Mig Gun, 74, 76, 255

P

Plasma Arc Welding, 13, 19, 58, 124, 128, 146-147, 255

Plastic Welding, 5, 7, 22, 24, 184-185, 187-189, 191, 193, 195, 197, 199, 201-203, 255

Polymer, 15, 44, 187, 189, 198, 255

S

Seam Welding, 14, 56

Shielded Metal Arc Welding, 5, 7, 9, 11-12, 16-17, 19, 21, 25, 44, 58-59, 92, 121-123, 126, 128-130, 139-140, 142-143, 145-146, 148, 154, 157-158, 163, 166, 169, 255

Shot Welding, 14, 55, 255 Slag, 10, 12-13, 25, 30, 41-42, 53-54, 59, 65, 67, 94, 118-119, 121, 123-124, 130-132, 137-139, 141, 144, 160, 163, 166-170, 172, 176, 183, 255

Soldering, 6-7, 9, 33, 185-186, 196, 205-229, 231-247, 249, 251-255

Spot Welding, 14, 16, 22, 55-56, 120, 158, 186, 220, 255

Stainless Steel, 5, 13-14, 44, 47, 55, 69, 75, 77, 82, 86, 90-94, 124, 140, 142, 145-146, 149, 154, 156, 158, 161, 165, 170, 210, 256

Stud Welding, 256

T

Temperature Gradient, 23, 163, 256

Thermoplastics, 9, 24-25, 184-185, 189, 193-194, 197-199, 256

Tig Machine, 82, 256

Torch, 5, 23, 31-34, 70-71, 73, 78, 83, 87-88, 90, 93-99, 114, 116-117, 120, 130, 140, 143, 146-151, 158, 160, 163, 208-210, 214-216, 220, 228-231, 239-242, 246, 256

Tungsten, 5, 10-11, 13, 17, 19, 24, 43, 47, 56, 58, 68, 70, 72-73, 82, 84, 86-87, 92, 107, 113, 122, 124, 128, 130, 146-155, 158, 163, 255-256

W

Welder, 5, 14, 28, 31, 36, 38, 45, 48, 59, 69, 72-73, 75, 78, 80, 82, 84, 95, 104, 106-107, 110, 112, 116, 121, 129, 138, 147, 151, 154, 163, 169, 173-176, 183-185, 187, 203, 256

Welding Helmet, 20, 26, 68, 83, 103, 120, 175, 183, 256

Welding Helmets, 20, 29, 44, 142, 164, 178, 256

Welding Jacket, 26, 103, 256

Welding Machine, 7, 25, 59, 64, 79, 83, 119, 128-130, 132, 134, 143, 256

Welding Power Supply, 11, 44, 59, 121, 139, 143, 145-146, 150, 158, 166, 256

Welding Rod, 41, 59, 119-120, 129, 131, 174, 185-186, 190-191, 202-204, 256

Welding Stock, 39, 256

Welding Torch, 93, 146-147, 149-151, 160, 163, 256


Wet Welding, 59, 62, 256

Wire, 10-13, 25, 27, 31, 43, 46, 53-54, 74-75, 77-78, 80-81, 86, 93, 110, 128, 140, 147, 160, 176, 196, 199, 202, 205, 210, 213, 220, 225-227, 229-230, 232-233, 235, 241, 256

Wire Brush, 25, 27, 31, 86, 93, 118-119, 138, 149, 163, 202, 217, 220, 256

X

X-ray Welding, 14, 256



23.10.19