



WELDING: A Beginner's Guide

TABLE OF CONTENTS

Preface

v

CHAPTER 1 INTRODUCTION TO WELDING.....	1
• Introduction	1
• Overview of Welding	2
• Welding Equipment	6
• The History of Welding	13
• Weld Joints	16
• Welding Symbols	19
• Safely Precautions for Welding	23
• Summary	26
• References	28
CHAPTER 2 PHYSICS OF WELDING ARC.....	29
• Introduction	29
• Arc Welding Fundamentals	30
• Methods of Initiating and Maintenance of the Welding Arc	41
• Arc Forces and Arc Efficiency	49
• Summary	68
• References	69
CHAPTER 3 WELDING POWER SOURCES	71
• Introduction	71
• Characteristics of Power Source	73
• Volt-Ampere Characteristics of a Welding Power Source	85
• Constant Current Characteristics of a Welding Power Source	88
• Constant Voltage Characteristics of a Welding Power Source	90
• Choosing a Welding Power Source	96
• Dynamic Characteristics of Welding Power Sources.....	102

• Summary	108
• References	110
CHAPTER 4 HEAT FLOW IN WELDING.....	111
• Introduction	111
• Weld Thermal Cycle.....	113
• Cooling Rate.....	116
• Peak Temperature and Heat Affected Zone.....	121
• Solidification Rate.....	124
• Residual Stresses.....	125
• Summary	135
• References	136
CHAPTER 5 PERFORMANCE OF GAS WELDING	137
• Introduction	137
• Process of Gas Welding	139
• Progression in Weld Pass.....	154
• Gas Welding in Carbon Steel Plates and Tubes.....	168
• Summary	181
• References	184
CHAPTER 6 DESIGN OF WELD JOINTS.....	187
• Introduction	187
• Design of Weld Joints.....	187
• Need for Edge Preparation in Welding	197
• Design Aspects of Weld Joint	203
• Design of Weld Joints for Fatigue Loading	207
• Parameters Related with Welding.....	228
• Improving the Fatigue Performance of the Weld Joints.....	235
• Summary	241
• References	242
INDEX.....	243

INDEX

A

- Alloys 3
Alternating current (AC) 30, 36, 68
Arc burn 8
Arc efficiency 50, 59, 60
Arc voltage 31, 37, 40, 46, 47, 48, 57, 58, 61, 62
Arc welding 3, 26
Arc welding processes 112, 135
arrow side 20

B

- base metal 5, 8, 10, 11
bead-on-plate (BOP) welding 120
bead weld 200, 241

- butt joint 18
butt weld 8

C

- Carbonizing flame 148
Constant voltage (CV) 76, 90
Consumable electrode 143, 144, 145, 181
cooling rate (CR) 116, 135
corner joints 16, 17, 27
cover pass 8
critical cooling rate (CCR) 120

D

- diffusion welding 11
Direct current (DC) 30, 36, 40, 68

Direct current electrode negative (DCEN) 39, 53

Direct current electrode negative polarity (DCEN) 40

Direct current electrode positive polarity (DCEP) 40

E

edge joint 17

Edge preparation 197, 241

electric arc 2, 13, 26

Electrode 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 48, 49, 50, 51, 52, 53, 54, 55, 57, 58, 59, 61, 62, 63, 64, 65, 66, 67, 68

Electrode diameter 232

Energy beam welding 3, 26

energy density 114, 115

F

fatigue crack growth (FCG) 218, 241

fatigue crack growth rate (FCGR) 217

field weld 21

filler material 187, 188, 241

filler pass 8

Fillet welds 200, 241

finish symbol 22

flat welding 194

Flux Core Arc Welding 2

forge welding 2

friction welding 11, 16

G

Gas cylinders 177

gas flame 2, 26

Gas metal arc welding (GMAW) 145, 181

Gas Tungsten Arc Welding (GTAW) 2, 99

Gas welding 137, 138, 139, 141, 147, 152, 153, 168, 181, 182

Gas Welding 3

Globular metal transfer 146

Groove weld 197

H

heat affected zone (HAZ) 116, 188, 203

Heat dissipation 44

Heat flow 111, 135

horizontal welding 194, 195

hot pass 8

I

Inert gas welding 142, 144

J

Joint 9, 17, 18

K

Kinetic energy 36, 54

L

lap joint 17

laser beam welding 3, 11, 26

M

metal industry 6, 26

Metal inert gas (MIG) 149, 182

Metal inert gas welding (MIG)

143

Methyl acetylene-propadiene-petroleum (MAPP) 152

N

Non-destructive testing (NDT) 161

O

Open Circuit Voltage (OCV) 74

overhead welding 196, 197, 202

Oxidizing flame 148, 149

Oxy-acetylene 152, 172, 177, 178

Oxy-acetylene welding 152, 172, 178

oxyfuel welding 11

P

peak temperature 113, 114, 116, 121, 122, 123, 127, 135

Plasma arc welding 88, 106

plasma transferred arc welding (PTAW) 201

Plastic Welding 11

Plug welding 9

Polarity 9

Pressure 187

Pressure Welding 11

R

Radiation 57

reference line 19, 20

Residual stresses 125, 126, 127, 129, 135

resistance welding 11

root bead 9

S

Shallow hardening 240

Shielding gas 61

Solidification 124, 125

solid-state welding 3, 11

Spot welding 9

stainless steel 3

Stick Welding 2

stringer pass 8, 9

Supplementary symbols 21

Surface preparation 170, 183, 188

Surface tension 34, 50, 51, 52, 62, 63, 64

T

tee joint 18

Thermal conductivity 48, 64

Thermal degradation 54, 67

Tungsten inert gas welding (TIG) 143

U

ultrasonic welding 11

V

vertical welding 195, 196

Visual inspection 159, 161, 182

W

welded joint 1, 8, 20


Welder Qualification Test Record (WQTR) 156

weld fusion boundary 116

Weld groove 10

Welding 1, 2, 3, 4, 5, 6, 7, 10,

- 11, 12, 13, 15, 19, 23, 26, 28
Welding code 171
welding current 190, 196, 202,
229, 230, 232, 236
welding parameters 114, 117,
122
Welding power source 71, 72,
73, 76, 78, 86, 87, 88, 90,
91, 92, 93, 94, 95, 96, 104
Welding Procedure Specification (WPS) 156, 182
Welding processes 1, 10, 28
Welding speed 202
Welding system 72
Welding torch 139, 141, 147,
150, 151, 152, 182
Weld joints 187, 188, 189, 208,
234, 238
weld metal 8, 10, 112, 115, 116,
117, 124, 127, 129, 135,
187, 188, 189, 194, 195,
196, 198, 199, 200, 201,
202, 203, 209, 210, 224,
226, 229, 231, 232, 233,
234, 236, 237
weld pass 10
Weld symbols 20
Weld thermal cycle 113, 117,
128, 135



07-10-19

100-004600