



This Edition is licensed for sale only in the Philippines. Circulation of this Edition outside of the Philippines is UNAUTHORIZED AND STRICTLY PROHIBITED.

Welding

Skills, Processes, and Practices Level 2



Larry Jeffus • Lawrence Bower • Hugh McPhillips

Contents

Mapping Grid v
Introduction vii
Foreword ix
Credit page ix
About the authors x
About the book x

1 Introduction to Welding 1

Heat Generation 3
Welding Defined 4
Pre-Requisites for Welding 5
Occupational Opportunities in Welding 5
Welding Processes 6
Factors Affecting The Selection of a Welding Process 9
Training for Welding Occupations 9
Qualified and Certified Welders 10
Professional Association 11
Skills Competitions 11
Workshop Tasks and Practices 11
ACTIVITIES AND REVIEW 12

2 Working Safely, Efficiently and Effectively 13

Legislation 14
Hazards and Risk 15
COSHH 17
Material Safety Data Sheets (MSDSs) 17
Waste Material Disposal 18
Burns 18
RIDDOR 21
Personal Protective Equipment 22
Respiratory Protection 25
Ventilation 28
Confined Spaces 29
Work Clothing 29
Special Protective Clothing 29
Handling and Storing Cylinders 30
Fire Protection 31
Equipment Maintenance 33
Work Area Housekeeping 34
Hand Tools 34
Electrical Safety 35

Electrical Safety Systems 36
Voltage Warnings 36
Extension Leads 36
Manual Handling 37
Lifting Operations and Lifting Equipment Regulations (LOLER) 37
Working at Heights 37
Working Efficiently and Effectively 39
ACTIVITIES AND REVIEW 40

3 Communicating Technical Information 42

Weld Joint Design 43
Mechanical Drawings 48
Welding Symbols 52
ACTIVITIES AND REVIEW 59

4 Engineering Materials, Measurement and Fitting Skills 61

Fabrication 62
Material Selection 63
Common Engineering Materials 64
International Organization for Standardization (ISO) 68
Material treatment 70
Market Forms of Supply 70
Measurement and Marking Out 71
Marking out tools 72
Marking Out 75
Assembly 81
Assembly Tools 82
Fitting 84
Tack Welding 85
Welding 86
Finishing 87
ACTIVITIES AND REVIEW 88

5 Oxy-fuel Gas Welding, Brazing and Soldering 90

Equipment 91
Regulators 92

Setup and assembly of equipment 102
 Lighting Up, Flame Variations and Shutting Down Technique 103
 Welding Techniques 104
 ACTIVITY AND REVIEW 118

6 Thermal Cutting Techniques 119

Oxy-Fuel Gas Cutting 120
 Oxy-Fuel Cutting, Setup and Operation 128
 Plasma Arc Cutting 142
 Oxy-Fuel Review 160
 Plasma Review 160

7 Manual Metal Arc Welding 161

Welding Current 162
 Types of Welding Power 165
 Types of Power Sources 166
 Duty Cycle 171
 Welding Cables and Leads 171
 Electrode Holders 172
 Work Clamps 172
 Setup 173
 Striking the Arc 174
 Practice Welds 181
 Plate Preparation 202
 Safety Rules for Portable Electric Tools 205
 ACTIVITY AND REVIEW 208

8 Metal Inert Gas Shielded and Flux Cored Welding 209

Welding Power Supplies 210
 Molten Weld Pool Control 214
 Equipment 221
 Spot Welding 227
 Face, Eye and Ear Protection 229
 General Work Clothing 230
 Setup 231
 Filler Metal Selection 236
 Gas Density and Flow Rates 241
 Arc-Voltage and Amperage Characteristics 243
 Metal Preparation 244
 Practices 245
 Short-Circuiting or Dip Transfer 245
 Dip Transfer Technique 247
 Vertical Down (PG) Positions 252

Axial Spray Metal Transfer 253
 Flux Cored Arc Welding 259
 Electrodes 263
 Flux 265
 Flux Cored Steel Electrode Identification 268
 Shielding Gas 270
 Welding Techniques 271
 Practice Welds 278
 Fillet Welds 285
 ACTIVITY AND REVIEW 290

9 Tungsten Inert Gas Shielded Welding 291

TIG Welding Equipment 292
 Setting Up a Tig Welder 311
 Filler Rod Manipulation 315
 Current Setting 316
 Practice Welds 320
 Back Purging 329
 ACTIVITY AND REVIEW 330

10 Heat Input and Distortion Control Techniques 331

Effects of Heat Input 332
 Types of Distortion 333
 Factors Affecting Distortion 335
 Distortion Control Techniques 336
 Alternative Joint Design 339
 ACTIVITY AND REVIEW 345

11 Quality Control 346

Documentation 347
 Weld Procedure Sheets (WPS) 350
 Inspection 350
 Component Features of a Weld 351
 Imperfections and Defects 353
 Destructive Testing 360
 Non-Destructive Testing (NDT) 373
 ACTIVITY AND REVIEW 381

Appendix 382
Glossary 385
Index 388

Index

- accident report books, 22
acetone, 13, 31, 92
acetylene, 91-2
acetylene cylinders, 31, 92
alloy steels, 65
alternative joint design, 335-44
alternators, 169-70
aluminium, 66-8, 321-2
aluminium alloy designations, 68
aluminium-silicon alloys, 112
American Society of Mechanical Engineers, 42
American Welding Society, 42
ammonium persulfate, 372
amperage, 243-4
amperage setting, 167
amperes, 119
angles, 71
angular distortion, 332-4
annealing, 70
approved welders, 10
arc blow, 165
arc plasma, 209
arc strikes, 358
arc voltage, 165, 243-4
argon, 31, 214, 300
argon gas blends, 214-15
arm protection, 29
ASME (American Society of Mechanical Engineers), 42
assembly, 81-7
attitude to work, 39
autogenous welds, 1, 4
automated operation, 1
automatic operation, 1
AWS see American Welding Society
axial spray metal transfer, 253-6
- back caps, 305
back gouging, 161, 203
back marks, 61
back purging, 329
backfires, 96
backhand welding, 219
backing, 58
backing bars, 341
backing strips, 341
band saws, 207
blowback, 90, 138
body protection, 29
brass, 69
brazing, 111-17
brazing, 1, 111-17
brazing wires, 382-3
Brinell hardness tester, 346, 364
brittleness, 63
- bronze, 69
burns, 18-21
butt joints in the flat position, 249, 257, 328
butt welds, 57-8
- cadmium, 27
calculations, 78-81
capping runs, 283
carbon dioxide, 215
carbon monoxide, 28
cast iron, 65
cerium tungsten electrodes, 308
certification approvals, 1
chain dimensioning, 75
chills, 341
Chrome 6, 27
chromium compounds, 27
clamps, 82-3, 172
Clean Air Act, 18
cleats, 84
close annealing, 70
closed outside corner welds, 106, 107, 108
co-ordinates, 75
cold rolling, 70
combination sets, 72-3
concentricity, 75
conductivity, 63
confined spaces, 1, 29
Control of Substances Hazardous to Health (COSHH), 17
copper, 68-9
copper flow, 112
copper-phosphorous alloys, 112
copper-zinc alloys, 112
corner joints in flat position, 252, 259
corrosion resistance, 64, 116
COSHH (Control of Substances Hazardous to Health), 17
COSHH labeling chart, 19
coupling distance, 119, 131
cover passes, 201-2
cranes, 37
crater cracks, 358-9
creep resistance, 64
cupro-nickel, 69
cut-off machines, 207
cutting tips, 119
cylinder valve outlets, 92
cylinders, 30-1, 92, 100-1
- datums, 75
defects, 1, 11, 353-60
delamination, 119, 138, 346, 359
- destructive testing, 360-73
preparation, 371-3
dexterity, 1, 3
dial test indicators, 74
dimensioning, 52, 75
dip transfer, 212-13, 245-7
distortion, 332-9
distortion control, 336-9, 341-4
dividers, 73
drag, 119, 134
drag lines, 119, 138
drawings, 48-52
drills, 206
dross, 119, 141
ductility, 63, 116
duty cycle, 171
- ear protection, 13, 25, 230
eddy current inspection, 380
effectiveness, 39
efficiency, 39
elasticity, 63
electric arc energy processes, 3
electric shocks, 13, 35
electrical conductivity, 63
electrical resistance, 1, 4
electrical safety, 35-6
electrode conduits, 226
electrode feeders, 223-5, 262
electrode holders, 172
electrode setback, 119, 145
electrode tips, 119
electrodes, 181-2, 263-5, 268-70, 305-10
electrolytic reactions, 61
EMS (environmental management systems), 18
engineers blue, 75
engineers squares, 72
environmental management systems, 18
equipment maintenance, 33-4
etching, 291, 371-3
exothermic reactions, 119
explosimeters, 13, 32
extension leads, 36-7
extrusions, 71
eye protection, 22, 229
- fabrication, 62-3
face shields, 229
fatigue resistance, 116
fatigue testing, 361-2
FCAW see flux cored arc welding
feeler gauges, 74
filler metals, 111-12, 236-41
- filler passes, 201
filler rods, 101, 315-16, 382-3
filler runs, 282-3
filler wires, 101, 382-3
fillet weld break test, 371
fillet welds, 42, 57, 285-7
finishing, 87
fire blankets, 33
fire extinguishers, 33
fire protection, 31-3
fire watching, 32
fitting, 61, 84
fixtures, 84
flange welds, 59
flash glasses, 13, 22, 229
flashback arrestors, 96
flashbacks, 90, 95-6
flatness, 75
flux cored arc welding, 2, 9, 259-89
advantages of, 262-3
capping runs, 283
electrode extension, 276
electrode feeders, 262
electrodes, 263-5, 268-70
filler runs, 282-3
fillet welds, 285-7
fluxes, 265-8
globular transfer, 275-6
gun angle, 271-4
lap fillet weld in the flat position, 288
limitations of, 263
mode of metal transfer, 274
porosity, 276-8
practice welds, 278-83
root runs, 281
shielding gas, 270-1
smoke extraction nozzles, 261
spray transfer, 274-5
square butt welds, 279
square butt welds in flat position, 279-80
stringer beads in the flat position, 278
T-fillet weld in the flat position, 287
techniques, 271-8
travel speed, 274
V-butt joint in the flat position, 283
V-butt welds in the flat position, 281
- flux residue, 115
fluxes, 112-15, 265-8
folding allowances, 77-8
foot protection, 29

- forced ventilation, 13, 28
 forces on a weld, 43
 forehand welding, 220
 forge welding, 2
 forgings, 71
 formulae, 76-7
 free bend test, 370
 french chalk, 14, 31
 frustrum, 42
 full face shields, 14
 fumes, 26-7
 fusion, 42, 46, 91
 fusion welding, 91, 108
- gas cylinders, 30-1, 92, 100-1
 gas economizers, 100
 generators, 169-70
 globular transfer process, 254, 275-6
 goggles, 14, 99, 229
 gouging, 91, 120, 155, 159, 161, 203
 graphite, 61
 grinders, 87, 205-6
 grooves, 42, 46, 119
 guided bend test, 367
- hand protection, 29
 hand tools, 34-5
 hard dross, 120, 141
 hard facing, 2
 hard soldering, 112
 hardening, 70
 hardness, 63
 hardness testing, 363-4
 hazards, 15-16
 health and safety classes, 14
 heat generation, 3-4
 heat input, 332-3
 heat-affected zones, 120
 helium, 215, 300
 helmets, 14, 24, 229
 hermaphrodite callipers, 73
 hexavalent chromium, 27
 high-frequency alternating current, 346
 high-speed cutting tips, 120
 hoists, 37
 hollow sections, 71
 hose check valves, 98
 hose connectors, 97-8
 hoses, 34, 96-7, 303-4
 hot passes, 199-201
 hot work permits, 14, 31-2
 housekeeping, 14, 34
 hydrochloric acid, 372
 hydrogen, 300-1
- impact testing, 364
 imperfections, 2, 11, 353-60
 inadequate joint penetration, 356
 inclusions, 355-6
 incomplete fusion, 357
 inductance, 213-14
 infrared light, 14, 21
 initiative, 39
 inspection, 330, 373-80
 inverter machines, 169
 ionized gas, 120, 143
- jacks, 84
 jigs, 84
 joint configuration, 42
 joint design, 43-7, 117
 joint types, 42, 43
 joints
 physical properties, 116
 joules, 120
- kerf, 2, 150-1
- ladders, 38
 lamellar tears, 360
 lamination, 359
 lanthanum tungsten electrodes, 308-9
 lap fillet welds, 108
 lap fillet welds in the flat position, 288
 lap joints, 106, 189, 325
 lap joints in flat position, 250, 258
 lap protection, 29
 lead, 27
 leak checking, 379
 leftward welding, 104
 leg protection, 29
 legislation, 14-15
 lifting, 37
 Lifting Operations and Lifting Equipment Regulations, 37
 line of chords rules, 72
 LOLER *see* Lifting Operations and Lifting Equipment Regulations
 longitudinal distortion, 334-5
- machine mounted cutting torches, 120
 machine operation, 2
 macro-examination, 371
 magnetic particle inspection, 373-80
 MAGS (metal active gas shielded welding), 8
 malleability, 63
 mandatory, 14
 manifolded cylinders, 100-1
 manual handling, 37
 manual metal arc welding, 2, 7, 161-208
 alternators, 169-70
 amperage setting, 167
 arc length, 177
 back gouging, 203
 band saws, 207
 cables and leads, 171-2
 cover passes, 201-2
 current settings, 175
 cut-off machines, 207
 drills, 206
 duty cycle, 171
 electrode angle, 178-9
 electrode holders, 172
 electrode manipulation, 180
 electrode size and heat, 176
 electrodes, 181-2
 filler passes, 201
 generators, 169-70
- grinders, 205-6
 hot passes, 199-201
 inverter machines, 169
 lap joints, 189
 metal-cutting machines, 206
 movable-coil machines, 168
 multiple-coil machines, 167
 open root weld on plate, 198
 outside corner joints, 188
 plate preparation, 202-4
 portable electric tools, 205
 positioning, 181
 power sources, 166-70
 practice welds, 181
 punches, 206-7
 rectifiers, 170
 root passes, 193-4
 safety rules, 205
 setup, 173-4
 shears, 206-7
 square butt joints, 185
 striking the arc, 174-5
 stringer beads, 182-3
 T-joints, 192
 transformers, 166
 weld beads, 183-4
 welding current, 162-4
 welding power, 165
 work clamps, 172
- manual operation, 2
 market forms of supply, 70-1
 marking out, 72-81
 material safety data sheets, 14, 17-18
 material selection, 63-4
 material treatment, 70
 measuring, 42, 71-2
 mechanical drawings, 48-52
 mechanical heat generation, 4
 mechanical testing, 209, 277
 metal active gas shielded welding, 8
 metal inert gas shielded welding, 3, 8, 209-59
 amperage, 243-4
 arc voltage, 243-4
 axial spray metal transfer, 253-6
 backhand welding, 219
 butt joint in flat position, 249, 257
 corner in flat position, 252
 dip transfer, 212-13, 245-7
 electrode conduits, 226
 electrode extension, 217
 electrode feeders, 223-5
 electrode wire threading, 235-6
 equipment, 221-7
 filler metals, 236-41
 flow rates, 241-3
 forehand welding, 220
 gas density, 241-3
 globular transfer process, 254
 gun angle, 219
 gun manipulation, 217
 inductance, 213-14
- lap joint in flat position, 250, 258
 metal preparation, 244
 molten weld pool control, 214-20
 outside corner in flat position, 259
 personal protective equipment, 229-30
 power settings, 217
 power source, 222
 power supplies, 210-14
 practices, 245
 pulsed-spray transfer, 254-6
 setup, 231-6
 shielding gas, 214-17, 256
 short-circuiting transfer, 212-13, 245-7
 spool guns, 225
 spot welding, 227-8
 stringer bead deposition, 247, 256
 T-joint in flat position, 251, 258-9
 travel speed, 217
 vertical down technique, 252
 welding guns, 226
 wire feeders, 223-5
 wire-feed speed, 212
 work clothing, 230
- metal-cutting machines, 206
 metallurgy, 2
 MIG *see* metal inert gas shielded welding
 mill certificates, 347-9
 MMA *see* manual metal arc welding
 molten weld pool control, 214-20
 movable-coil machines, 168
 MSDS (material safety data sheets), 14, 17-18
 multi-stage regulators, 94
 multiple-coil machines, 167
- natural ventilation, 14, 28
 NDT (non-destructive testing), 2, 373-80
 nick-break test, 366
 nickel, 112
 nickel alloys, 112
 nitric acid, 372
 nitric oxide, 27-8
 nitrogen, 217, 301
 non-destructive testing, 2, 373-80
 non-return valves, 98
 normalization, 70
 nozzle insulators, 120
 nozzle tips, 120
 nozzles, 91, 98-9, 120, 124-7, 261, 304-5
- open circuit voltage, 165
 orifices, 91
 orthographic projection drawings, 50-1
 outside corner joints, 188, 324
 outside corner joints in flat position, 252, 259
 overlap, 358

- oxy-acetylene welding, 6-7
oxy-fuel gas cutting, 120-42
 chemistry of, 131
 conditions, 137-8
 cut interpretation, 138-9
 cutting nozzles, 124-7
 cutting tables, 127
 cutting torches, 121-3, 128-30
 delamination, 138
 distortion, 136-7
 hand cutting, 141
 pipe, 135
 plate, 131-4
 health and safety, 127
 holes, 135
 layout, 130
 personal protective equipment, 121
 setup, 128-30
 torch guides, 127-8
- oxy-fuel gas welding, 14, 91
 equipment, 91-101
 flame variations, 103
 lighting up, 103
 setup and assembly of equipment, 102
 shutting down, 103
 welding techniques, 104-17
- oxygen, 92
oxygen cylinders, 31, 92
ozone, 27
- PAC *see* plasma arc cutting
parallax error, 72
parallelism, 75
PAT (Portable Appliance Testing), 36
peening, 43, 342
penetrant inspection, 373-80
personal hygiene, 39
personal protective equipment, 13-14, 22-5, 29, 229-30
phosgene, 27
pig iron, 64
pipes, 70
plasma, 120, 143
plasma arc cutting, 43, 142-59
 applications, 148-9
 distortion, 147-8
 electrode setback, 145
 gases, 151-2
 heat input, 147
 kerf, 150-1
 machine cutting, 153-4
 manual cutting, 154
 plasma torches, 143-5
 power and gas cables, 145-6
 power sources, 146-7
 safety, 155-6
 stack cutting, 153
 stand-off distance, 149
 starting methods, 149-51
plasma arc gouging, 120, 155
plasma torches, 143-5
plasticity, 63
plate metal, 70
plate welding positions, 45-6
plate-generated problems, 359
plug welds, 43, 57
polar co-ordinates, 75
Pollution Prevention and Control Act, 18
porosity, 276-8, 354
Portable Appliance Testing, 36
portable grinders, 87
post-heating, 342
PPE *see* personal protective equipment
pre-heat flame, 120
pre-heat holes, 120, 138
pre-heating, 342
pre-qualification, 47
precision steel rules, 72
pressure gauges, 95
production documents, 349
profiles, 75
progressive dimensioning, 75
projection drawings, 43, 50-1
protective clothing, 29-30
prototypes, 2
pulsed-spray transfer, 254-6
punches, 74, 206-7
- qualified welders, 10
quality control, 346-80
 definition, 346
 documentation, 347-50
- radiation of heat and light, 4
radiographic inspection, 347, 374-7
reamers, 100
rectangular co-ordinates, 75
rectifiers, 170
regulators, 92-5
Reporting of Injuries, Diseases, and Dangerous Occurrences Regulations, 21-2
respiratory protection, 25-8
RIDDOR (Reporting of Injuries, Diseases, and Dangerous Occurrences Regulations), 21-2
rightward welding, 105-6
risk assessment, 16-17
risks, 16
Rockwell hardness tester, 347, 364
rods, 71
root passes, 193-4
root runs, 281
rounding numbers, 72
roundness, 75
RT (radiographic inspection), 347, 374-7
rules, 72
- safety glasses, 14, 25, 229
safety release valves, 94
scratch gauges, 73
scribers, 72
scribing gauges, 74
semi-automatic operation, 2
shear strength, 43, 347, 362
shears, 206-7
sheet metal, 70
sheet squares, 72
shielding gas, 214-17, 256, 270-1, 300-1
short-circuiting transfer, 212-13, 245-7
side bend test, 370
silver, 112
silver soldering, 112
single-stage regulators, 93
SkillWeld and Constructional Metalwork Competitions, 11
slag, 2
slip gauges, 74
slope, 106
smoke extraction nozzles, 261
snifting, 91
soft dross, 120, 141
spatter, 2
specifications, 209
spirit levels, 74
spool guns, 225
spot welding, 57, 227-8
spray metal transfer, 253-6, 274-5
square butt joints, 185
square butt welds, 279
square butt welds in flat position, 279-80
square edge butt joints, 110
squareness, 75
stack cutting, 120, 153
stainless steel, 65-6, 321
stand-off distance, 120, 149
standards, 2, 47, 120
steel, 64-5, 65-6
 strength, 63
 stress relief, 342-3
 striking voltage, 165
stringer bead deposition, 247, 256
stringer beads, 182-3, 323
stringer beads in the flat position, 278
strongbacks, 61, 84
structural sections, 71
student welding report, 384
surface finish, 75
surface tables and plates, 74
- T-fillet joints, 327
T-fillet welds, 109
T-fillet welds in the flat position, 287
T-joints, 192
T-joints in the flat position, 251, 258-9
tack welds, 14, 85-6, 210
TAGS (tungsten active gas shielded welding), 2, 3, 7-8
tempering, 70
tensile strength, 116
tensile testing, 361
thermal conductivity, 63
thermal cutting, 119-59
thermit welding, 4
thermo-chemical energy-combustion, 3
thoriated tungsten electrodes, 308
- TIG *see* tungsten inert gas shielded welding
tilt, 106
time keeping, 39
tip cleaners, 120
tolerances, 43, 71
torches, 98, 301-2
toughness, 63
trammels, 73
transformers, 166
transverse distortion, 335
tufting, 91, 114
tungsten active gas shielded welding, 2, 3, 7-8
tungsten electrodes, 305-10
tungsten inert gas shielded welding, 2, 291-329
 AC balance control, 295-7
 aluminium, 321-2
 back caps, 305
 back purging, 329
 butt joints, 328
 contactors, 297
 current setting, 316-20
 electrodes, 305-10
 equipment, 292-311
 filler rods, 315-16
 flow meters, 301
 gas flow, 299, 318-20
 gas lenses, 303
 hoses, 303-4
 hot start, 297
 lap joints, 325
 low carbon steel, 320-1
 metal preparation, 321-2
 mild steel, 320-1
 nozzles, 304-5
 outside corner joint, 324
 post-flow control, 298
 power sources, 293-4
 practice welds, 320-2
 pre-flow control, 298
 remote controls, 299
 setup, 311-14
 shielding gas, 300-1
 slope-in control, 297
 slope-out control, 297
 stainless steel, 321
 stringer beads, 323
 T-fillet joints, 327
 torch angle, 314
 torches, 301-2
 tungsten contamination, 316
 welding return leads, 300
two-stage regulators, 94
- ultrasonic inspection, 161, 347, 379
ultraviolet light, 14, 21
undercut, 358
underfill, 359
UT (ultrasonic inspection), 161, 347, 379
- V-butt joint in the flat position, 283
V-butt welds in the flat position, 281
valve protection caps, 14, 30-1
ventilation, 14, 28

- venturi effect, 210, 241, 291
- vernier tools, 73-4
- visible light, 14, 21
- visors, 99
- visual inspection, 373
- volts, 14, 120

- waist protection, 29
- warning labels, 14, 20
- waste material disposal, 18
- water tables, 14, 25, 120, 154
- weld beads, 183-4
- weld features, 351-2
- weld joint design, 43-7
- weld joints, 43
- weld procedure sheets, 2, 10, 161, 350
- weld ripples, 106
- weld tests, 2, 10
- weldability, 63

- welder certification, 2, 10
- welder performance qualification, 2
- welding
 - definition, 4
 - history, 2
 - occupational opportunities, 5-6
 - pre-requisites, 5
 - process selection, 9
 - skills competitions, 11
 - timeline, 3
 - training, 9-10
- welding codes, 161
- welding guns, 226
- Welding Institute, 10, 11
- welding positions, 43, 45-6
- welding procedure qualification
 - record, 2
- welding procedure specifications, 2, 10, 161, 350

- welding process classification, 4
- welding symbols, 2, 43, 52-9
- welding wires, 382-3
- weldments, 14
- welds, 2, 210
- wire feeders, 223-5
- wire-feed speed, 212
- wires, 71, 101, 382-3
- witness marks, 61, 74
- work area housekeeping, 34
- work clothing, 29
- working at heights, 37-8
- workshop calculations, 78-81
- workshop formulae, 76-7
- workshop tasks, 11-12
 - flux cored arc welding, 227-80, 283, 287-8
 - manual metal arc welding, 185, 189-90, 195, 197

- metal inert gas shielded welding, 249-52, 256-9, 257
- oxy-fuel gas cutting, 141-2
- oxy-fuel gas welding, 107-10
- plasma arc cutting, 156, 158-9
- tungsten inert gas shielded welding, 323-5, 327-8
- WorldSkills Competitions, 11
- WPQR (welding procedure qualification record), 2
- WPS (welding procedure specifications), 2, 10, 161, 350
- wrought iron, 64-5

- zinc, 27
- zirconium tungsten electrodes, 308